186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



ŝR

BENTLEY











Ì

:

÷

2

GUSTOMER NO.	32945			96	^{G №0.} 7471	INVOICE DATE 07/10/23	ZZCS89594
		LABOR RATE		MILEA	^{GE} 2,623	COLOR TEAL/	STOCK ND. 8839
			ER MAKE/VECT	NP WY-3/		DELIVERY DATE 01/31/19	DECIVERY MILES
		VEHICLE I.D. N	IŌ.			SELLING DEALER NO.	PRODUCTION DATE
		1 V 9	VW2629	PW04	8001	R. O. DATE	
						01/28/19	
		COMMENTS		·····			MO: 26
B# 1 CHARG	ÆS					OTHER AVAILA	ABLE SERVICE
BOR	CHECK CA	R OVER HOURS: 32.75 1	ECH(S):50 787		7336.00	Full	detail
	CLIENT STATES PL	EASE PERFORM FULL CHECK OVER TIRES, BATTERY ETC.	ON VEHICLE.			Cerami	c coating
	 RUNS POORLY. 	DUMPING FUEL, ENGINE KNOCKS.				Paint c	orrection
		PAINT DEFECTS, CRACKED BODY				Vehicle styling	enhancements
		BODY WORK, MISSING STRIKERS F VISION FOR RELEASING THEM.	OR TRUNK BECAUSE				lent removal
	MISSING MIRROR D PASSENGER OUTSID	DETENTS, THEY WERE NEVER DEVE DE DOOR HANDLE	LOPED.				d chip removal
	BROKEN (REMOVED A						umper repairs
	DAMAGED, RF TIRE	FLAT					vheel repairs
	COMPLETELY INEFF	8MM. DRIVING THE CAR, THE E ECTIVE. THEY AREN'T POWER BR	AKES, AND NEED			•	el fabrication
	,	SIBLY REPLACE MASTER CYLINDER WAS ON THE ENGINE AND TRANSMI					
	COVER GASKETS, T	THE TRANS PAN GASKET AND MODU EDS TO BE REPLACED.					w tinting
	7. AXLE BOOTS NE	ED REPLACEMENT.				-	em upgrades
	OFF.	ROL, ALL EMISSIONS CONTROL SY	STEPS ARE CAPPED				dio systems
		SYSTEM NO SOUND. SPOILERS SO THEY ARE WORKIN	G				detectors
	CORRECTLY NOW. T THE MOTOR WAS LO	HE RIGHT SPOILER WAS SEIZED	UP WITH RUST AND			Leathe	er repair
	13. BRACKET FOR	FRONT ACCESSORY DRIVE IS MIS	SING, NEEDS TO			Clear pro	tective film
		OTHER ENGINE INCIDENTALS AS				Car o	covers
		AS DEVELOPED, NO TRUNK RELEA MPARTMENT ON EITHER CAR.	SE, NO PROPS FOR			Upholster	y products
		28/2019 FROM 12:30-4:30 IS P	UTTING CAR			Apparel and	accessories
		DESCRIPTION				Transport of	your vehicle
(j)(j)	1 56-864	C-TEK TENDER	UN.	178.50	178.50	anywhe	re in the
	2 RU-1790 1 35051	AIR FILTER CRIMP TOOL		105.73 173.40	211.46 173.40	Contine	ental US.
	1 SFL-1628 1 DEI-01060	VALVE COVER GAKS B HEAT SLEEVE		115.43 194.61	115.43 194.61	FACTORY A	UTHORIZEI
	1 34049 1 MT-34	IGN WIRE 8.5MM BATTERY		387.90	387.90		SHOP
	2 8852	SPARK PLUG BOOT		207.90 70.51	207.90 141.02		F WARRANTIES
	1 8853 1 TOS-18629	SPARK PLUG BOOT TANS PAN GASKET		74.31 40.73	74.31 40.73	The only warranties, if a and/or service are those	
	1 TCI-35000	1 TRANS MODULATOR		75.37	75.37	turer. The selling dealer h all warranties, either exp	nereby expressly discla
	8 BCH-W5DP0 1 316-50002			72.32 54.15	578.56 54.15	ing any implied warrant	ties of merchantability
	2 60654	THROTTLE BODY GA		11.84	23.68	fitness for a particula assumes or authorizes an	
	1 2441061 1 DS116	BATTERY TIE DOWN DIMMER SWITCH		21.34 28.50	21.34 28.50	for it any liability in conne	ection with the sale of
				-0.00	20,30	part(s) and/or service. B to recover from the selling	
						damages, damages to p	roperty, damages for i
AGE 1 OF 11		CUSTOMER COPY	[CONTINUED ON	NEXT PAGE	11:16am	of use, loss of time, loss any other incidental dama	

any other incidental damages.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY
















[CONTINUED ON NEXT PAGE] 11:16am

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













.....

:

.....

ţ Ł

ŝ

CUSTOMER NO.	A 77	ADVISOR				NO.	INVOICE DATE	INVOICE NO.
3294	45	DAN LABOR PATE		SE NO.	96 MILEAG	7471	07/10/23	ZZCS89594
		98.00		JE NO.		2,623	TEAL/	8839
		YEAR/MAKE/MOD 93/0THER	MAKE/	VECTOR	NX-3/0	OUPE	DELIVERY DATE 01/31/19	2,623
		1 V 9 V	W 2 6	29P		8001	SELLING DEALER NO.	PRODUCTION DATE
		F.T.E.NO.			P. O. NO.		01/28/19	
		COMMENTS					<u>.</u>	MO: 262
	D MAP SENSOR WITH S MUCH BETTER.	A NEW ONE AND RECHECKE	D OPERAT	ION,			OTHER AVAILA	
	MENTS FOR RUNNING	CONDITION REPAIRS					Full o	
		DESCRIPTION		UNIT		105 45	Ceramic	
1	12569241	MAP SENSOR		TOTAL -	195.45 PARTS	195.45 195.45	Paint co	•
			CONT	ROL NO			Vehicle styling	enhancements
LBF2	15% DISCOUNT/LAB	OR		TOTAL -	MISC	-2548.56 -2548.56	Paintless de	
JOB# 2 TOTALS							Touch up and	chip removal
				labor Parts		16990.40 195.45	Lower front bu	umper repairs
				MISC		-2548.56	Damaged w	heel repairs
OB# 3 CHARGES		JOB# 2 JOURNAL PREFI	X ZZCS	JOB# 2	TOTAL	14637.29	Custom when	el fabrication
_ABOR							Window	/ tinting
J# 3 61ASZ	EXTERIOR TRIM	HOURS: TECH			Enst niger,		Stereo syste	m upgrades
AND/OR	BODY REPAIRS. D ESTIMATE AS REQU		CORRECT				Satellite rac	lio systems
	-						Radar d	etectors
127241		TE-DESCRIPTION 19 CLIP				0.00	Leather	repair
				TOTAL -	SUBLET	0.00	Clear prote	ective film
00B# 3 TOTALS							Car c	overs
JOB# 4 CHARGES		JOB# 3 JOURNAL PREFI	X ZZCS	JOB# 3	TOTAL	0.00	Upholstery	/ products
ABOR							Apparel and	accessories
		HOURS: 6.00 TECH				1344.00	Transport of	your vehicle
INSTALL		Y HOLD DOWN SYSTEM, AN					anywher	e in the
PARTSOTYFP-		DESCRIPTION			ÓÐTCE		Continer	ntal US.
1	6867931 LA45760	12V PLUG BATT DISCONNECT		TOTAL -	82.23 93.98	82.23 93.98 176.21	FACTORY A	
4TSCCODE	DESCRIPTION		CONT			1.0.111	DISCLAIMER OF	
LBF2	15% DISCOUNT/LAB	OR	CUNT	TOTAL -		-201.60 -201.60	The only warranties, if an and/or service are those turer. The selling dealer he all warranties, either expri- ing any implied warrantii fitness for a particular assumes or authorizes any for it any liability in conner part(s) and/or service. Bu	offered by the manufac reby expressly disclaim essed or implied, includ es of merchantability of purpose, and neither y other person to assum ction with the sale of the
PAGE 3 OF 11	CUSTOME	R COPY	[CONTINU	IED ON NE	EXT PAGEJ	11:16am	to recover from the selling damages, damages to pro- of use, loss of time, loss any other incidental damage	dealer any consequenti operty, damages for los of profits, or income, o

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













CUSTOMER NO. ADVISOR NVOICE DATI 07/10/23 32945 96 7471 ZZCS89594 DAN LICENSE NO STOCK NO. LABOR RATE MILEAGE COLOR 98.00 2,623 TEAL/ 8839 YEAR / MAKE / MODEL DELIVERY DATE DELIVERY MILES 93/OTHER MAKE/VECTOR WX-3/COUPE 01/31/19 2,623 SELLING DEALER NO. PRODUCTION DATE VEHICLE LD. NO. 1 V 9 V W 2 6 2 9 P W 0 4 8 0 0 1 F.T.E.NO. P. O. NO. R. O. DATE 01/28/19 COMMENTS MO: 2623 JOB# 4 TOTALS-----OTHER AVAILABLE SERVICES 1344.00 LABOR PARTS 176.21 Full detail MISC -201.60 Ceramic coating JOB# 4 JOURNAL PREFIX ZZCS JOB# 4 TOTAL 1318.61 JOB# 5 CHARGES------Paint correction ABOR - - - - -Vehicle styling enhancements J# 5+11ASZ ENGINE MINOR HOURS: 9.60 TECH(S):50 2150.40 CLIENT STATES PLEASE INSTALL UPDATED AIR FILTERS. Paintless dent removal REMOVED THROTTLE BODY AND AIR INTAKE SYSTEM AND REPLACED AIR FILTERS WITH UPDATED FILTERS. Touch up and chip removal Lower front bumper repairs MISC-----CODE-----DESCRIPTION------LBF2 15% DISCOUNT/LABOR -322.56 Damaged wheel repairs GAS GAS ALL MAKES 27.00 TOTAL - MISC -295.56Custom wheel fabrication JOB# 5 TOTALS-----Window tinting 2150,40 I ABOR MISC -295.56 Stereo system upgrades JOB# 5 JOURNAL PREFIX ZZCS JOB# 5 TOTAL 1854.84 Satellite radio systems 30B# 6 CHARGES-----Radar detectors ABOR -----3# 6+11ASZZ1 ENGINE CONCERN HOURS: 34.65 TECH(S):50 7761.60 Leather repair CLIENT STATES PLEASE REPLACE SPARK PLUGS AND WIRES. Clear protective film FOUND THE PLUG WIRES BURNED OFF. . REMOVED EXHAUST SHIELDS, HAD TO DRILL AND TAP OUT BROKEN BOLTS, REPLACED ALL SPARK PLUGS AND MADE ALL NEW WIRES WITH HEAT PROOF SLEEVES AND Car covers HEAT PROOF SPARK PLUG BOOTS, ROUTE WIRES CORRECTLY AND Upholstery products SECURE OUT OF THE WAY OF ALL HEAT SOURCES. Apparel and accessories MISC-----CODE-----DESCRIPTION-----LBF2 15% DISCOUNT/LABOR -1164.24 Transport of your vehicle TOTAL - MISC -1164.24 anywhere in the JOB# 6 TOTALS-----Continental US. LABOR 7761.60 MISC -1164.24 FACTORY AUTHORIZED JOB# 6 JOURNAL PREFIX ZZCS JOB# 6 TOTAL 6597.36 BODY SHOP 10B# 7 CHARGES-----DISCLAIMER OF WARRANTIES LABOR - - - - -The only warranties, if any, applying to the part(s) J# 7+45ASZ STEERING/SUSPENSION HOURS: 14.85 TECH(S):50. 3326.40 and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims CLIENT STATES PLEASE CHECK REAR AXLE BOOTS. all warranties, either expressed or implied, includ-REMOVED BOTH REAR AXLES, DISASSEMBLE AND INSTALLED NEW AXLE BOOTS. REFIT AXLES AND TORQUE BOLTS. OK ing any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume PARTS-----QTY---FP-NUMBER-----DESCRIPTION------DESCRIPTION--------UNIT PRICEfor it any liability in connection with the sale of this 1474-108 CV JOINT BOOT 516.12 129.03 part(s) and/or service. Buyer shall not be entitled TIL - 72 - 509 BIAS ADJUSTER RE 166.30 166.30 to recover from the selling dealer any consequential damages, damages to property, damages for loss

of use, loss of time, loss of profits, or income, or any other incidental damages.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



S P

BENTLEY













ļ

į

i

ļ ŧ ł.

÷

CUSTOMER NO. 329	45				96	^{3 NO.} 7471	07/10/23	ZZCS89594
		LABOR PATE 98.0		ISE NO.	MILEA	se 2,623	TEAL/	8839
		93/OTHE	R MAKE	VECTOR	WX-3/	COUPE	DELIVERY DATE 01/31/19	DELIVERY MILES
		VEHICLE J.D. NO				8001	SELLING DEALER NO.	PRODUCTION DATE
		F. 1. E. NO.			P.O.NO.		R. O. DATE 01/28/19	
		COMMENTS					01/20/20	MO: 262
				TOTAL -	PARTS	682,42	OTHER AVAILA	
			CON1	ROL NO				detail
LBF	2 15% DISCOUNT/LAB	OR		TOTAL -	MISC	-498.96 -498.96		coating
JOB# 7 TOTALS								prrection
				LABOR PARTS		3326.40 682.42		enhancements
				MISC		-498.96		ent removal
JOB# 8 CHARGES		JOB# 7 JOURNAL PRE	FIX ZZCS	JOB# 7	TOTAL	3509.86		chip removal
					•••			umper repairs
LABOR	FLUID LEAK-ENGINE	HOURS: 12.15 TE	CH(S):50	an Shindag	n is dividente Statistica	2721.60		heel repairs
REPLAC		GASKETS. HAD TO MOD					÷	el fabrication
	SO THE BOLTS WOULD GASKETS.	SIT DEEPER TO ACCOM	MODATE THE	E NEW				v tinting
PARTSQTYFP	-NUMBER	DESCRIPTION		UNIT	PRICE-			em upgrades
1	FRAG3000	STAINLESS HOSE		TOTAL -	169.99 PARTS	169.99 169.99	-	dio systems
ISCCODE	DESCRIPTION		CON1	ROL NO				letectors
	2 15% DISCOUNT/LAE			TOTAL -		-408.24 -408.24	Leathe	r repair
JOB# 8 TOTALS								tective film
				LABOR PARTS		2721.60 169.99	Carc	overs
				MISC		-408.24	Upholster	y products
		JOB# 8 JOURNAL PRE	FIX ZZCS	JOB# 8	TOTAL	2483.35	Apparel and	accessories
							Transport of	your vehicle
# 9+30ASZ04	AUTO TRANS LEAK	HOURS: 9.40 TE	CH(S):50			2105.60	anywhe	re in the
REMOVE	D THE TRANSMISSION	NSMISSION FLUID LEAK PAN, RESEALED AND RE	FIT. REPLA				Contine	ntal US.
SYSTEM		NED UP ALL BOLTS, RE					FACTORY A	UTHORIZED
		RANS FLUID DRIPPING EXTERNAL COOLANT LEA						SHOP
	XHAUST CAUSING SILI FOUND SELECTOR SHAF	CONE SEAL TO FAIL AN T SEAL LEAKING.	ID LEAK FRO	IM PAN			DISCLAIMER O The only warranties, if an	F WARRANTIES ny, applying to the part
		DESCRIPTION		UNIT	PRICE-		and/or service are those turer. The selling dealer h	
1 12	5971 ATF	GASKET TRANS FLUID			42.72 10.38	42.72 124.56	all warranties, either exp ing any implied warrant	
				TOTAL -		167.28	fitness for a particular assumes or authorizes an	
							for it any liability in conne part(s) and/or service. B	ection with the sale of t
							to recover from the selling damages, damages to pr	dealer any consequen
PAGE 5 OF 11	CUSTOME	RCOPY	[CONTIN	UED ON NE	XT PAGE]	11:16am	of use, loss of time, loss any other incidental dama	s of profits, or income,
					-	•		Reynolds Company EBAINE SF2152 Q (01.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY



ADVISOR














of use, loss of time, loss of profits, or income, or any other incidental damages.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













i

1 1.

CUSTOMER NO. 32945			96 7471	INVOICE DATE 07/10/23	ZZCS89594
	LABOR RATE	LICENSE NO	MILEAGE 2,623	TEAL/	STOCK NO. 8839
	YEAR / MAKE / MODEL 93/OTHER M	MAKE/VECTOR W	X-3/COUPE	DELIVERY DATE 01/31/19	DELIVERY MILES 2, 623
	VEHICLE LD NO. 1 V 9 V W	2629PW	048001	SELLING DEALER NO.	PRODUCTION DATE
	F. T. E. NO	P. O.	NO.	B. O. DATE 01/28/19	
	COMMENTS	I		J	MO: 26
		TOTAL - PAR	RTS 3024.89	OTHER AVAIL	
ISCCODEDESCRIPTIO		CONTROL NO			detail
LBF2 15% DISCOU	NT/LADUR	TOTAL - MIS	-413.28 5C -413.28		c coating
08# 11 TOTALS	•••••				orrection
		LABOR PARTS	2755.20 3024.89	Vehicle styling	enhancements
		MISC	-413.28		lent removal
OB# 12 CHARGES	JOB# 11 JOURNAL PREFIX	ZZCS JOB# 11 TOT	AL 5366.81	Touch up and	d chip removal
ABOR				Lower front b	umper repairs
#12+S1ASZO5 HEADLIGHTS TECH FOUND HEADLIGH	HOURS: 1.60 TECH(S T HIGH/LOW BEAM SWITCH IS FAUL		358.40	Damaged v	vheel repairs
	BEAM SWITCH. HAD TO REMOVE MOS			Custom whe	el fabrication
ISCCODEDESCRIPTIO		CONTROL NO		Windo	w tinting
LBF2 15% DISCOU		TOTAL - MIS	-53.76	Stereo syst	em upgrades
08# 12 TOTALS			-55.70	Satellite ra	dio systems
		LABOR	358.40	Radar e	letectors
		MISC	-53.76	Leathe	er repair
OB# 13 CHARGES	JOB# 12 JOURNAL PREFIX	ZZCS JUB# 12 101	AL 304.64	Clear pro	tective film
ABOR	na na mana ao kaominina dia			Card	covers
#13+46ASZD7 CLIENT STATES PLEAS	ALANCE HOURS: 4.00 TECH(S E REPLACE ALL FOUR TIRES.):50	396.00	Upholster	y products
MOUNT AND BALANCE 4	NEW TIRES.			Apparel and	accessories
ARTSQTYFP-NUMBER 2 0926100	PIRELLI P ZERO		CE- .61 541.22	Transport of	your vehicle
2 2592900	PIRELLI P ZERO	- • +	.79 1167.58	anywhe	re in the
0B# 13 TO⊺ALS			1700.00	Contine	ental US.
		LABOR PARTS	396.00 1708.80		UTHORIZED SHOP
08# 14 CHARGES	JOB# 13 JOURNAL PREFIX	ZZCS JOB# 13 TOT	AL 2104.80	DISCLAIMER O The only warranties, if a	F WARRANTIES
ABOR #14+46ASZO1 WHEEL/TIRE (ONCERN HOURS: TECH(S)			and/or service are those turer. The selling dealer t all warranties, either exp ing any implied warran filness for a particula assumes or authorizes a for it any fiability in conn part(s) and/or service. E to recover from the selling	offered by the manufatereby expressly disclain pressed or implied, incluing ties of merchantability or purpose, and neith my other person to assume oction with the sale of the puper shall not be entitied.

of use, loss of time, loss of profits, or income, or any other incidental damages. The Reynolds and Reynolds Company ERAINTING SF2152 Q (01/18)

to recover from the selling dealer any consequential damages, damages to property, damages for loss

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY
















PAGE 8 OF 11

any other incidental damages. The Reynolds and Reynolds Company ERMININVE SF2152 Q (01/18)

of use, loss of time, loss of profits, or income, or

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com

LICENSE NO.



CUSTOMER NO.

ABOR - - - - -

J#18+90ASZWASH

LABOR

123140

2

1

1

1

1

1

BENTLEY

127241

357

2714

15-8240

SSS-SSL

61944

CPER

GMKIN

VNTEL

32945



40//19/06

LABOR RATE

DAN

RUGAT





TAG NO

MILEAGE

96

7471





ZZCS89594




07/10/23

COLOR



NVOICE NO

STOCK NO



ABOR - - - - -D#20+30ASZ1 TRANSMISSION CONCERN HOURS: TECH(S):787 0.00 TECH NOTICED THERE ARE ADDITIONAL LEAKS FROM TRANSMISSION. THIS IS A CONTINUATION OF JOB 9.

PAGE 9 OF 11

CUSTOMER COPY

JOB# 20 CHARGES------

turer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555

www.millermotorcars.com



BENTLEY













USTOMER NO. ZZCS89594 07/10/23 32945 7471 DAN 96 LICENSE NO. LASOR RATE MILEAGE STOCK NO 2,623 TEAL/ 98.00 8839 DELIVERY MILES 2,623 YEAR / MAKE / MODEL DELIVERY DATE 93/OTHER MAKE/VECTOR WX-3/COUPE 01/31/19 VEHICLE I.D. NO SELLING DEALER NO. PRODUCTION DATE 1 V 9 V W 2 6 2 9 P W 0 4 8 0 0 1 F.T. E. NO. P O NO B O DATE 01/28/19 COMMENTS MO: 2623 ONCE TRANSMISSION SEALS WERE REPLACED AS NEEDED TESTED AND OTHER AVAILABLE SERVICES CONFIRMED NO FURTHER LEAKS ARE NOTED AT THIS TIME. Full detail K34900F SEAL KIT 259.98 2 129.99 Ceramic coating 1 80697 SEALANT 24,99 24.99 RECON TURBOCHARG T4RECON 1501.50 1501.50 1 Paint correction 1 BILLET BILLET WHEEL UPG 425.70 425.70 1 ES10966 02 SENSOR 48.14 48.14 Vehicle styling enhancements 1 80016 SEALANT 17.72 17.72 2278.03 TOTAL - PARTS Paintless dent removal 30B# 20 TOTALS------. Touch up and chip removal PARTS 2278.03 Lower front bumper repairs JOB# 20 JOURNAL PREFIX ZZCS JOB# 20 TOTAL 2278.03 Damaged wheel repairs COMMENTS -----Custom wheel fabrication -LINE 2 PER 787-10/22 FOUND CAR DOES NOT START & ENGINE TURNS OVER SLOWLY. VERIFY Window tinting BATTERY STATE OF CHARGE. VERIFY SPARK SIGNAL ON ALL WIRES. REMOVE SPARK PLUGS AND READ, FOUND SOME ARE CARBON FOULED, BUT OTHERS WET WITH FUEL. CLEAN PLUGS, GAP TO 0.035" & ADD DIELECTRIC GREASE TO BOOTS. ENGINE NOW TURNS OVER QUICKLY, BUT DOES NOT START. VERIFY TPS SIGNAL 1 & 2 CORRECT RESISTANCE CLOSED AND OPEN. VERIFY IAC Stereo system upgrades Satellite radio systems OPERATION, WORKING BUT WIRES ARE WORN AND BARE. PERFORM FUEL Radar detectors PRESSURE TEST, FOUND AIR IN FUEL RAIL AND ONLY 20PSI WHILE CRANKING, 10/23 ACCESS FUEL TANK BEHIND SEATS, FOLLOW LINES TO Leather repair VERIFY ALL LINES IN TACT & NOT CRUSHED. ACCESS FUEL PUMP RIGHT REAR, PERFORM CIRCUIT TEST, 0.50 OHMS TO GROUND AND GROUND RUSTED AND ONLY 10.1V AT PUMP KOEO WITH BATTERY T 12.5V. 10/24 ACCESS Clear protective film Car covers ENGINE COMPUTER AND FOLLOW WIRING TO FUEL PUMP RELAY UNDER INTERCOOLER. REMOVE RELAY AND BENCH TEST, ALL RESISTANCE OK BUT APPEARS BURNED. PERFORM VOLTAGE DROP TEST AND FOUND 1.90V DROPPED Uphoistery products ACROSS 30+ & 87 OUTPUT WIRES, 0.50V DROPPED ACROSS WIRE FROM RELAY TO PUMP AND WIRE GETS HOT TO THE TOUCH. JUMP PUMP DIRECTLY AND Apparel and accessories FOUND FUEL PRESSURE NOW AT 45PSI & ENGINE STARTS & RUNS. RELAY ON Transport of your vehicle ORDER, SEVERAL WIRES WILL NEED TO BE REPLACED. 10/24 REPLACE RELAY AND FOUND PUMP NOW RUNS TO 40PSI KOEO. CAR NOW STARTS AND RUNS, BUT anywhere in the STALLS WHEN THROTTLE IS TIPPED IN. WILL REWIRE CIRCUIT FOR PUMP FROM RELAY FIRST. 10/25 WHILE RUNNING PUMP WIRES, FOUND ADDITIONAL Continental US. WIRES. FOLLOW WIRES TO SECOND FUEL PUMP. FOUND PUMP AND FILTER ACCESS THROUGH HIDDEN RIGHT REAR TRUNK PANEL. FOUND 2 FUEL PUMPS **FACTORY AUTHORIZED** WIRED IN SERIES AND PLUMBED IN SERIES, OVERHEATING RELAY, RESULTING BODY SHOP IN LOSS OF VOLTAGE TO PUMPS. INSTALL CHASSIS GROUND STUD BEHIND RR PANEL & WIRE PUMP GROUND TO STUD TO ELIMINATE VOLTAGE DROP ON DISCLAIMER OF WARRANTIES GROUND SIDE. REWIRE BOOST VALVE GROUND TO GROUND STUD THAT WAS The only warranties, if any, applying to the part(s) SHARING GROUND WITH DROP. REWIRE RELAY POWER WIRE WITH NEW and/or service are those offered by the manufac-CONNECTOR TO ELIMINATE FAILING BUTT CONNECTOR, APPLY VOLTAGE turer. The selling dealer hereby expressly disclaims DIRECTLY TO EACH PUMP AND MONITOR PRESSURE, FOUND HIGH PRESSURE all warranties, either expressed or implied, includ-PUMP NOT INCREASING PRESSURE, OVERHEATS WIRE, & TRIPS RELAY. PUMP ing any implied warranties of merchantability or filness for a particular purpose, and neither REPLACEMENT ON ORDER. 10/28 ACCESS BATTERY AND LOCATE POWER WIRE FOR FUEL RELAY. FOUND POWER WIRE SPLICED FOR IGNITION MODULE, assumes or authorizes any other person to assume for it any liability in connection with the sale of this COOLING FAN RIGHT SIDE, & BOTH FUEL PUMPS. NEED TO RUN INDEPENDENT

RELAYS & POWER WIRES FOR FUEL PUMPS TO PREVENT BURNT RELAY AGAIN,

part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages. The Reynolds and Reynolds Company ERAINTINVE SF2152 Q (01/18)

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555

www.millermotorcars.com
















BENTLEY



for it any liability in connection with the sale of this

part(s) and/or service. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY











i

÷

:

ŧ i.

;

CUSTOMER NO.	3294	5		advisor DAN		96	8001	INVOICE DATE 07/10/23	ZZCS96339
				LABOR RATE 98.00	LICENSE NO.	MILEA	^{GE} 2,323	COLOR TEAL/	STOCK NO. 8839
				93/0THER M	AKE/VECTOR	WX-3/	COUPE	DELIVERY DATE 01/31/19	DELIVERY MILES 2,62
				VEHICLE I.D. NO. 1 V 9 V W				SELLING DEALER NO.	PRODUCTION DATE
				F. T. E. NQ.		P. O. NO.		R.O. DATE 11/19/19	
				COMMENTS		1		I,	MO: 23
IOB# 1 CHARGE	5				•••••			OTHER AVAILA	
ABOR	ki wikasi:	DRIVEABILITY C	NCERN HOURS	548 05 TECH(S)	•787		122763 20	Full	detail
Р	LEASE	REPAIR LEAKS NO	TICED DURING C	HECK OVER. CON	TINUATION		, () : : : : : : : : : : : : : : : : : : :		coating
		IRS FROM RO#895 ATION OF REPAIR		89594. REPAIR	ORDER				-
W	RITTEN	DUE TO TECH PU							orrection
0	N PREV	IOUS RO.						Vehicle styling	enhancements
		NUMBER		ION	UNIT			Paintless d	ent removal
		CQH355W 08 - 0005	H3 BULB	2 GAL T		31.32 1036.89	62.64 1036.89		chip removal
		TIL74-750U		nder kit		168.32	168.32	-	-
	1	TIL74-625U	5/8 cyli	nder kit		168.32	168.32	Lower front b	umper repairs
		12569240 25527077	MAP SENS VALVE	OR		171.91 181.88	343.82 181.88	Damaged w	heel repairs
		3F - 12	BRAKE FL	UID		8.30	49.80	-	•
	3 (ORB-06		VE DIREC		71.50	214.50	Custom whe	el fabrication
		1000-6	AEROMOTI			286.00	286.00	Window	v tinting
1		/IBRANT-2690 /IBRANT-11200	VACUUM M HOSE BAR			110.33 17.82	220.66 213.84		-
		/IBRANT-11205	HOSE BAR			23.28	46.56	Stereo syste	em upgrades
	1	27044	VACUUM H	OSE		61.10	61.10	Satellite ra	dio systems
		27053 7160075-COPPER-	VACUUM H			120.15 28.44	120.15 28.44		letectors
		GA2462	SENDING			417.04	417.04		
		LGAS98	GASKETS			114.02	228.04	Leathe	r repair
		2204	MOUNTING			65.68	65.68	Clear prot	tective film
		1C49493272 7768K61.MCMSTR	HOSE AND THREADED			148.59 82.37	148.59 82.37	Clear pro	lective min
		TY X2 1/8 NPT		CHN, YAE		02.37	02.57	Car c	overs
	1 !	HIPPING-TURBO				76.36	76.36	Unhoister	y products
		21-10008 2822T14	TURBO DR. THREADED			151.54 79.64	151.54 79.64	÷	
		PT5696	PIGTAIL/			50.45	50.45	Apparel and	accessories
			,		TOTAL -		4502.63	Transport of	your vehicle
UBLET PO# 139		-VEND INV#-INV 3715 11/	.DATE-DESCRIPT 20/20 FUEL LIN				79.59	anywhe	re in the
		2.40 12,			TOTAL -	SUBLET	79.59	Contine	ntal US.
ISCCODE		-DESCRIPTION FERRARI HAZ M		 SC	-CONTROL NO		19.00	FACTORY A	UTHORIZED SHOP
	GAS	GAS ALL MAKES	,, _				15.38		
		GAS ALL MAKES TOTAL RO 15%	ASTON				29,71	The only warranties, if a	F WARRANTIES
	0122				TOTAL -	MISC	-19089.87 -19025.78	and/or service are those	offered by the manui
								turer. The selling dealer h	
								all warranties, either exp ing any implied warrant	
								fitness for a particular	
								assumes or authorizes ar	y other person to assu
								for it any liability in conne part(s) and/or service. B	
								to recover from the selling	
							ļ	damages, damages to p	roperty, damages for i
PAGE 1 OF 3		CUSTO	MER COPY	(C)	ONTINUED ON NE		11:21am	of use, loss of time, loss any other incidental dama	

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













:

į

:

• • •

.

32945 ADVISOR			96	1AG NO. 8001	07/10/23	ZZCS96339
LABOR RATE 98.0		ICENSE NO.	MIL	EAGE 2, 323	COLOR TEAL/	STOCK NO. 8839
YEAR / MAKE / 93/0TH	MODEL	E/VECTOR	2 WX-3	,	DELIVERY DATE 01/31/19	DELIVERY MILES
VEHICLE I.D. N	Q .				SELLING DEALER NO.	PRODUCTION DATE
L V 9 F.T.E.NO	V W Z	0298	P.O. NO.	8001	R. O. DATE	
COMMENTS					11/19/19	
						MO: 23
0B# 1 TOTALS		LABOR		122763.20	OTHER AVAIL	ABLE SERVICE
		PARTS SUBLET		4502.63 79.59	Full	detail
		MISC		-19025.78	Cerami	c coating
JOB# 1 JOURNAL PR	EFIX ZZ	CS JOB# 1	TOTAL	108319.64	Paint c	orrection
					Vehicle styling	enhancements
REMOVED TURBOS FOR REBUILD REMOVE TRANS PAN AND SIDE COVER, MEASURED FOR GASKETS					Paintless of	lent removal
REBUILT TURBOS INSTALLED TRANS SIDE AND LOWER PANS RESEALED. STILL LEAKING. REMOV					Touch up an	d chip removal
ESEAL AGAIN. REPLACED O-RING FOR MODULATOR AGAIN. OK AFT ESEAL. NOTE PAN MAY BE WARPED, BUT IS CUSTOM CUT AND WEL		0			Lower front b	umper repairs
PPLICATION TH425 REPAIRED ENGINE CONTROL WIRING					Damaged v	wheel repairs
ABRICATED COMPLETE HARNESS FOR FUEL PUMPS REPLACED 2 FUEL PUMP RELAYS					Custom whe	el fabrication
REPLACED 1 FUEL PUMP PERFORM SHORT ROAD TEST AND EXTENDED RUN TIME, BUT FOUND		-			Windo	w tinting
INES LEAKING	NULTIFL	-			Stereo syst	em upgrades
REMOVED LINES AND TURBOS, SENT OUT LINES FOR REPAIR RESEALED COOLING SYSTEM, MADE NEW COUPLERS FOR PIPES, RE	PLACED					dio systems
CT, CAP AND COOLANT FABRICATED BRACKET FOR RR COOLANT PIPE					1	detectors
REMOVED OIL TANK, FOUND INCORRECTLY SEALED, ORDERED NEW T REPLACED 2 FOG LIGHT BULBS AND REPAIRED WIRES, ALL LIGHT					Leathe	er repair
ORKING REFIT NEW TRANS, FUEL, COOLANT AND OIL DRAIN LINES TURBO	TO SUMP					tective film
EFIT TURBOS AND RESEAL GASKETS. PERFORM COOLING SYSTEM TO	EST				· ·	covers
REFILL TRANS AND LEAK CHECK. REFILL FUEL AND LEAK CHECK, HIS TIME. REFIT ALL SHIELDS AND NEW TURBO SHIELDS IN GOLD						y products
RAPPED EXHAUST IN COPPER HEAT WRAP AND COATED. REPLACED		R			· ·	accessories
ND REPAIRED WIRE DIL TANK COMING FROM UK AND NOT AVAILABLE DUE TO CORONAV:	IRUS.					your vehicle
ISASSEMBLE, CLEAN, AND RESEAL OIL TANK AS-IS. FILL WITH H ND LEAK CHECK, PASS. REFIT TO CAR AND FILL WITH OIL.						re in the
PRESSURE TEST FUEL SYSTEM, PASS WITH NEW LINES. PERFORM : TARTUP AND RECHECK ALL AN LINE TIGHTNESS.	INITIAL					ental US.
FILLED TIRES 36PSIF/44PSIR RUN TO OPERATING TEMP, CHECK ALL FLUIDS. CAR HAS SLOW THE						UTHORIZED
ESPONSE AND STALLS POST-WOT SNAP-THROTTLE SHUT. CHECK ECT AND TPS SIGNALS AND SENSORS, PASS. CHECK IAC, N						SHOP
ROSS-CONTINUITY. ISOLATE AND REPAIR. AFTER REPAIR, CAR WI ONGER IDLE, SWAP IAC WITH PURPLE CAR, NOW IDLES. RELOCATI ENSOR CLOSER TO MANIFOLD, THROTTLE RESPONSE IMPROVED. SW/ ENSOR TO GM PART FROM PURPLE CAR, ENGINE NOW RUNS SMOOTHI TALL STILL OCCURS. INVESTIGATE FOR VACUUM LEAKS, FOUND OI AP SEAL BAD. PCV VALVE OK. BRAKE PEDAL MUSHY ON ROAD AND REQUIRES PUMPING TO STOP. F ASH AND PERFORM FLUSH, FLUID CLEAR BUT LOTS OF AIR. NO LE XTERNALLY. PERFORM 3 MANUAL FLUSHES, PEDAL UNCHANGED. MAY YLINDERS	ELL NO E MAP AP MAP ER, BUT EL TANK REMOVE EAKS FOUN	ID W			DISCLAIMER C The only warranties, if a and/or service are those turer. The selling dealer all warranties, either exp ing any implied warran fitness for a particula assumes or authorizes a for it any liability in conn part(s) and/or service. E to recover from the sellin damages, damages to p of use, loss of time. Ins	e offered by the manufacers offered by the manufacers of the ma

of use, loss of time, loss of profits, or income, or any other incidental damages. The Reynolds and Reynolds Company ERAINTINVE SF2152 Q (01/18)

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555

www.millermotorcars.com



BENTLEY


















of use, loss of time, loss of profits, or income, or any other incidental damages. The Reynolds and Reynolds Company ERAINTINVE SF2152 Q (01/18)

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com















.

t -÷

CUSTOMER NO	329	45					96 TAG		07/10/23	ZZCS106000
				LABOR RATE 98.00	LICE	NSE NO.	MILEAG	2,323	COLOR TEAL/	STOCK ND. 8839
				YEAR / MAKE / MO		VECTOR W	X-3/0	· · · · · · · · · · · · · · · · · · ·	DELIVERY DATE 01/31/19	DELIVERY MILES
				VEHICLE LD. NO.		2 9 P W			SELLING DEALER NO	PRODUCTION DATE
				F.T.E.NO.		P. O.	NO.		H O. DATE 02/24/21	
				COMMENTS						MO: 26
IOB# 1 CHAR	RGES····	•••••							OTHER AVAIL	ABLE SERVICE
ABOR	1	DRIVEABL	tty conceri	1 HOURS: 382.20 TEC	H(S):787			85612.80	Full	detail
				EHICLE DRIVABLE.					Cerami	c coating
			OOLANT, OI	L. UNBOLT DRIVESHAF	TS, CROS	SBAR,			Paint c	orrection
	PLEASE	NOTE COMME		ITE UP ON VEHICLE.					Vehicle styling	enhancements
				ROAD TEST AND ALL R					Paintless o	lent removal
АКТ5(QTYFP 1	•NUMBER • • • • 0 - 580 - 254 -		DESCRIPTION		285	5.88	285.88	Touch up an	d chip removal
	1 1	1838-001 16392		GOLD HEAT REFLEC ROBERTSHAW TSTAT			5.42	315.42 107.47	-	oumper repairs
	1	VPE-2702 VPE-27031		HOSE COUPLERS HOSE COUPLER		156	5.57	156.57 89.84		wheel repairs
	1	5312K577		SS BOLT CLAMPS		212	2.67	212.67	U	eel fabrication
	1 2	PERMATEX FL-1-A		GASKET MAKER OIL FILTER			1.91 2.07	61.91 60.14		w tinting
	1 2	9262K307 COOLANT		O RINGS COOLANT			7.76 4.79	67.76 49.58		-
	1	FUEL-INJEC	TOR	FUEL INJECTOR SE			5.79	835.79	-	em upgrades
	1	5/11/23 5060770		SERP BELT			3.35	68.35		dio systems
	1	ECC1053		THROTTLE SENSOR		114 TOTAL - PAR	4.61 RTS	114.61 2425.99		detectors
	PO#		#-TNV DATE	DESCRIPTION					Leathe	er repair
1	143752		05/19/21	FB TO SINGH 5/17 RS	5			INTERNAL	Clear pro	tective film
	144264 148627	106000 106000		DEPOSIT FOR ENGINE EXTRA DEPOSIT FOR E				3000.00 6000.00	Car	covers
	153633 166046	6400B 106000		FINAL INVOICE FOR E REPAIR ASSISTANCE	ENGINE			9187.90 INTERNAL	Upholstei	ry products
						TOTAL - SUE	BLET	18187.90	Apparel and	accessories
ISCC0					CON	ROL NO		45 45	Transport of	f your vehicle
	GAS	GAS ALL I GAS ALL I	MAKES					15.95 35.28	anywhe	are in the
	GAS	5 GAS ALL 1 5 GAS ALL 1	MAKES					46.91 47.08	Contine	ental US.
	TA15	5 TOTAL RO	15% ASTON			TOTAL - MIS	sc	-13205.82 -13060.60	FACTORY A	UTHORIZED
0B# 1 TOTA	ALS								BODY	SHOP
						LABOR		85612.80		F WARRANTIES
						PARTS SUBLET		2425.99 18187.90	The only warranties, if a and/or service are those	e offered by the manu
						MISC		-13060.60	turer. The selling deater i all warranties, either exp	pressed or implied, inc
			C	08# 1 JOURNAL PREFI	X ZZCS	JOB# 1 TOT	AL	93166.09	ing any implied warrant filness for a particula	
					· · · · · · · · · · · · · · · · · · ·	•••••			assumes or authorizes a for it any liability in conn	ny other person to assu
ONTINUING R REMOVED ENG		PERFORMED (COMPLETE TE	ARDOWN. FOUND DAMAG	E TO CYL	INDER			part(s) and/or service. E to recover from the sellin damages, damages to p	Buyer shall not be enti g dealer any consequer
PAGE 1 OF 4		ſ	CUSTOMER (ÔPV		UED ON NEXT I	DAGEL	11:08am	of use, loss of time, los any other incidental dam	s of profits, or income

[CONTINUED ON NEXT PAGE] 11:28am

any other incidental damages.

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













Ì

į

.

32945	DAN		96 [™]	VECT	INVOICE DATE 07/10/23	ZZCS106000
	LABOR RATE 98.00	LICENSE NO.	MILEAGI	2,323	COLOR TEAL/	STOCK NO. 8839
	YEAR / MAKE / MODEL		 W2/0	,	DELIVERY DATE	DELIVERY MILES
	93/OTHER MAI	CE/VECTOR W	IX-3/0	OUPE	01/31/19 SELLING DEALER NO.	2,623
	1 V 9 V W 2	629PW	048	3001		
	F. T. E. NO.	P.O). NO.		R. D. DATE 02/24/21	
	COMMENTS					MO: 262
DMMENTS	GNITION EVENTS CAUSE	D BY FAILED			OTHER AVAIL	ABLE SERVICES
JEL SYSTEM BEFORE REPAIRS. ENGINE WAS SENT (Full	detail
DMPLETE REBUILD. SEE REBUILD SHEET. REQUESTED ENGINE MACHINE SHOP TO LINE UP DR:	EVE BELT AND CLEAN IN	JECTORS				
HILE BEING WORKED ON.						c coating
ALSO HAD CRACKED INACTIVE SECONDARY AIR POR' EAKS.	IS REMOVED TO STOP IN	MIFOLD			Paint c	orrection
WHEN ENGINE ARRIVED BACK, REFIT PERIPHERALS					Vehicle styling	enhancements
SSEMBLY TO CAR AND FOUND REAR LID CONTACTS N LOSE. BEFORE ENGINE REBUILD LID WAS CONTACT:					Paintless of	ent removal
OR CLEARANCE. NOW NOTCH IS NOT LARGE ENOUGH BOUT 10MM HIGHER THAN OLS PORTS. REWORK LID					Touch up an	d chip removal
REFIT ALL COMPONENTS, REPLACE ALL COOLANT CO					-	
XOLANT. USE ENGINE OIL SUPPLIED BY ENGINE M/ ILTERS.	ACHINE SHOP WITH NEW	OIL			Lower front t	oumper repairs
COULD NOT GET ENGINE TO IDLE WITH MORE THAN	10 IN-HG VACUUM AND	MISFIRES			Damaged v	vheel repairs
ND STALLS. REMOVE PLUGS AND READ, FOUND CYL > FUEL. ACCESS ECM DRIVERS SIDE INTERIOR AND					Custom who	eel fabrication
JECTOR HARNESS, NOTED SEVERAL INJECTORS DO					Windo	w tinting
DINOT CLICK AT ALL. REMOVED INJECTORS AND BENCH TEST, FOUND 3 II	ATECTORS DO NOT SPRAY	/ SENT				•
IJECTORS TO MARREN INJECTION SERVICES IN CT					-	em upgrades
IJECTORS AND REBUILT ALL 8. REFIT REBUILT INJECTORS. SET FUEL PRESSURE /	3PSI KOEO AND PERFOR	M FUEL LEAK			Satellite ra	dio systems
ST BEFORE REFITTING MANIFOLD. PERFORM SMOKE					Radar	detectors
ACUUM SYSTEM, PASS. CAR RAN ON ONLY 4 CYLINDERS AFTER INJECTOR F	REBUILD AND REFITTING	. REMOVE			Leathe	er repair
ND READ PLUGS, FOUND CYL 4,5,7,8 ARE BLACK /	AND FOULED.					tective film
PERFORM SCOP TEST OF INJECTOR DRIVERS AND FO DOKS NORMAL UNDER CRANKING, WHEN INJECTORS /						
EFFERENT THAN 1 AND 4. REMOVE CONNECTOR AT 3 SISTANCE TEST. EACH INJECTOR PAIR IS 1.2 OF					Cart	covers
D FOUND EACH INJECTOR PAIR CLICKS. REMOVE }					Upholster	ry products
INS FOR DRIVERS 2 AND 3 BACK OUT WHEN PRESS INNECTOR, NOTE CONNECTOR IS BRITTLE. SECURE					Apparel and	accessories
IT IS VERY CLOSE TO WATER PIPE.					Transport o	f your vehicle
NFTER REPAIRING INJECTOR PINS, FOUND CAR RUM /LINDERS. REMOVE AND READ PLUGS AGAIN, NOW (CYL 4&7 ARE WET FOUL	D AND CYL			anywhe	ere in the
ARE SOOT FOULED INDICATING TIMING CONCERS					Contine	ental US.
·8-4-3-6-5-7-2. REMOVE COIL PACKS AND FOUND CORROSION UNDER WAP COIL PACKS. MISFIRES STILL OCCUR, PULL F						UTHORIZED
SULTS. CROSS REFERENCED WITH SISTER CAR PU						SHOP
RE 1-3-2-4. SWAP COIL PACK WIRES TO MATCH CO INS ON ALL & CYLINDERS. REMOVE IAC CONNECTOR AC CONNECTOR AND PERFORM PARKING LOT RUNS, (CELERATES WITHOUT MISFIRES. RECHECK TIRE PRESSURES, WHEEL LUG NUTS, AND FIT ALL INTERIOR TRIM. JURING FINAL QC FOUND CAR WILL INTEMRITTENLY ESTARTED. FOUND TPS SIGNAL IS FLUCTUATING. A ITERMITTENT SIGNAL LOSS OF TPS. CROSS REFERENCE ELIVERED IS NOT CORRECT FIT. CROSS REFERENCE	R, SET BASE IDLE AND CAR IDLES AND RUNS SM ALL FLUIDS. CHARGE E (STALL AND IDLES HIC COUND TPS PINS ARE LO ENCE PART GM#17111471	TPS. REFIT WOTH, AND WATTERY AND WHEN WOSE CAUSING . BUT PART			The only warranties, if a and/or service are thos turer. The selling dealer all warranties, either exy ing any implied warran fitteess for a particult assumes or authorizes a	OF WARRANTIES any, applying to the part(e offered by the manufa hereby expressiv disclain pressed or implied, inclu- ities of merchantability ar purpose, and neith my other person to assum lection with the sale of the avers shall not be entitle.

any other incidental damages. The Reynolds and Reynolds Company ERAINTINVE SF2152 Q (01/18)

damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com



BENTLEY













NVOICE DATE 07/10/23 ZZCS106000 CUSTOMER NO. ag No 32945 VECT 96 DAN ABOR BATE LICENSE NO. MILEAGE COLOR STOCK NO 8839 98.00 2,323 TEAL/ EAR / MARE / MODEL DELIVERY DATE DELIVERY MILES 3/OTHER MAKE/VECTOR WX-3/COUPE 01/31/19 2,623 SELLING DEALER NO. EHICLE ID. NO. 1 V 9 V W 2 6 2 9 P W 0 4 8 0 0 1 PRODUCTION DATE T. E. NO. R. O. DATE P.O. NO. 02/24/21 OMMENTS 2623 MO: COMMENTS OTHER AVAILABLE SERVICES CQ#ECC1137. FOUND PIN HOUSING DOES NOT FIT CORRECTLY AND HOLDS PINS TOO FAR FROM SENSOR PINS, REWORK ORIGINAL TPS PIN HOUSING TO FIT PINS, NOW SIGNALS Full detail ARE IN LINE WITH GM TPS SPECS. SET TO 0.58V, ANTHING BELOW 0.6V IS IDLE PER DK. ENGINE NOW STARTS AND RUNS WITHOUT STALLING. SET IDLE SPEED AND RESET Ceramic coating TPS POSITION TO 0.58V, NOT IDLE SET TO 1200RPM TO AVOID IDLE DROPPING TOO LOW WITH AC ON. Paint correction -NOTES FOR WX3 COUPE: -SPEEDO DOES NOT WORK, NO PROVISIONS FOR SPEEDO SIGNAL ON THIS CAR Vehicle styling enhancements -ENGINE OIL DRIPS FROM DRY SUMP TANK, SIZE IS NOT AVAILABLE AND WOULD REQUIRE EXTENSIVE REWORKING TO FIT NEW TANK. TANK WAS RESEALED BUT IS Paintless dent removal SLIGHTLY WARPED AND STILL LEAKS. BE SURE OIL IS TOPPED UP BEFORE DRIVING Touch up and chip removal USING DIPSTICK IN TANK CAP. -FUEL TANK WILL ONLY READ ON GAUGE WHEN AT LEAST HALF TANK, THE IN TANK SENSOR IS NOT FULLY COMPATIBLE WITH THE ON DASH READING DUE TO UNAVAILABILITY OF SIMILAR FUEL TANK SENSOR. BE SURE FUEL IS TOPPED UP, USE Lower front bumper repairs Damaged wheel repairs 93 OCTANE WITH STABIL OR VP FUELS C9 -TRANS OIL DRIPS FROM TRANS PAN. PAN HAS BEEN CUSTOM SECTIONED FOR HIGHER Custom wheel fabrication CAPACITY AND MATING SURFACES ARE NOT TRUE. SEALED AS BEST AS POSSIBLE, PERIODICALLY CHECK TRANS OIL USING DIPSTICK IN ENGINE COMPARTMENT. Window tinting -NO WINDSHIELD WIPERS AND WINDSHIELD IS DOUBLE-STICK TAPED IN PLACE BRAKES HAVE NO BOOST OR ASSIST, BRAKES REQUIRE MORE THAN USUAL PRESSURE Stereo system upgrades WHEN COLD. THIS IS A NORMAL CHARACTERISTIC OF THE BRAKING SYSTEM FOR THIS CAR Satellite radio systems -IDLE HUNT IS NORMAL PER DK, THE ENGINE MANAGEMENT USES SPARK ADVANCE TO CONTROL IDLE SPEED AND IS A UNIQUE CHARACTERISTIC OF THE VECTOR. Radar detectors -THE WX3 COUPE WAS USED AS A TEST MULE TO PROVE THE REAR RADIATOR COOLING Leather repair CONCEPT. THOUGH IT WAS DRIVEN BY THE DESIGNERS AND ENGINEERS, IT WAS NEVER FINISHED TO BE USED AS A ROAD CAR. THE BODY IS FIBERGLASS AND VERY HEAVY, Clear protective film THE CONCEPT SEATS ARE NOT NOT FULLY ANCHORED IN, AND SOME OF THE INSTRUMENTS ARE NOT ACCURATE OR DO NOT WORK. THE AXLES ARE AT EXTREME ANGLES DUE TO THE BODY WEIGHT AND CAUSE AN OSCILLATION AT LOWER SPEEDS. THE ENGINE FITTED TO Car covers THE CAR CURRENTLY IS THE SAME BASE ENGINE USED IN THE W8 ROAD CAR WITH Upholstery products NOTABLE DIFFERENCES IN THE INTAKE SYSTEM. THE ENGINE COMPUTER IS BY ELECTROMOTIVE AND USES A TPI SYSTEM WITH GM SENSORS. ORIGINALLY, THE CAR WAS Apparel and accessories DESIGNED TO FIT A QUAD OVERHEAD CAM ENGINE THAT PROVED TO BE AN ENGINEERING CHALLENGE. THE ENGINE WAS SWAPPED WITH THIS ONE BY THE VECTOR ENGINEERS TO Transport of your vehicle FOCUS ON PROVING THE REAR MOUNTED COOLING CONCEPT, WHICH IS WHY MANY OF THE PATS IN THIS CAR ARE ONE OFF OR NOT COMPLETE. THE CAR WAS ORIGINALLY SILVER anywhere in the AND REPAINTED IN IT'S CURRENT TEAL TO MATCH WIEGERT'S AQUAJET COMPANY COLORS FOR THE 1993 GENEVA AUTOSHOW WHERE IT APPEARED WITH IT'S SISTER CAR, THE Continental US. PURPLE WX3R ROADSTER. FACTORY AUTHORIZED BODY SHOP DISCLAIMER OF WARRANTIES The only warranties, if any, applying to the part(s) and/or service are those offered by the manufacturer. The selling dealer hereby expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume for it any liability in connection with the sale of this

The Reynolds and Reynolds Company ERAINTMIVE SF2152 Q (01/18)

part(s) and/or service. Buyer shall not be entitled to recover from the selling deafer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or

186 Magee Ave. • Stamford, CT 06902 (203) 661-2555 www.millermotorcars.com


















to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or