



PORSCHE

Porsche Production Specifications

The Porsche vehicle with the identification number listed below
was manufactured with the following assembly specifications:

WP0AC2995VS375841

Model Year/Type

1997 911 Turbo S Coupe

Engine Number/Type

61V02074 (M64/60)

Production Completion Date

4/9/1997

Transmission Number/Type

2007493 (G64/51)

Manufacturer's Suggested Retail Price (MSRP)

\$155,189.00 USD

Exterior Paint Color/Code

Black/A1

Interior Material Color/Code

Black Leather/VD

Optional Equipment

US Standard Emissions
Self Dimming Mirrors & Rain Sensor
Porsche Floor Mats - Black

Leather Tray Behind Parking Brake
6 Disc Remote CD Changer
Pirelli Tires

Klaus Zellmer
President and Chief Executive Officer
Porsche Cars North America, Inc.



1997 911 TURBO S (993-780)

VIN: WP0AC2995VS375841

Gearbox Type	G6451	Gearbox Serial	2007493
Engine Type	M64/60	Engine Serial	61V02074
Tire Code	PIRE	Transmission	6-SPEED MANUAL

Country	United States		
Country Code	C02	Trading Partner	4300010
Date of Production	April 09, 1997	Commission Number	055984
Invoice Date	April 23, 1997	Production Number	1771658
		Assembly Factory	Stuttgart

Exterior

Exterior Color	Black/Black		
Exterior Paint Color	A1, Black	Roof Color	A1, Black
Exterior Color Code	L741	Conv Top Color Code	L741

Interior

Interior Trim	Black Leather Interior		
Interior Trim	VD	Seat Combination Number	ATH
Interior Trim	LE	Seat Cushion Material	LED
Carpet Color Code	5FV	Seat Side Support Material	LE
		Seat Back Material	LE

Optional Equipment (3)

Option Code	Description
692	Remote CD Changer (6 Disc)
P11	Standard Turbo Equipment
XF7	Lthr Tray Behind Parking Brake

Z Options (3)

Option Code	Description
09981	FAHRZEUG-UEBERSTELLUNG NACH ZP 7.0 AN VRS (EXC-SCHLEIFE) #GEAENDERT LT. H. HAHN/14.10.96
16981	SITZE: KOPFSTUETZEN MIT GEPRAEGTEM PORSCHE-WAPPEN (CA. 10 CM) #FZG. ERHAELT GANZLEDERAUSST. #SIEHE EHEM. Z-ANTRAG 1139 #BEP/H. GANSS HAT EINE VORLAGE #+ EINMALIGE WERKZEUGKOSTEN = # DM 1.500 ABRECHNEN!!!!!!!!!!!!!!!!!!!!#NETTO OHNE RABATT
09991	

Additional Equipment (100)

Option Code	Description
-------------	-------------

X26	Steering Wheel in Special Lthr
XN9	Lthr Sunvisors w/Make up Miror
XRF	Brake Calliper Painted Yellow
XRG	Light Metal Wheels 8X18 10X18
XTH	Dorpul Cardn w/Script in Silvr

058	STOSSFAENGER MIT AUFPRALLDAEMPFER
092	911 TURBO S (SONDERMODELL)
130	BESCHRIFTUNG ENGLISCH
139	REGELBARE SITZHEIZUNG LINKER SITZ
197	STAERKERE BATTERIE
218	KENNZEICHENHALTER AUSF. IV
220	SPERRDIFFERENTIAL
224	AUTOM. BREMSDIFFERENTIAL (ABD)
235	BRIDGESTONE N1/PIRELLI N1
288	SCHEINWERFER-REINIGUNGSANLAGE
323	OHNE ECE-REGLEMENT AUFKLEBER
335	3-PKT. AUTOMATIK-GURTE HINTEN
339	ALLRAD-ANTRIEB
340	REGELBARE SITZHEIZUNG RECHTER SITZ
425	HECKSCHEIBENWISCHER
434	ARBEITSANWEISUNG F.UEBERSEE-FAHRZG.
437	KOMFORTSITZ LINKS ELEKTR.VERSTELLB.
438	KOMFORTSITZ RECHTS ELEKTR.VERSTELLB
441	RADIOVORBEREITUNG
454	AUTOM. GESCHWINDIGKEITSREGULIERUNG
455	DIEBSTAHLSICHERUNG F. RAEDER
480	6-GANG SCHALTGETRIEBE
484	USA-AUSFUEHRUNG (OHNE KANADA)
490	KLANGPAKET
529	WEGFAHRSSICHERUNG M. FERNBED. 315MHZ
534	DIEBSTAHLSICHERUNG
544	75L-TANK
553	USA-/KANADA-AUSFUEHRUNG
562	AIRBAG FAHRER- U. BEIFAHRESEITE
566	NEBELSCHEINWERFER WEISS
567	GRUENGET. FRONTSCHIEBE M. GRUENKEIL
573	KLIMAAANLAGE ELEKTRONISCH
576	OHNE NEBELSCHLUSSLEUCHTE
599	DACHBLENDE
601	LITRONIC-SCHEINWERFER
602	HOCHGESETZTE BREMSLEUCHTE
650	SCHIEBE-/HUBDACH ELEKTRISCH
651	ELEKTRISCHE FENSTERHEBER
657	SERVOLENKUNG
659	BORDCOMPUTER
660	OBD II
685	HINTERE SITZANLAGE
688	CD-RADIO "PORSCHE CDR 210" USA
912	OHNE TYPSCILD

975	KOFFERRAUM-VERKLEID.M.VELOURTEPPICH
981	LEDER-AUSSTATTUNG (OHNE SITZBEZUG)
X43	SCHALTERR.MITTELKONS.VORN LED
X47	SCHALTKNOPF CARBON/ALU/LEDER
X50	LEISTUNGSSTEIGERUNG TURBO 430 PS
X56	INSTRUMENTENTRAEGER +BLENDE CARBON
X57	TUERSPIEGEL LI.,RE. CARBON
X58	HANDBREMSHEBEL CARB/ALU/LEDER
X70	EINSTIEGSBLENDE EDELSTAHL,SCHRIFTZ
X71	INSTR.-ZIFFERBL.LACKIERT ALUFARBE
X78	LUFTEINLAESSE VO, POSITIONSLEUCHTEN
X79	LUFTEINLAESSE FONDSEITENTEIL LI. RE
XD1	FRONTSPOILER AUS AEROKIT TURBO II
XD2	HECKSPOILER AUS AEROKIT TURBO II
XE3	AUTOMATISCH ABBLEND. INNENSPIEGEL
XE7	ZUSATZ-FRONTUELKUEHLER(F.SCHALTG.)
XF6	ABDECKUNG MITTELTUNNEL LEDERBEZOGEN
XFA	ALU-DOMSTREBE CARBON
XJ4	ROSETTE F. ZUENDSCHLOSS LEDERBEZ.
XJ6	LENKSAEULENVERKLEIDUNG LEDERBEZOGEN
XLB	4-ROHR ABGASANLAGE
XM5	BEDIENUNGSKNOEPFE ARMATURENBR.LEDER
XM7	KNOPF HANDSCHUHKASTENSCHLOSS LEDER
XM9	BETAETIGUNGSGRIFFE BLINKER LEDERBEZ
XMA	HIMMEL UND A+B-SAEULEN LEDERBEZOGEN
XN1	FENSTERHEBERSCHALTER LEDERBEZOGEN
XN3	LUFTSEITENDUESE ARMATURENBR. LEDER
XN4	LUFTMITTELDUESE ARMATURENBR. LEDER
XNA	ABDECKKAPPEN KNIELEISTE,ARMATURENBR
XP6	GURTSCHL. U.-PEITSCHEN VO. LEDERBEZ
XP9	LAUTSPRECHERRAHMEN LEDERBEZOGEN
XR3	ABDECK.F.SITZBESCHLAEGE VORN LEDER
XR6	LEHNENENTRIEGELUNG VORNE LEDERBEZ.
XV1	DEFROSTERBLENDE LEDERBEZOGEN
XV2	ABDECKKAPPEN LUFTSEITENDUESEN LEDER
XV3	BLENDE KLIMA-/HEIZREG. LEDERBEZOGEN
XV4	SCHALTER SITZHEIZUNGSREGUL. LEDER
XV5	SCHALTER F. SITZVERST. LEDERBEZOGEN
XV6	BLENDE RAHMEN SCHALTER SITZV. LEDER
XV7	KNOPF TANKDECKELBET. LEDERBEZOGEN
XV9	ABDECKUNG F.GURTDURCHFUEHRUNG LEDER
XW1	ROSETTE GURTDURCHF. VORNE LEDERBEZ.
XW2	GURTSCHL. U.-PEITSCHEN HI. LEDERBEZ
XW3	SCHALTER UHRVERSTELLUNG LEDERBEZ.
XW4	KNOPF F. LICHTSCHALTER LEDERBEZOGEN
XW5	KNOPF SCHEIBENW./INTERVALL LEDER
XW6	ROSET. LEUCHTDIODEN-ALARMANL. LEDER
XW8	ABDECKKAPPEN TUERGARNIERLEIST.LEDER
XW9	ABDECKLEISTE F. SCHWELLER LEDERBEZ.
XZ4	ROSETTE HANDSCHUHKASTENSCHLOSS LED.
XZ7	RAHMEN AUSSENSPIEGELVERST. LEDERBEZ

09981 VEHICLE TRANSITION ACCORDING TO ZP 7.0 TO VRS (EXC LOOP) #MODIFIED LT.
H.HAHU14.10.96

16981 SEATS: HEADRESTS WITH EMBOSSED PORSCHE CREST (APPROX. 10 CM) #FZG. RECEIVES
09991 FULL LEATHER EXTERIOR. #SEE FORMER Z-APPLICATION 1139 #BEP/H. GANS\$ HAS A
TEMPLATE #+ ONE-TIME TOOLING COSTS = # BILL DEM 1,500!!!!!!!!!!!!!!!!!!#NITTO WITHOUT
DISCOUNT

058 BUMPER WITH IMPACT ABSORBER
092 911 TURBO S (SPECIAL MODEL)
130 CAPTION ENGLISH
139 ADJUSTABLE HEATED LEFT SEAT
197 HEAVY DUTY BATTERY
218 LICENSE PLATE HOLDER VERS. IV
220 LOCKING DIFFERENTIAL
224 AUTO. BRAKE DIFFERENTIAL (ABD)
235 BRIDGESTONE N1/PIRELLI N1
288 HEADLIGHT CLEANING SYSTEM
323 WITHOUT ECE REGULATIONS STICKERS
335 3-PKT. REAR AUTOMATIC BELTS
339 ALL-WHEEL DRIVE
340 RIGHT SEAT HEATER ADJUSTABLE
425 REAR WIPER
434 WORK INSTRUCTIONS FOR OVERSEAS VEHICLES.
437 COMFORT SEAT LEFT ELECTR.ADJ.
438 COMFORT SEAT RIGHT ELECTRICALLY ADJUSTABLE
441 RADIO PREPARATION
454 AUTO. CRUISE CONTROL
455 ANTI-THEFT DEVICE F. WHEELS
480 6-SPEED MANUAL
484 USA VERSION (NO CANADA)
490 SOUND PACKAGE
529 IMMOBILIZER WITH REMOTE CONTROL. 315MHZ
534 ANTI-THEFT DEVICE
544 75L TANK
553 USA/CANADA VERSION
562 AIRBAG DRIVER AND PASSENGER SIDE
566 FOG LIGHTS WHITE
567 GRUENGET. WINDSCREEN WITH GREEN WEDGE
573 AIR CONDITIONING ELECTRONIC
576 WITHOUT REAR FOG LIGHT
599 ROOF PANEL
601 LITRONIC HEADLIGHTS
602 HIGH MOUNTED BRAKE LAMP
650 ELECTRIC SLIDING/LIFT ROOF

651 POWER WINDOW REGULATORS
657 POWER STEERING
659 TRIP COMPUTER
660 OBDII
685 REAR SEAT SYSTEM
688 CD RADIO "PORSCHE CDR 210" USA
912 WITHOUT ID PLATE
975 TRUNK PANEL.WITH VELOR CARPET
981 LEATHER INTERIOR (WITHOUT SEAT COVER)
X43 SWITCH REAR CENTER CONS.FRONT LED
X47 SHIFT KNOB CARBON/ALUMINUM/LEATHER
X50 PERFORMANCE INCREASE TURBO 430 HP
X56 INSTRUMENT CARRIER +COVER CARBON
X57 DOOR MIRROR LEFT,RIGHT CARBON
X58 HANDBRAKE LEVER CARB/ALU/LEATHER
X70 ENTRANCE PANELS STAINLESS STEEL,LETT
X71 INSTRUMENT DIAL PAINTED ALUMINUM COLOUR
X78 AIR INTAKES FRONT, POSITION LIGHTS
X79 AIR INTAKES REAR SIDE PART LEFT. RE
XD1 FRONT SPOILER MADE OF AEROKIT TURBO II
XD2 REAR SPOILER MADE OF AEROKIT TURBO II
XE3 AUTO DIMMING. INTERIOR MIRROR
XE7 ADDITIONAL FRONT OIL COOLER (F.SHIFT)
XF6 CENTER TUNNEL COVER COVERED IN LEATHER
XFA ALUMINUM STAY STRUT CARBON
XJ4 ROSETTE F. IGNITION LOCK LEATHER COVER.
XJ6 STEERING COLUMN COVERED IN LEATHER
XLB 4-PIPE EXHAUST SYSTEM
XM5 CONTROL BUTTONS DASHBOARD LEATHER
XM7 KNOB GLOVE BOX LOCK LEATHER
XM9 CONTROL HANDLES INDICATOR LEATHER COVER
XMA HEADLINER AND A+B COLUMNS COVERED IN LEATHER
XN1 WINDOW SWITCH LEATHER COVERED
XN3 AIR SIDE NOZZLE INSTRUMENT BR. LEATHER
XN4 AIR NOZZLE INSTRUMENT PANEL. LEATHER
XNA COVER CAPS KNEE RAIL,ARMATUREBR
XP6 BELT BUCKLE U. WHIPS VO. LEATHER COVER
XP9 SPEAKER FRAME COVERED IN LEATHER
XR3 COVER FOR FRONT SEAT FITTINGS LEATHER
XR6 BACK RELEASE FRONT LEATHER COVER.
XV1 DEFROST COVER LEATHER COVERED
XV2 SIDE AIR VENTS COVER CAPS LEATHER
XV3 DISC AIR CONDITIONING/HEATING REG. LEATHER COVERED
XV4 HEATED SEAT REGULATOR SWITCH LEATHER

XV5 SWITCH FOR SEAT LIFTING LEATHER COVERED
XV6 PANEL FRAME SWITCH SEAT V. LEATHER
XV7 BUTTON FUEL CAP BET. LEATHER COVERED
XV9 COVER FOR BELT HOLE LEATHER
XW1 ROSETTE BELT DIA. FRONT LEATHER COL.
XW2 BELT BUCKLE & WHIPS HI. LEATHER COVER
XW3 SWITCH CLOCK ADJUSTMENT LEATHER COL.
XW4 KNOB F. LIGHT SWITCH LEATHER COVERED
XW5 BUTTON WASHER/INTERVAL LEATHER
XW6 ROSET. LED ALARM. LEATHER
XW8 COVER CAPS DOOR TRIM.LEATHER
XW9 COVER RAIL F. SILL LEATHER TRIM.
XZ4 ROSETTE GLOVE BOX LOCK LED.
XZ7 FRAME EXTERIOR MIRROR REINFORCEMENT LEATHER COVER

Device**Serial/Version**

DME serial number

02500105

While every reasonable effort is made to ensure the accuracy of this data, we are not responsible for any errors or omissions contained on this page. Please verify any information in question with Porsche Cars Customer Service.

Display CARFAX in online listings: ☐

Vehicle History Report™

US \$44.99

1997 PORSCHE 911 TURBO S

VIN: WP0AC2995VS375841
COUPE
3.6L H6 F
GASOLINE
ALL WHEEL DRIVE

This CARFAX Report Provided
by:
Broad Arrow Group



No accidents or damage reported to CARFAX



5 Service history records



8 Previous owners



Personal vehicle



41 Detailed records available



20,296 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/6/23 at 1:58:55 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

	Owners 1-6	Owner 7	Owner 8
Year purchased	1997	2014	2018
Type of owner	Personal	Personal	Personal
Estimated length of ownership	17 yrs. 7 mo.	2 months	4 yrs. 9 mo.
Owned in the following states/provinces	See Details	Ohio	Montana, Connecticut
Estimated miles driven per year	See Details	---	357/yr
Last reported odometer reading	19,417	---	20,296




Title History


CARFAX guarantees the information in this section




	Owners 1-6	Owner 7	Owner 8
--	------------	---------	---------


Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem





GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.
View Terms | View Certificate

 Additional History Not all accidents / issues are reported to CARFAX	Owners 1-6	Owner 7	Owner 8
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Porsche dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported

 Detailed History			
 Owner 1 Purchased: 1997		Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 1,786 mi/yr
Date	Mileage	Source	Comments
04/30/1997	15	California Motor Vehicle Dept.	Odometer reading reported
05/27/1997		California Motor Vehicle Dept.	Title issued or updated - First owner reported - Titled or registered as personal vehicle

03/19/1998	1,874	Service Facility	 Vehicle serviced
------------	-------	------------------	---

09/30/1999	4,248	Service Facility	 Vehicle serviced - Battery replaced
------------	-------	------------------	---

 **Owner 2**
Purchased: 1999

Personal Vehicle

Date	Mileage	Source	Comments
10/12/1999	4,289	California Motor Vehicle Dept. Ramona, CA	Odometer reading reported
11/06/1999	4,632	California Inspection Station San Diego, CA	Passed emissions inspection
11/06/1999		California Motor Vehicle Dept. Ramona, CA	Title issued or updated - New owner reported

 **Owner 3**
Purchased: 2000

Personal Vehicle

Date	Mileage	Source	Comments
04/04/2000	4,959	California Motor Vehicle Dept. Cardiff by the Sea, CA	Odometer reading reported
04/27/2000		California Motor Vehicle Dept. Cardiff by the Sea, CA	Title issued or updated - New owner reported



 **Owner 4**
Purchased: 2002



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
946 mi/yr

Date	Mileage	Source	Comments
06/03/2002	9,003	Washington Motor Vehicle Dept. Kenmore, WA	Title or registration issued - New owner reported
05/19/2004		Washington Inspection Station Seattle, WA	Passed emissions inspection

06/08/2004		Service Facility	 Vehicle serviced - Trim repaired
06/26/2006	16,776	Washington Inspection Station Lynnwood, WA	Passed emissions inspection
06/29/2006		Washington Motor Vehicle Dept. Kenmore, WA Title #0215414702	Registration issued or renewed - Vehicle color noted as Black
05/25/2007		Washington Motor Vehicle Dept. Kenmore, WA Title #0215414702	Registration issued or renewed - Vehicle color noted as Black
05/08/2012		Washington Inspection Station Lynnwood, WA	Passed emissions inspection
05/08/2012		Washington Motor Vehicle Dept. Kenmore, WA Title #0215414702	Registration issued or renewed - Vehicle color noted as Black
06/08/2012	18,135	Porsche Bellevue Bellevue, WA 425-467-6000 porschebellevue.com/index.htm ★ 4.5 / 5.0 177 Verified Reviews ❤️ 171 Customer Favorites	 Vehicle serviced
06/12/2012	18,500	Dealer Inventory	Vehicle offered for sale
06/27/2012		Ohio Motor Vehicle Dept. Solon, OH Title #4302406104	Vehicle purchase reported - Title issued or updated - Dealer took title of this vehicle while it was in inventory
10/12/2012		Dealer Inventory Solon, OH	Vehicle offered for sale

**Owner 5**

Purchased: 2012

Personal Vehicle

Date	Mileage	Source	Comments
12/07/2012		Ohio Motor Vehicle Dept.	Vehicle purchase reported
12/18/2012		Ohio	Title issued or updated

Motor Vehicle Dept.
Mansfield, TX
Title #4302483363

- New owner reported

03/08/2013

Texas
Motor Vehicle Dept.
Mansfield, TX
Title
#22044441331170454

Title issued or updated

- Loan or lien reported
- Vehicle color noted as Black

02/01/2014

Texas
Motor Vehicle Dept.
Mansfield, TX
Title
#22044441331170454

Registration issued or renewed

- Loan or lien reported
- Passed safety inspection
- Vehicle color noted as Black

07/26/2014

Dealer Inventory

Vehicle offered for sale



Owner 6

Purchased: 2014

Personal Vehicle

Date	Mileage	Source	Comments
------	---------	--------	----------

10/30/2014	19,417	Ohio Motor Vehicle Dept. Solon, OH Title #4302819040	Vehicle purchase reported - Title issued or updated - New owner reported
------------	--------	---	---



Owner 7

Purchased: 2014

Personal Vehicle

Date	Mileage	Source	Comments
------	---------	--------	----------

12/10/2014		Ohio Motor Vehicle Dept.	Vehicle purchase reported
------------	--	-----------------------------	----------------------------------

12/11/2014		Ohio Motor Vehicle Dept. Title #4302838981	Title issued or updated - New owner reported
------------	--	--	--

02/24/2015		Dealer Inventory	Vehicle offered for sale
------------	--	------------------	---------------------------------



Owner 8

Purchased: 2018






Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
357 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------

09/24/2018		Montana Motor Vehicle Dept.	Vehicle purchase reported
------------	--	--------------------------------	----------------------------------

10/23/2018		Montana	Title issued or updated
------------	--	---------	--------------------------------

		Motor Vehicle Dept. Missoula, MT Title #AA4220856	- New owner reported - Vehicle color noted as Black
01/10/2019		Montana Motor Vehicle Dept. Missoula, MT Title #AA4314483	Title issued or updated - Vehicle color noted as Black
06/07/2019	19,497	Connecticut Inspection Station New Canaan, CT	Failed emissions inspection
06/07/2019	19,527	Connecticut Inspection Station New Canaan, CT	Passed emissions inspection
06/07/2019		Connecticut Motor Vehicle Dept. Mystic, CT	Registration issued or renewed - Vehicle color noted as Black
08/30/2021	20,296	Hank May's Discount Tire & Auto Center - Stamford Stamford, CT 203-348-3000 hankmays.com/stamford.htm  4.6 / 5.0 110 Verified Reviews  109 Customer Favorites	 Vehicle serviced - Emissions or safety inspection performed
08/30/2021		Connecticut Inspection Station Stamford, CT	Passed emissions inspection
09/14/2021		Connecticut Motor Vehicle Dept. Mystic, CT	Title or registration issued - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Black
04/26/2023		Vehicle Importer	Vehicle exported from Indiana and imported to Ontario - Vehicle may not comply with Canada Motor Vehicle Safety Standards
04/26/2023		Connecticut Motor Vehicle Dept. Mystic, CT	Registration issued or renewed - Vehicle color noted as Black

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:facebook.com/CARFAX[@CARFAXinc](https://twitter.com/CARFAXinc)[About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.

7/6/23 1:58:55 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1997 PORSCHE 911 vehicle (VIN: WP0AC2995VS375841), which is based on information supplied to CARFAX and available as of 7/6/23 at 2:58 PM (EDT).

Customer Signature

Date

Dealer Signature

Date

BECK'S EUROPEAN

Beck's-An Independent Porsche

8215 East Jutherus Drive
 Scottsdale, AZ 85260
 480-566-6572 602-997-6572
 www.beckseuropean.com

License		VIN WP0AC2995VS375841		Year 1997	
Make Porsche		Model 993 Turbo S			
Engine		Transmission Manual			
In Mileage 19439	Out	Fleet #		P.O. Number	
Prod Date 03/97	Turbo/Non	Color Black	Body Style Coupe	Ext. War.	Written By: KB

Problem Statements

Assess any oil leaks.

Labor Operations

Tech	Type	Description	Price
SM	Lab	Customer complaint: Oil leaks. Diagnose timing chain cover leaks. Replace sealing grommets as necessary.	\$249.34
FB	Lab	Check clutch operation. Replace hydraulic accumulator.	\$187.01
KB	Lab	2.5% Discount	(\$18.18)
Labor Total			\$418.17

Parts

Part Number	Part Description	Status	Qty	Price Ea.	Total
96410514001	Rubber Seal Ring	N	5.00	\$4.48	\$22.40
99731416600	Clutch Hydraulic Accumulator	N	1.00	\$199.80	\$199.80
Parts Total					\$222.20

Pre-Pay	Payment	Total Tax	Taxable Parts	NonTax Parts	Total Parts	From date of service - 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in workmanship to the vehicle in this facility only. Does not include racing products/services. Towing not included.	Date
\$0.00	Cash \$707.24	\$19.49	\$222.20	\$0.00	\$222.20		10/18/2018
\$0.00	Check						RO # 12409
\$0.00	Chk #	\$23.00	Labor \$418.17	Sublet \$0.00			RO Total \$707.24
\$0.00	Credit		NonTax Labor \$0.00	NonTax Sublet \$0.00			Balance Due \$0.00
\$0.00	Type Expires	\$7.73	Total Labor \$418.17			Signature or Initial	Date
\$0.00	Paid \$707.24	\$16.65					

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
Scottsdale, AZ 85260
480-556-6572 602-997-6572
www.beckseuropean.com

License		VIN		Year	
		WP0AC2995VS375841		1997	
Make		Porsche		Model	
				993 Turbo S	
Engine				Transmission	
				Manual	
In	Mileage	Out	Fleet #	P.O. Number	
	19417				
Body Style		Coupe		Ext. War.	
				Written By: KB	
Prod Date		03/97		Turbo/Non	
				Color	
				Black	

Problem Statements

White smoke coming out the tail-pipes. Please diagnose.
Vehicle had to be jumped to start this morning, we may need to jump it (DO NOT diagnose).

Labor Operations

Tech	Type	Description	Price
SM	Lab	Install turbocharger inlet check line kit with check valves.	\$498.68
Labor Total			\$498.68

Parts

Part Number	Part Description	Status	Qty	Price Ea.	Total
	Turbocharger Inlet Check Line Kit with Check Valves	N	1.00	\$650.00	\$650.00
Parts Total					\$650.00

Authorization

Date/ Time	Spoke to/ Phone	Amount/ Emp.	Comment/ Reason
7/11/2018 1:31pm	The Stables (Chris) 480-699-3095 office	KB	Chris called and gave authorization on repairs that were discussed with Frank Beck.
7/11/2018 11:35am	The Stables (Chris) 480-699-3095 office	FB	Frank called and spoke with Chris in regard to turbo oil lines. Quoted approximately \$1000 parts and labor.

Pre-Pay	Payment	Total Tax	Taxable Parts	NonTax Parts	Total Parts	Labor	Sublet	NonTax Labor	NonTax Sublet	Total Labor	From date of service - 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in workmanship to the vehicle in this facility only. Does not include racing products/services. Towing not included.	Date	RO #	RO Total	Balance Due
\$0.00	Cash	\$0.00	\$650.00	\$0.00	\$650.00	\$498.68	\$0.00	\$0.00	\$0.00	\$498.68		7/19/2018	12172	\$1,199.71	\$0.00
\$0.00	Check														
\$0.00	Chk #	\$10.43													
\$0.00	Credit	\$10.73													
\$0.00	Type														
\$0.00	Expires														
\$0.00	Paid	\$29.87													
		\$1,199.71													



PO18_r0061

Chassis Number: WP0AC2995VS375841

Model Year/Type: 1997 911 Turbo S Coupe

Production Completion Date: 1997-04-09

Manufacturers Suggested Retail Price: \$155,189.00 USD

Engine Number Type: 61V02074 (M64/60)

Transmission Number Type: 2007493 (G64/51)

Exterior Paint Color/Code: Black/A1

Interior Material Color/Type: Black Leather/VD

Optional Equipment:

- US Standard Emissions
- Self Dimming Mirrors & Rain Sensor
- Porsche Floor Mats – Black
- Leather Tray Behind Parking Brake
- 6 Disc Remote CD Changer
- Pirelli Tires

Chassis

- TYPE Rear-engine, all-wheel drive
- CURB WEIGHT 3,307 lbs.
- HEIGHT 51.77 in/1,315 mm
- GROUND CLEARANCE 5.12 in/130 mm
- LENGTH 167.72 in/4,260 mm
- WHEELBASE 89.45 in/2,272 mm
- WIDTH 70.67 in/1,795 mm
- TRACK FRONT 55.55 in/1,411 mm
- TRACK REAR 59.21 in/1,504 mm
- DRAG COEFFICIENT .34
- WHEEL SIZE FRONT 18 x 8
- WHEEL SIZE REAR 18 x 10
- TIRE SIZE FRONT 225/40ZR-18
- TIRE SIZE REAR 285/30ZR-18

Brakes

- CALIPER FRONT Fixed 4-piston
- CALIPER REAR Fixed 4-piston
- DISC TYPE FRONT Ventilated and cross-drilled discs
- DISC TYPE REAR Ventilated and cross-drilled discs
- DISC SIZE FRONT 12.68 in/322 mm x 1.26 in/32 mm
- DISC SIZE REAR 12.68 in/322 mm x 1.10 in/28 mm

Performance

- 0 TO 60 MPH 4.4 seconds
- TOP SPEED 183 mph

Fuel

- MPG CITY 11
- MPG HIGHWAY 17
- MPG COMBINED 14
- FUEL TANK CAPACITY 19.4 U.S. gallons
- REQUIRED OCTANE Premium unleaded (91+)

* Behind the Numbers

Porsche 993 Turbo S

The 993 Turbo S had carbon-fiber and leather interior trim

During the second to the last year of production of the 993 (1997), Porsche offered the 993 Turbo S. Ultimately 183 cars were sold. The Turbo S is a high-specification Turbo including a power upgrade to 450 hp (DIN) (424 hp (SAE) for the American market). The inclusion of extras including carbon fiber decoration in the interior makes it different from the earlier lightweight, spartan 964 Turbo S. The 993 Turbo S is recognized by yellow brake calipers, a slightly larger rear wing, a quad-pipe exhaust system and air scoops behind the doors. This was the last of the air-cooled 911 Turbos. 12 cars were delivered to Australia.

Unlike some other special-edition models, Porsche did not sacrifice creature comforts and usability for track performance with the Turbo S. Inside was a luxurious full leather interior with generous amounts of carbon fiber trim on the lower portion of the dashboard, around the gauges, along the doorsills, and on the center console, door panels, and door pulls. It even has an electric sunroof.

This black-on-black Turbo S, when purchased new, resided with its first owner in California. According its accompanying CARFAX report, there have been six subsequent owners before it was acquired by the current consignor, a prodigious Porsche collector. Exterior features on the car include a sunroof, vented rear wing, rear windshield wiper, and Turbo S badging. The car features yellow brake calipers, a nice touch against the black exterior, and large ventilated four-wheel disc brakes behind factory wheels featuring Porsche crest center caps. The car is powered by a 3,605-cc SOHC air-cooled horizontally opposed six-cylinder engine with twin turbochargers and Bosch Motronic management. The engine is paired to a six-speed manual transaxle, with power distributed to all four wheels for incredible grip and acceleration.

Inside is a luxurious full black leather interior that features generous amounts of carbon fiber trim on the lower portion of the dashboard, around the gauges, door panels, and door pulls. The driver and passenger seats feature the Porsche crest in the headrest; rear seats offer the flexibility of additional passenger space or extra luggage space when folded down. Power amenities are abundant, and the car retains the Porsche factory radio with CD. Air conditioning keeps occupants cool on warmer days. The odometer read 19,426 original miles at the time of cataloguing. The car is accompanied by a collapsible Vredestein spare tire and compressor.

The Turbo S delivered stunning performance in a package as luxurious and exclusive as discerning Porsche customers had come to expect. It really was the ultimate supercar that could comfortably be driven as a daily commuter. Collectors today value the Turbo S for its rarity, performance, and the timeless styling of the final iteration of the legendary air-cooled Turbo.

Speedsport Tuning
 52 Miry Brook Road
 Danbury, CT 06810
 203 730-0311

Estimate #0001458
 Date : 7/18/19
 Page : Page 1 of 2
 Center : 1

Vehicle : 1997 PORS 911 TURBO S
 License : 00LATG
 VIN : WP0AC2995VS375841
 Fleet #:
 Engine :
 Mileage : 19527
 CLR : BLACK
 Trans :
 4WD :

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts	Subtotal
Quan	Part Number					Price	
OIL064	BE	993 OIL CHANGE WITH TOTAL OIL DRAINED ENGINE OIL, REMOVED RT LOWER ROCKER TO REPLACE OUTER FILTER. INSTALLED NEW OIL FILTERS, INSTALLED NEW DRAIN PLUG WASHER, FILLED WITH TOTAL 5/40 ENGINE OIL, RAN ENGINE AND CHECKED OVER CAR			195.00	156.48	351.48
	2.00		ALUMINUM SEAL RING			2.92	
	1.00		Oil Filter			25.08	
	1.00		Oil Filter			19.28	
	12.00		FULL SYNTHETIC 5/40 ENGI			109.20	
CS 0	BE	Remove and repalce cabin filters.			139.00	30.91	169.91
	1.00		Cabin Air Filter Set			30.91	
	BE	Remove and replace front brake rotors, pads, sensors and shims.			347.50	1111.27	1458.77
	1.00		Brake Disc-Front Lef			391.12	
	1.00		Brake Disc-Front Rig			384.22	
	2.00		Brake Pad Sensor-Fro			41.16	
	1.00		Brake Pad Set-Front			230.85	
	4.00		Brake Pad Shim-Front			31.96	
	4.00		Brake Pad Shim-Front			31.96	
	BE	Remove and replace rear brake pads, rotors, sensors and shims.			347.50	940.52	1288.02
	1.00		Brake Disc-Rear Left			271.30	
	1.00		Brake Disc-Rear Righ			271.30	
	2.00		Brake Pad Sensor-Rea			41.16	
	1.00		Brake Pad Set-Rear w			264.48	
	4.00		Brake Pad Shim-Rear			30.40	
	4.00		Brake Pad Shim-Rear			61.88	
TRK002	BH	MOUNT AND BALANCE FOUR TIRES.			160.00	1340.48	1500.48
	4.00		TIRE DISPOSAL FEE			18.00	
	2.00		MICH PS2 225/40/18			452.68	
	2.00		MICHELIN PS2 285/30/18			772.26	
	1.00		SHIPPING & HANDLING			87.54	
BRK502	BH	COMPLETE BRAKE FLUID FLUSH AND EXCHANGE WITH NEW PORSCHE SPEC DOT4 BRAKE FLUID.			155.00	26.00	181.00
	1.00		BRAKE FLUID			26.00	
ALG502	BH	FOUR WHEEL PORSCHE STREET ALIGNMENT. - <i>straighten steering wheel</i>			300.00		300.00
CS 0	BE	Diagnose and replace passenger side door lock actuator.			500.40	115.99	616.39
	1.00		DOOR LOCK ACTUATOR			115.99	
	BE	Remove and replace front hood shocks.			41.70	77.46	119.16
	2.00		Hood Strut-Front Fro			77.46	
	BE	Remove speedometer to be sent out for internal repair. Reinstall upon arrival.			166.80		166.80
SUB589	SUB	SUBLET: Repair/rebuild speedometer as needed. Odometer is inop.			350.00	125.00	475.00
	1.00		FEDEX NEXT DAY AIR			125.00	
CS 0	BH	Remove and replace clutch as needed.			2710.50	3790.99	6501.49
	1.00		CLUTCH DISC			598.50	
	1.00		PRESSURE PLATE			690.56	
	9.00		BOLT			43.65	
	1.00		RELEASE BEARING			257.23	

DE theft deterrent - cannot lock car.

Speedsport Tuning
 52 Miry Brook Road
 Danbury, CT 06810
 203 730-0311

Estimate #0001458
 Date : 7/18/19
 Page : Page 2 of 2
 Center : 1

Vehicle : 1997 PORS 911 TURBO S
 License : 00LATG
 VIN : WP0AC2995VS375841
 Fleet #:
 Engine :
 Mileage : 19527
 CLR : BLACK
 Trans :
 4WD :

Op	Tech	Description				Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement			Price		
2.00		BUSHING				11.46		
1.00		CLUTCH FORK				285.63		
1.00		GUIDE TUBE				151.49		
1.00		BEARING				13.69		
2.00		SEAL				13.90		
1.00		NEEDLE BEARING				12.97		
1.00		COVER				1.98		
1.00		FLYWHEEL				1651.25		
9.00		FLYWHEEL BOLT				58.68		

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
----	-----	----------------	----	-----	----------------	----	-----	----------------

Labor : \$5,063.40
 Parts : \$7,715.10
 Sublet : \$350.00
 Other Fees : \$0.00
 Supply Charg \$48.98
 Subtotal : \$13,177.48
 Sales Tax : \$836.77
 Total : \$14,014.25
 Estimate Only



52 Miry Brook Road
Danbury, CT 06810
203 730-0311

Repair Order # 0023684

Orig Est #:

Date: 8/7/2019

Page 1 of 2

Center : 1

Customer

Vehicle : 1997 Porsche 911 turbo s

CLR : BLACK

Address

VIN : WP0AC2995VS375841

City

Fleet #:

Trans :

Cell

Engine :

4WD :

Work

Mileage : 19527

Tech	Job Description	Labor	Parts Price	Subtotal
Qty	Part Number	Part Description		
BH	Front end vibration particularly when the front is under load. Feels like tie rods or perhaps front rotors out of round	0.00		
BH	Straighten steering wheel.	0.00		
BH	Correct OE theft deterrent system. Buzzer goes off randomly and the car will not lock either with the key or remote. It locks and then immediately unlocks	0.00		
BH	Clutch needs adjustment (I think?). There is a lot of travel in the pedal	0.00		
BH	The odometer does not work. It just recently broke	0.00		
BH	I put about 400 miles on the car but a general going through would not hurt in case you see anything else that needs attention.	0.00		
BH	Technician Notes:			
	Oil service			
	Cabin filters			
	Front brakes (rotors have rust spots)			
	Rear brakes (same rust causing pulsation)			
	Balance tires			
	Clutch engages high, will need to be replaced when it starts to slip			
	Toyo tires are 8 years old!			
	Wheels have been painted			
	Brake fluid flush			
	Alignment, pulls left			
	Passenger door lock actuator is bad			
	Front hood shocks are weak			
	Remove speedo for odometer repair			
BH	993 OIL CHANGE WITH TOTAL OIL DRAINED ENGINE OIL, REMOVED RT LOWER ROCKER TO REPLACE OUTER FILTER. INSTALLED NEW OIL FILTERS, INSTALLED NEW DRAIN PLUG WASHER, FILLED WITH TOTAL 5/40 ENGINE OIL, RAN ENGINE AND CHECKED OVER CAR	195.00	161.22	356.22
	2.00 ALUMINUM SEAL RING		2.92	
	12.00 FULL SYNTHETIC 5/40 ENGINE OIL		109.20	
	1.00 OIL FILTER		19.28	
	1.00 OIL FILTER		29.82	
BH	Remove and replace cabin filters.	139.00	30.91	169.91
	1.00 CABIN AIR FILTER SET		30.91	
BH	Remove and replace front brake rotors, pads, sensors and shims.	347.50	111.27	1458.77
	1.00 BRAKE DISC COATED		391.12	
	1.00 BRAKE DISC COATED		384.22	
	2.00 BRAKE PAD SENSOR ELE		41.16	
	1.00 BRAKE PAD SET OE REP		230.85	
	4.00 BRAKE PAD SHIM		31.96	
	4.00 BRAKE PAD SHIM		31.96	
BH	Remove and replace rear brake pads, rotors, sensors and shims.	347.50	940.52	1288.02
	1.00 BRAKE DISC COATED		271.30	
	1.00 BRAKE DISC COATED		271.30	
	2.00 BRAKE PAD SENSOR ELE		41.16	
	1.00 BRAKE PAD SET OE FOR		264.48	
	4.00 BRAKE PAD SHIM		30.40	
	4.00 BRAKE PAD SHIM 4 REQ		61.88	
BH	MOUNT AND BALANCE FOUR TIRES.	160.00	934.37	2094.37
	4.00 TIRE DISPOSAL FEE		18.00	
	2.00 MICH PS2 225/40/18		674.54	
	2.00 MICHELIN PS2 285/30/18		1158.18	
	1.00 SHIPPING & HANDLING		83.65	
BH	COMPLETE BRAKE FLUID FLUSH AND EXCHANGE WITH NEW PORSCHE SPEC DOT4 BRAKE FLUID.	155.00	26.00	181.00
	1.00 BRAKE FLUID		26.00	



52 Miry Brook Road
Danbury, CT 06810
203 730-0311

Repair Order # 0023684

Orig Est #:

Date: 8/7/2019

Page 2 of 2

Center : 1

Vehicle : 1997 Porsche 911 turbo s

CLR : BLACK

VIN : WP0AC2995VS375841

Fleet #:

Engine :

Mileage : 19527

Trans :

4WD :

Tech	Job Description	Qty	Part Number	Part Description	Labor	Parts Price	Subtotal
BH	FOUR WHEEL PORSCHE STREET ALIGNMENT.				300.00		300.00
BH	Diagnose and replace passenger side door lock actuator.				500.40	143.32	643.72
	1.00			SHIPPING & HANDLING		27.69	
	1.00			DOOR LOCK ACTUATOR		115.63	
BH	Remove and replace front hood shocks.				41.70	77.46	119.16
	2.00			HOOD STRUT FRONT HOO		77.46	
BH	Remove speedometer to be sent out for internal repair. Reinstall upon arrival.				166.80		166.80
SUB	SUBLET: Repair/rebuild speedometer as needed. Odometer is inop.				300.00	125.00	425.00
	1.00			FEDEX NEXT DAY AIR		125.00	

Payments:

VISA, \$7712.45, on 08/07/19

I hereby accept the repair work that has been performed by SST Auto, Inc and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by the unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage from freezing due to lack of antifreeze. Used and taken off parts left for more than fifteen days become the property of SST Auto, Inc.

WOULD YOU LIKE TO HAVE YOUR CAR WASHED? YES _____ NO _____ *****

Labor : \$2,352.90
Parts : \$4,550.07
Sublet : \$300.00
Other Fees : \$0.00
Supply Charges : \$48.98
Subtotal : \$7,251.95
Sales Tax : \$460.50

Total : \$7,712.45

Paid : \$7,712.45
Due : \$0.00

Signature X _____

8/7/2019 2:36:22 PM Auth 086694

Ref

SUCCESS

\$ 7,712.45

Agrees to Pay Total Amount According to

VISA *****9545 Card Issuer Agreement

Signature X

Manwa

1997 Porsche 911 Turbo (Black)VIN: WP0AC2995VS375841
Mileage: 19,770**911 Oil Service**

Description	Price	QTY	Subtotal
1 Set up car on lift, Drain both tank and engine case. Replace oil filter and clean area around filter. Inspect suspension and brakes, tire condition, set tire pressures. Top off fluids as necessary. Lubricate door, engine cover, and front trunk hinges.			\$230.07
2 SPECTRO MG 20/50	\$8.25	12	\$99.00
3 PARTS CLEANER	\$5.89	1	\$5.89
4 SEAL RING	\$2.43	2	\$4.86
5 OIL FILTER Note: OC213	\$25.20	1	\$25.20
6 OIL FILTER Note: OC229	\$29.12	1	\$29.12
EPA (1%): \$3.94 Shop Supplies (6.8%): \$26.80 Tax (6.35%): \$26.98			Total: \$451.86

Brake fluid flush

Description	Price	QTY	Subtotal
1 COMPLETE BRAKE FLUID FLUSH AND EXCHANGE WITH NEW PORSCHE SPEC DOT4 BRAKE FLUID.			\$160.00
2 BRAKE FLUID SL6 Note: DOT 4 LOW VISCOSITY ATE FLUID	\$24.29	1	\$24.29
EPA (1%): \$1.84 Shop Supplies (6.8%): \$12.53 Tax (6.35%): \$12.62			Total: \$211.28

RADAR

DISCONNECTED POWER TO RADAR/JAMMER PER CUSTOMER REQUEST

Description	Subtotal
	Total: \$0.00

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

Parts	\$188.36
Labor	\$390.07
Subtotal	\$578.43
Shop Supplies	\$39.33
EPA	\$5.78
Tax	\$39.60
Grand Total	\$663.14
Paid To Date	(\$663.14)

REMAINING BALANCE	\$0.00
--------------------------	---------------

Payments

8/5/2021

\$663.14