

PORSCHE

2019 911 Speedster

Model Year	2019	Warranty Start Date	06-16-2020
Model Code	991890	Transmission	Manual
Model Type	911 Speedster	Engine	Gasoline
VIN	WPOCF2A94KS172639	Exterior Color	GT Silver Metallic
Commission Number	D39780	Interior Color	Leather Interior in Black/Cognac i.o.w. Heritage Design Package
Total Retail Price*	\$311,600	Top Color	Speedster Top in Black

Optional Equipment

Option Code	Description	Price (USD)
991890	911 Speedster	
ZA	Leather Interior in Black/Cognac i.o.w. Heritage Design Package	
U2	GT Silver Metallic	
XWW	Heritage Design Package	
XWV	Deletion of Heritage Design Package Exterior Trim	
474	Front Axle Lift System	
GR5	Chrono Package	
082	Extended Range Fuel Tank, 23.7 gal	
346	Wheels Painted in Silver	
573	2-Zone Automatic Climate Control incl. Air Conditioning	
583	Smoking Package	
581	Luggage Net in Passenger Footwell	
509	Fire Extinguisher	
CZW	Dashboard Trim Package in Leather	
CXM	Door Panel Trim Package in Leather	
XNS	Steering Column Casing in Leather	
QH1	Voice Control	
9VL	BOSE® Surround Sound System	
630	Light Design Package	
P13	Auto-Dimming Mirrors with Integrated Rain Sensor	

Total Retail Vehicle Price:	\$308,650
Delivery, Processing and Handling Fee:	\$1,250
Gas Guzzler Tax:	\$1,700
Total of Charges & Taxes:	\$2,950
Total Retail Price*:	\$311,600

*Total Retail Price is the Manufacturer's Suggested Retail Price (MSRP) plus options and manufacturer charges and taxes. It excludes tax, title, registration, and dealer charges. Dealer sets actual selling price.
While every reasonable effort is made to ensure the accuracy of this data, we are not responsible for any errors or omissions contained on this page. Please verify any information in question with Porsche Cars North America.

© 2023 Porsche Cars North America, Inc.

1 / 1

Printed 9/27/2023

From: Chris Fiffie chris@meritpartners.com
Subject: Re: Porsche 911 Speedster
Date: Sep 29, 2023 at 9:49:03 AM

I do apologize. I misspoke it is Porsche North Houston who will be picking the vehicle up this today.

The stock wheels for 639 will be delivered with the vehicle.

As per our conversation on the phone, the factory specification decals will be applied to the new speedster. "57" will be on the side of the car.

Please keep the car cover and trickle charger that you currently have. "639" will come with 2 keys, books, Window sticker and any service records available. (I will confirm the most recent service)


Chris,

Thank you and your associates for attending to this matter. A few points of clarification. Previously you indicated North Houston. Now Dallas?

I understand they are picking the car up today and I will plan to give them the stock set of wheels and tires to put back on 777. I trust the existing, stock wheels and tires on 639 will be delivered with the car, as well?

As to the livery, I had asked you to confirm this will be to factory specification paint to the front fascia, hood and fenders and meatball decals. You asked me to specify a number and that would be "57".

As to 639, have they done any service, if so, service records? You sent a build sheet, but do they have window sticker, car cover, manuals, trickle, etc.? You indicated I should just keep the ones from 777, but I don't think that is good for the next owner?

Finally, I sent you a text yesterday that the clutch finally released, yesterday and is working again. That said, there must be a gremlin in there and I hope they find it when they interpret the codes. Really pathetic on a 300 mile example.

Please respond ASAP, as they are picking up 777, today.

Thank you.

Warm regards,

Sent from my iPhone

> On Sep 29, 2023, at 8:14 AM, Chris Fiffie <chris@meritpartners.com> wrote:

>

>

> Good morning,

>

> I am writing to formally confirm our agreement for the acquisition of a new Heritage 911 Speedster. This transaction entails an equitable exchange, with your current 911 Speedster (VIN: WPOCF2A95KS172777) being traded for the new 911 Speedster (VIN: WPOCF2A94KS172639).

>

> Key points to highlight:

- >
- > 1. The Heritage Speedster (VIN: 2639) will be delivered with the distinctive heritage livery already applied.
- >
- > 2. Your current Heritage Speedster will undergo necessary repairs for the clutch issues. Merit Partners will cover the cost of these repairs.
- >
- > 3. The aftermarket wheels will be professionally swapped at Porsche of Dallas, ensuring a seamless transition.
- >
- >
- > Should you have any questions or require further details, please do not hesitate to reach out.
- >
- > Warm regards,
- >
- > Chris