



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
8/22/2024	JF7653

Name / Address

Vehicle Info
2009 Mercedes SL63 AMG WDBSK70F79F145237 Miles: 51219 SILVER

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Cust Issue	MILES IN: 51273 A Service, Wiper Blades, Cabin and Engine Air Filters - Fresh Tires with New TPMS Sensors - don't want battery issues get key working or replace - Replaced the batteries and it seems to function. Double check all functions	1	0.00	0.00
Repair Labor	ELECTRICAL ISSUES Car had issues with no key fob, no window operation for door open - Car would start - ran codes - had multiple communication codes, low voltage codes across all modules - Found that house battery was not holding correct charge - replaced house battery - did full fuse check in all fuse boxes - did window and system relearn. All functions have now returned.	2.5	146.00	365.00
Parts	CR2032 Key Fob Battery	1	6.99	6.99T
Parts	OR Super Start Platinum Battery 48PLT list \$440.66 SERVICE	1	287.09	287.09T

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
8/22/2024	JF7653

Name / Address

Vehicle Info
2009 Mercedes SL63 AMG WDBSK70F79F145237 Miles: 51219 SILVER

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Repair Labor	Drained the oil and replced the filter. Refilled with oil. Checked fluids and adjusted as needed. Installed the engine air filter and cbin air filter. Inspected the car for any other needs. Tires are needed and it is scheduled for new tires. No other needs found. Checked oil level, level is good. Reset Service reminder	2	146.00	292.00
Parts	WP Hengst Oil Filter 0001803009 list \$20.00	1	15.86	15.86T
Parts	WP LiquiMoly Synthetic Oil LM 2332 list \$72.93	2	49.87	99.74T
Parts	WP Mann Air Filter Set 1560940504 list \$56.00	1	45.74	45.74T
Parts	WP Mann Cabin Air Filter 2308300418 list \$142.00	1	67.91	67.91T
Parts	WP Bosch Wiper Blade Set 3397118948 list \$58.00	1	37.19	37.19T
	TIRES			
Repair Labor	Mount and Balance 4 new tires and TPMS Sensors	2.5	95.00	237.50
Parts	TRW Michelin Pilot Sport 4S 255/35R19 96Y XL 66901	2	306.99	613.98T
Parts	TRW Michelin Pilot Sport 4S 285/30R19 98Y XL 14185	2	399.99	799.98T
Shipping	Shipping	1	44.32	44.32
Parts	WP VDO/Conit Redi TPMS Sensor SE10007 list \$216.15 MISFIRE AND CEL	4	45.89	183.56T

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
8/22/2024	JF7653

Name / Address

Vehicle Info
2009 Mercedes SL63 AMG WDBSK70F79F145237 Miles: 51219 SILVER

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Repair Labor	On final test drive - We noticed a random misfire on prior drives on final road test the car finally coded - Further diag found that we had a misfire on Cyl 1 - We did a coil swap and the issue stayed with Cyl #1 - further inspection with fuel trims and scan tool data found a misbehaving fuel injector - We Pulled Fuel rail and repalced #1 Injector and all injector o-rings on right bank. Cleared Codes and Redrove - Misfire and codes did not return. Added fuel.	2.5	146.00	365.00
Parts	WP Bosch Fuel Injector 1560780023 list \$112.00	1	59.29	59.29T
Parts	WP Bosch Fuel Injector Seal 1280210711 list \$4.90	4	2.27	9.08T
Parts	WP Elring Fuel Injector O-Ring 06A906149B list \$9.29	4	6.39	25.56T
Fuel Charges	Fuel Charges	1	20.42	20.42
	TAKE CAR TO HAGERTY			
	COMPLETE TICKET [REDACTED]			

	<b>Subtotal</b>	\$3,576.21
	<b>Sales Tax (7.0%)</b>	\$157.64
	<b>Total</b>	\$3,733.85
	<b>Payments/Credits</b>	\$0.00
	<b>Balance Due</b>	\$3,733.85