

TOYOTA

Supra

JT164JA8000027190

Dossier documenting Toyota Supra's JT164JA8000027190

1. First paint condition by 31/12/2022


1.1. Paint Meter Chart



1.2. Paint defects



2. Paint measurements as per of today, after very high quality respray

2.1. Paint measurements from 80 to 200 microns

1.1. Paint Meter Chart







1.2. Paint Defects















2.1. Paint Measurements After Respray

Paint after respray



