

The Ultimate Driving Machine®

2002 Z8



Manufacturer's Suggested Retail Price \$ 130,000.00

Options and Additional Charges:

Optional equipment may be priced differently than shown. Check with your authorized Center.

Jet Black	Included
Soft Leather Drama Black	Included
Optional Timeport Phone Kit	Included
Destination Charge	\$ 645.00
Gas Guzzler	\$ 2,100.00
Total Suggested Retail Price	\$ 132,745.00

The BMW Advantage

- 3 year/50,000 mile Full Maintenance Program
- 4 year/50,000 mile limited warranty
- Six year limited rust perforation warranty
- BMW Roadside Assistance Program
- 4 year/50,000 mile

Standard Features

Engineering and Safety Features

- 5 liter DOHC, dual VANOS 22-valve V-8 engine
- Six-speed manual transmission
- Synchronized valve control of 8 individual needles
- M Driving Dynamics Control
- Dynamic Stability Control (DSC) Dynamic Brake Control (DBC) and M Drive Selection (MDS) with integral slip differential
- Adaptive space frame
- Dual threshold "Saver" airbags for driver and passenger
- Dual door-mounted side-impact airbags
- Automatic seatbelt pre-tensioners, sport seats
- Coded Drivetrain Protection
- Four-wheel ventilated anti-lock disc brakes
- Z8 double spoke forged 18" light alloy wheels with 245/45ZR18 Sport 275/40Z18 rear performance run flat tires
- Tire Pressure Monitoring
- Xenon headlights
- Automatic shift tip
- Rollover protection
- Neon brake lights, front and rear red-side lights

Comfort and Convenience Features

- Remote entry security system
- Coded Drivetrain Protection
- Power windows with one touch up and down
- Deeply sculptured, padded interior
- Sport steering wheel with chrome spokes
- Auto dimming interior mirrors
- Radio with navigation system and multi-antenna system
- Harmonized Radio sound system with 12 speakers
- 5 dual CD Changers
- 7-way electronically adjustable sport seats
- Air conditioning with two zones
- Digital satellite navigation
- Hand free cell phone system

BMW Delivery Quality Assurance

Every BMW vehicle has been designed, engineered and manufactured under strict quality control guidelines. It has been prepared and inspected to ensure that it is free of defects in workmanship and materials in accordance with the New Vehicle Limited Warranty issued by BMW of North America, LLC.

PARTS CONTENT INFORMATION

For Vehicles in this Car Line:

U.S./Canadian Parts Content: 5%

Major Source of Foreign Parts Content: GERMANY: 80%


Note: Parts content does not include final assembly, distribution, or other non-parts work.

For This Vehicle:

Final Assembly Point: MUNICH, GERMANY

Country of Origin:

Engine: GERMANY
Transmission: GERMANY



Note: The Smog Index (SI) indicates the relative level of smog-forming pollutants emitted by this vehicle. The lower the SI, the lower the vehicle's emissions.

Compare this vehicle to others in the FREE FUEL ECONOMY GUIDE available at the BMW center.

CITY MPG

13

Actual Mileage per gallon varies with many factors. Driving habits and vehicle condition factors reflected in EPA ratings for this vehicle. All shown in miles per gallon.

11 city 15 hwy in the city and hwy
17 city 25 hwy in the hwy



HIGHWAY MPG

21

For Comparison Shopping, all vehicles classified as Two Seater have been based mileage average ranging from 9 city and 11 hwy mpg and 13 city and 25 hwy mpg.

2002 Z8
2DR

6-Cylinder, 5.0 Liter, DOHC, 24-Valve, Transmission, Power, Fuel System, Fuel Injection, Three-Valve Carburetor

Estimated Annual Fuel Cost
\$ 1,547.00

** Gas Guzzler Tax \$ 2,100.00

See the EPA/DOE web site at www.fueleconomy.gov

VIN: WBAEJ13412AH61818

Port of Entry: HUENEME, CALIFORNIA
PC Location: OXNARD, CALIFORNIA

Sold To:
Long Beach BMW
2906 Cherry Avenue
Long Beach, CA
(562) 427-5494 90809
Buyer: WAGGONERS TRUCKING

Sold To:
Long Beach BMW
2906 Cherry Avenue
Long Beach, CA
(562) 427-5494 90809

This vehicle is equipped with bumpers that can withstand an impact of 2.5 miles per hour with no damage to the vehicle's body and safety systems, although the bumper and related components may sustain damage. The bumper system on this vehicle conforms to the current federal bumper standard of 2.5 miles per hour.

BMW of North America
Woodcliff Lake, NJ 07077

The Ultimate Driving Machine®

2002 Z8

Manufacturer's Suggested Retail Price \$ 130,000.00

Options and Additional Charges:

(Optional equipment may supersede standard equipment; check with your authorized Center)

Jet Black	Included
Soft Leather Crema/black	Included
Cpt8000 Timeport Phone Kit	Included
Destination Charge	\$ 645.00
Gas Guzzler	\$ 2,100.00
Total Suggested Retail Price	\$ 132,745.00

The BMW Advantage

- 3 year/36,000 mile Full Maintenance Program
- 4 year/50,000 mile limited warranty
- Six year limited rust perforation warranty
- BMW Roadside Assistance Program - 4 years/50,000 miles

Standard Features

Engineering and Safety Features


- 5 liter DOHC, dual VANOS 32-valve V-8 engine
- Six-speed manual transmission
- Electronic throttle valve control of 8 individual throttles
- M Driving Dynamics Control
- Dynamic Stability Control (DSC), Dynamic Brake Control (DBC), and All Season Traction (ASC) with limited slip differential
- Aluminum space frame
- Dual threshold "Smart" airbags for driver and passenger
- Dual door-mounted side-impact airbags
- Automatic seatbelt pre-tensioners, front seats
- Coded Driveway Protection
- Four-wheel ventilated anti-lock disc brakes
- Z8 double spoke forged 18" light alloy wheels with 245/45ZR front, 275/40ZR rear performance run-flat tires
- Tire Pressure Monitoring
- Xenon headlights
- Automatic soft top
- Rollover protection
- Neon brake lights, front and rear indicator lights

Comfort and Convenience Features

- Remote entry security system
- Coded Driveway Protection
- Power windows with one-touch up and down operation
- Electrically adjustable steering column
- Sport steering wheel with chrome spokes
- Auto dimming interior mirror
- Radio with navigation system and multi-information display
- Harman Kardon sound system with 10 speakers
- 6 disc CD changer
- 6 way electrically adjustable sport seats
- Air conditioning with microfilter
- Digital cellular telephone
- Hard top to match body color

BMW Delivery Quality Assurance
The BMW vehicle has been designed, engineered and manufactured under strict quality control guidelines. It has been prepared and inspected to ensure that it is free of defects in workmanship and materials in accordance with the New Vehicle Limited Warranty issued by BMW North America, LLC.

Smog Index of this



Note: The Smog Index is a measure of the amount of pollutants emitted by this vehicle.

Compare this vehicle to other

CITY MPG

13

Actual Mileage will vary with options, driving conditions, driving habits and vehicle condition. Results reported by EPA indicate that the mileage you will achieve between 11 and 15 mpg in the city and between 17 and 25 mpg on the highway.

Titanium silver

Black

Topaz blue

Red

Stratus gray

Individual color

Two-tone

Interior

Number

Black

667

Crema

229

Sport red / Black

342

Crema / Black

331

Individual color

3

Total

1572

2002

Battery Log Form Stock # _____

VPC USE:	VIN: <u>AH61818</u>
	Voltage: <u>12.62</u>
	Date: <u>7/15/02</u>
	Inspector: <u>JR</u>

This form should be filled out when the vehicle is received and updated according to the proper procedure (display vs. storage vehicle). It should be placed in the vehicle history file when sold.

Note: Failure to maintain batteries as recommended and documented with this form will be considered sufficient cause to reject warranty claims.

(A) Vehicle Receipt		Model	VIN
Center #	Voltage as received	Inspected by	Date received

(B) Vehicle In Storage - Charged Every 4 Weeks											
Color indicates battery is to be charged during the week of . . .											
Week Of	Voltage Before Charge	Charged By	Week Of	Voltage Before Charge	Charged By	Week Of	Voltage Before Charge	Charged By	Week Of	Voltage Before Charge	Charged By
Jan. 7			Jan. 14			Jan. 21			Jan. 28		
Feb. 4			Feb. 11			Feb. 18			Feb. 25		
Mar. 4			Mar. 11			Mar. 18			Mar. 25		
April 1			April 8			April 15			April 22		
April 29			May 6			May 13			May 20		
May 27			June 3			June 10			June 17		
June 24			July 1			July 8			July 15		
July 22			July 29			Aug. 5			Aug. 12		
Aug. 19			Aug. 26			Sept. 2			Sept. 9		
Sept. 16			Sept. 23			Sept. 30			Oct. 7		
Oct. 14			Oct. 21			Oct. 28			Nov. 4		
Nov. 11			Nov. 18			Nov. 25			Dec. 2		
Dec. 9			Dec. 16			Dec. 23			Dec. 30		

(C) Display Vehicle - Monitored Daily											
Date											
Voltage before charge											
Charged by											

Date											
Voltage before charge											
Charged by											



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

BAR REG # AB005652
 EPA # CAD981676679

SERVICE DEPARTMENT HOURS
 7:30 a.m. to 6:30 p.m.
 Monday - Thursday
 7:30 a.m. - 5:30 p.m.-Fri & Sat

7/14/15	6243196/2
R/O Close Date	Status
7/15/15	Pre-Invoice
Mileage In	Mileage Out
8014	8016
Service Advisor / Tag #	
DENNIS BOHLIG/U93	

WBAEJ13412AH61818

Delivery Date	In-Service Date
	7/26/02
Color	License Number
JET BLACK	5LSU439

BMW SERVICE

Year	Make	Model	Body
2002	BMW	Z8	CV

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
ESTIMATE REAR VIEW MIRROR Unrealized 51 16 8 257 711 :B1-Rearview mirror EC 1@655.23 PART HAS BEEN ORDERED FROM GERMANY Sub Total: 655.23	Ordered
#5 - Customer Reports: R/F SEAT BELT IS TWISTED Work performed by JACK TARAKCHYAN (336) TECH 336 2.0 , REMOVE SEAT AND COVERS UNTWIST SEAT BELT AND REINSTALL, CHECK OPERATION OF SEAT BELT Sub Total: 342.12	342.12
#6 - Customer Reports: C/D CART WONT EJECT NO REBUILT AVAILABLE NEED TO REPLACE CHANGER , CUST OMER DECLINED REPAIRS AT THIS TIME . Sub Total: .00	
#7 * 11: BRAKE FLUID FLUSH ADDED OPERATION Work performed by JACK TARAKCHYAN (336) Installed 81 22 0 142 156 :B0B1MI-Brake fluid 2@5.60 Brake flush TECH 336 1.0 PERFORM BRAKE FLUID FLUSH Sub Total: 159.20	148.00 11.20 -30.00
#8 * 21: COOLANT FLUSH ADDED OPERATION Work performed by JACK TARAKCHYAN (336)	148.00



TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

I acknowledge notice and oral approval of an increase in the original estimated price.

Customer Signature or Initials

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NOTICE TO CONSUMER. PLEASE READ IMPORTANT INFORMATION ON THE BACK.



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

BAR REG # AB005652
 EPA # CAD981676679

SERVICE DEPARTMENT HOURS
 7:30 a.m. to 6:30 p.m.
 Monday - Thursday
 7:30 a.m. - 5:30 p.m.-Fri & Sat

7/14/15	6243196/3
R/O Close Date	Status
7/15/15	Pre-Invoice
Mileage In	Mileage Out
8014	8016
Service Advisor / Tag #	
DENNIS BOHLIG/U93	

BMW SERVICE

WBAEJ13412AH61818

Delivery Date	In-Service Date
	7/26/02
Color	License Number
JET BLACK	5LSU439

Year	Make	Model	Body
2002	BMW	Z8	CV

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Installed 82 14 1 467 704 :B0B1SA-COOLANT	1@30.23 30.23
Coolant Flush	-30.00
TECH 336 1.0 PERFORM COOLANT FLUSH	
Sub Total: 178.23	

10% Discount	-89.54


Please Note: PAYS 1825.20	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	977.28
PARTS	255.58
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	22.35
SPECIAL ORDER DEPOSIT	720.03
DISCOUNTS	-149.54
TOTAL DUE	1825.70

I acknowledge notice and oral approval of an increase in the original estimated price.

 Customer Signature or Initials

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.



NOTICE TO CONSUMER. PLEASE READ IMPORTANT INFORMATION ON THE BACK.

Center BMW
5201 Van Nuys Blvd.
Sherman Oaks, CA 91401
818-907-9995

Order# C8-C81-6243196-000
MerchantID: 542929804983955
Term ID: 174798
Date/Time: 7/15/2015 10:27:48 AM
Trans Type: Sale
Amount: 1825.70
Entry Method: SWIPED
Cardholder:
Card Type:
Card Number:
OrderID:
TransID:
AuthCode:
RefCode:

Consumer acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth by the cardmember's agreement with the issuer.

x 
Authorized Signature



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

BAR REG # AB005652
 EPA # CAD981676679

SERVICE DEPARTMENT HOURS
 7:30 a.m. to 6:30 p.m.
 Monday - Thursday
 7:30 a.m. - 5:30 p.m.-Fri & Sat

7/14/15 6243196/1

R/O Close Date	Status
7/15/15	Pre-Invoice
Mileage In	Mileage Out
8014	8016
Service Advisor / Tag #	
DENNIS BOHLIG/U93	

BMW SERVICE

WBAEJ13412AH61818	
Delivery Date	In-Service Date
	7/26/02
Color	License Number
JET BLACK	5LSU439

Year	Make	Model	Body
2002	BMW	Z8	CV

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

Cell: 818-652-6522 Email: PGOEL@BUCKLEYLA.ORG

#1 - Customer Reports:

OIL CHANGE

Work performed by JACK TARAKCHYAN (336)

Installed 83 21 2 405 085 :B1BIMIRR-BMW GROUP LL-0 8@8.25 83.98

Installed 11 42 7 510 717 :B1RRSA-Set oil-filter e 1@24.07 66.00

TECH 336 , .5 PERFORM BMW ENGINE LOW MILAGE OIL CH NAGE 24.07

Sub Total: 174.05

#2 - Customer Reports:

CHECK ENGINE LIGHT IS ON

DID LOOSE POWER

Work performed by JACK TARAKCHYAN (336)

Installed 12 13 7 599 219 :B1SA-Ignition coil 1@124.08 255.18

Unrealized 13 53 7 831 681 :B1MISA-Hose clamp 3@1.78 124.08

TECH 336 1.5 , CHECK FAULT MEM FOUND MISFIRE #4 CY L. REMOVE COIL REMOVE SPARK PLUG INPECT SPARK PLUG 3@1.78 Ordered

FOUND FAILED COIL BY SWAPING WITH #3 AND FAULT MI

GRATE. REPLACE #4 COIL AND CLEAR FAULTS

Sub Total: 384.60

#3 - Customer Reports:

SEEMS TO HESITATE ON ACELERATION

SEE LINE 2

Sub Total: .00

#4 - Customer Reports:

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

I acknowledge notice and oral approval of an increase in the original estimated price.

Customer Signature or Initials

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NOTICE TO CONSUMER. PLEASE READ IMPORTANT INFORMATION ON THE BACK.



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

BAR REG # AB005652
 EPA # CAD981676679

SERVICE DEPARTMENT HOURS
 7:30 a.m. to 6:30 p.m.
 Monday - Thursday
 7:30 a.m. - 5:30 p.m.-Fri & Sat

8/27/15 6246815/1

R/O Close Date	Status
8/27/15	Pre-Invoice
Mileage In	Mileage Out
8054	8054
Service Advisor / Tag #	
DENNIS BOHLIG/WTR67	

BMW SERVICE

WBAEJ13412AH61818

Delivery Date	In-Service Date
	7/26/02
Color	License Number
JET BLACK	5LSU439

Year	Make	Model	Body	Color	License Number
2002	BMW	Z8	CV	JET BLACK	5LSU439

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Cell: 818-652-6522 Email: PGOEL@BUCKLEYLA.ORG	
#1 - Customer Reports: INSTALL SPECIAL ORDER REAR VIEW MIRROR Installed 51 16 8 257 711 :B1-Rearview mirror EC / 1@655.23 REPLACED REAR VIEW MIRROR AS PER REQUEST. Sub Total: 655.23	655.23

#2 - WASH: CENTER BMW COURTESY WASH AND VACUUM Sub Total: .00	

#3 - CT: CHECK TIRE PRESSURE, INFLATE IF NECESSARY PLEASE INFORM CENTER BMW IF TIRES NITROGEN FILLED SET TIRE PRESSURE FRONT AND REAR 34 PSI Sub Total: .00	

#4 - WIKI: I AM A WIKI CUSTOMER Sub Total: .00	

Please Note: NO CHARGE	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	655.23
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	58.97
SPECIAL ORDER DEPOSIT	-714.21
DISCOUNTS	.00
TOTAL DUE	-.01

I acknowledge notice and oral approval of an increase in the original estimated price.

Customer Signature or Initials

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.



NOTICE TO CONSUMER. PLEASE READ IMPORTANT INFORMATION ON THE BACK.



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

SERVICE DEPARTMENT HOURS
 7:00 a.m. to 7:00 p.m.
 Monday - Friday
 8:00 a.m. - 4:00 p.m.-Saturday
 By Appointment Only

R/O Open Date	R/O Number
7/15/06	6025322/1
R/O Close Date	Status
7/18/06	Pre-Invoice
Mileage In	Mileage Out
3389	3390
Service Advisor / Tag #	
MARK RUSCONI/1794	
Vehicle Identification Number	
WBAEJ13412AH61818	
Delivery Date	In-Service Date

Year	Make	Model	Body	Color	License Number
2002	BMW	Z8		BLACK/TAN	5LSU439

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>#1 - Customer Reports: ROAD TESTED WITH CUSTOMER & FORMAN#215;SERVICE ENG INE SOON LIGHT ON - LACK OF POWER & CAR STARTED CH UGGING - CK FOR FAULTS & REPORT</p> <p>Installed 12 13 1 748 018 :IGN. COIL Qty: 2</p> <p>TECH 336 TEST DRIVE CAR AND VERIFY CUTOMER CONSERN CHECK FAULT MEM FOUND CYL MISSFIRE ON CYL 1 AND 6 PERFROM TEST PLAN AND REPLACE # 1 COIL AND # 6 COIL RESTEST DRIVE OK.</p> <p>CHECK SERVICE HIS FOUND ON LAST VISIT #7 AND #5 MISSFIRE FOUND THE COIL BOOTS BAD</p>	Warranty

Please Note: W	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

(C) 2003 ARKONA, Inc. - Dealership Application Group (800)945-1028



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

SERVICE DEPARTMENT HOURS
 7:00 a.m. to 7:00 p.m.
 Monday - Friday
 8:00 a.m. - 4:00 p.m.-Saturday
 By Appointment Only

R/O Open Date	R/O Number				
5/16/06	6021614/1				
R/O Close Date	Status				
5/18/06	Pre-Invoice				
Mileage In	Mileage Out				
3123	3125				
Service Advisor / Tag #					
MARK RUSCONI/1379					
Vehicle Identification Number					
WBAEJ13412AH61818					
Delivery Date	In-Service Date				
Year	Make	Model	Body	Color	License Number
2002	BMW	Z8		BLACK	5LSU439

Year	Make	Model	Body	Color	License Number
2002	BMW	Z8		BLACK	5LSU439

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
#1 - Customer Reports: CAR WON'T START - HAS TO JUMP-START;CK & REPORT Installed 61 21 6 946 334 :90 AH BATTERY WARNTY Qty: 1 TECH 336 CHECK BATTER WITH MIDTRONICS AND CHARGING SYSTEM FOUND BAD CELL IN BATTERY REPLACE BATTERY AND CHECK FOR DROWS	Warranty
#2 - Customer Reports: LT DOOR WON'T CLOSE - CK & REPORT TECH 336 ADJUST DRIVERS DOOR LATCH	
#3 - Customer Reports: CK ENGINE FOR A LACK OF POWER & REPORT Installed 12 13 1 748 018 :IGN. COIL Qty: 1 Installed 12 13 9 067 831 :PLUG SOCKET Qty: 1 TECH 336 CHECK FAULT MEM AND FOUND FAULT FOR MISFIRE IN CYL 1-3-5-6-7-8 PERFROM TEWST MODULES ON ALL CYLENDERS AND ALL PASSED EXCEPT 7 AND 5 ON FURTHER DIAGNOSIS FOUND # 7 COIL BAD AND # 5 COIL BOOT BAD REPLACE COIL AND BOOT AN D REPERFORM TEST PLAN AND TEST PASSED CLEAR ALL FAULT CODES AND TEST DRIVE	Warranty Warranty
#4 - Customer Reports: NEED EST ON DAMAGED FIREWALL PADDING TO REPLACE. Ordered 51 48 8 264 204 :INSULATION 1@106.70 Ordered 51 48 8 234 458 :INSULATION 1@92.69 Ordered 51 48 8 234 457 :INSULATION 1@92.69 Installed 51 48 1 923 999 :BUTTON 3@1.75 ORDER PARTS,ON BACK ORDER - ESTIMATE FOR LABOR - \$165.00 TO REPLACE WHEN PARTS ARRIVED(PARTS ARE PR	Ordered Ordered Ordered 5.25

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

SERVICE DEPARTMENT HOURS
 7:00 a.m. to 7:00 p.m.
 Monday - Friday
 8:00 a.m. - 4:00 p.m. - Saturday
 By Appointment Only

R/O Open Date	R/O Number				
5/16/06	6021614/2				
R/O Close Date	Status				
5/18/06	Pre-Invoice				
Mileage In	Mileage Out				
3123	3125				
Service Advisor / Tag #					
MARK RUSCONI/1379					
Vehicle Identification Number					
WBAEJ13412AH61818					
Delivery Date	In-Service Date				
Year	Make	Model	Body	Color	License Number
2002	BMW	Z8		BLACK	5LSU439

Year	Make	Model	Body	Color	License Number
2002	BMW	Z8		BLACK	5LSU439

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
EPAY) Sub Total: Labor: .00 Parts: 297.33 Total: 297.33	
#5 - Customer Reports: HARD TOP LATCH COVERS ARE BROKEN, AND CENTURY WEST BMW ORDERED IT ALREADY. PLEASE CHECK AND SEE IF WE CAN REPLACE IT HERE AT CENTER BMW. Installed 54 21 7 064 089 :COVER Qty: 2 ORDER COVERS AND INSTALL OLD PARTS ARE WITH CENTURY WEST BMW	Warranty
#6 * Customer Reports: DRIVERS SIDE DOOR SEAL AT COV.TOP WORN Installed 51 71 8 232 339 :COVER Qty: 1 TECH 336 DOOR HAD RUBBED ON THE C PILLER SEAL AND WORN IT OUT REPLACE C PILLER SEAL AND ADJUST DOOR	Warranty
Please Note: \$297.00+TX	

PAID
 MAY 19 2006
 CENTER BMW
Amey

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	5.25
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.43
SPECIAL ORDER DEPOSIT	316.17
DISCOUNTS	.00
TOTAL DUE	321.85

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X



5201 Van Nuys Boulevard
 Sherman Oaks, CA 91401
 Phone: (818) 907-9995

BAR REG # AB005652
 EPA # CAD981676679

SERVICE DEPARTMENT HOURS
 7:30 a.m. to 6:30 p.m.
 Monday - Thursday
 7:30 a.m. - 5:30 p.m.-Fri & Sat

8/30/16	6278457/1
R/O Close Date	Status
8/30/16	Pre-Invoice
Mileage In	Mileage Out
8326	8326
Service Advisor / Tag #	
DENNIS BOHLIG/WTR71	

WBAEJ13412AH61818

Delivery Date	In-Service Date
	7/26/02
License Number	
5LSU439	

Year	Make	Model	Body	Color	License Number
2002	BMW	Z8	CV	JET BLACK	5LSU439

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Cell: 818-652-6522 Email: PGOEL@BUCKLEYLA.ORG	
#1 - CT: CHECK TIRE PRESSURE, INFLATE IF NECESSARY PLEASE INFORM CENTER BMW IF TIRES NITROGEN FILLED Work performed by Adam Huynh (010) Installed 61 21 2 353 810 :B1-EP Battery 90AH 1@195.00 FRT 33PSI REAR 41PSI Sub Total: 362.00	167.00 195.00
#2 - TEXT: MY SIGNATURE/INITIAL IS CONSENT TO RECEIVING AUTOMATED FOLLOWUP AND MARKETING COMMUNICATIONS AS LISTED ON THE REVERSE	
Sub Total: .00	
#3 - Customer Reports: REPLACE BATTERY PER REQUEST Caused by BATTERY REPLACEMENT REQUESTED REPLACE BATTERY COMPLETED Sub Total: .00	
#4 - WIKI: I AM A WIKI CUSTOMER Sub Total: .00	
10% Discount	-36.20
Please Note: PAYS 341.60	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

I acknowledge notice and oral approval of an increase in the original estimated price.

Customer Signature or Initials

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

LABOR	167.00
PARTS	195.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	15.80
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	-36.20
TOTAL DUE	341.60

NOTICE TO CONSUMER. PLEASE READ IMPORTANT INFORMATION ON THE BACK.

CENTER BMW

5201 Van Nuys Boulevard

Sherman Oaks, CA 91401

Phone# (818) 907-9995

August 30, 2016 03:38:44

MERCH LOC CODE: C81

CLERK:

ENTRY:

CREDIT PURCHASE: 341.60

APPROVAL CODE: 575498

HOST: 0/

TRAN ID: 1545800858

I AGREE TO PAY THE ABOVE
TOTAL AMOUNT ACCORDING
TO CARD ISSUER AGREEMENT

X _____

SIGNATURE

THANK YOU
CARDHOLDER COPY



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226		ADVISOR	NICHOLAS JANCIC 5236		TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501	
			LICENSE NO.		MILEAGE	1,182	COLOR	BLACK/CREMA	STOCK NO.			
	YEAR / MAKE / MODEL							DELIVERY DATE	07/26/02	DELIVERY MILES		
	02/BMW/28/2 DOOR ROADSTER											
	VEHICLE I.D. NO.							SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
	W B A E J 1 3 4 1 2 A H 6 1 8 1 8											
	F. T. E. NO.					P. O. NO.		REPAIR DATE	02/21/05			
	COMMENTS										MO: 1186	

JOB# 1 CHARGES

LABOR-----
 J# 1 00BMZ MAINTENANCE TECH(S):5198 WARRANTY
 PERFORM 1200 MILE SERVICE
 PERFORMED 1200 MILE SERVICE AS PER CHECK LIST.

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 2 XJ BMW XJ DIFF OIL WARRANTY
 2 07-11-9-963-355 SEAL RING WARRANTY
 TOTAL - PARTS 0.00

JOB# 1 TOTALS-----
 JOB# 1 JOURNAL PREFIX BMCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES

LABOR-----
 J# 2 51BMX99-4 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES FRONT WINDSHIELD LOWER EDGE BY ANTENNA IS
 DISCOLORED OR FOGGED
 FRONT WINDSHIELD TINTED(AFTERMARKET).

JOB# 2 TOTALS-----

JOB# 2 JOURNAL PREFIX BMCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR-----
 J# 3 63BMZ *LIGHTS TECH(S):5198 WARRANTY
 CLIENT STATES RIGHT HEADLAMP HOLDS MOISTURE, LENS FOGGED UP
 SPECIAL ORDER PART

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 0 63-12-8-385-934 HEADLAMP WARRANTY
 PART ON SPECIAL ORDER
 ** QUANTITY 1 IS SPECIAL ORDERED **
 TOTAL - PARTS 0.00

JOB# 3 TOTALS-----
 JOB# 3 JOURNAL PREFIX BMCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES

LABOR-----
 J# 4 51BMZ99 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES DRIVERS SUN VISOR CLIP DOES NOT HOLD PROPERLY
 SPECIAL ORDER PART

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 0 51-16-8-236-127 SUN VISOR WARRANTY
 PART ON SPECIAL ORDER
 ** QUANTITY 1 IS SPECIAL ORDERED **
 0 51-16-8-262-006 BRACKET WARRANTY
 PART ON SPECIAL ORDER

Copyright © 1998 The Reynolds and Reynolds Company ERAINTIVE GQ-512385 (08/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

MAILING ADDRESS
P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN

MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

EPA # CAL000262279
BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501	
		LICENSE NO.			MILEAGE	1,182	COLOR	BLACK/CREMA	STOCK NO.		
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.			P. O. NO.		R. O. DATE	02/21/05			
		COMMENTS									

MO: 1186

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
** QUANTITY 1 IS SPECIAL ORDERED **					
				TOTAL - PARTS	0.00
JOB# 4 TOTALS					
JOB# 5 CHARGES	JOB# 4 JOURNAL PREFIX BMCS			JOB# 4 TOTAL	0.00
LABOR					
J# 5 11BMZ		*ENG REPAIR DIAG	TECH(S):5198	WARRANTY	
CLIENT STATES CHECK ENGINE, MAKING TICKING NOISE CAR NEEDS TO BE DRIVEN.					
JOB# 5 TOTALS					
JOB# 6 CHARGES	JOB# 5 JOURNAL PREFIX BMCS			JOB# 5 TOTAL	0.00
LABOR					
J# 6 18BMZ		*EXHAUST SYS DIAG	TECH(S):5198	WARRANTY	
CLIENT STATES THERE IS OIL LEAKING FROM REAR EXHAUST TIPS AND DRIPPING ON GROUND NO OIL LEAK. ONLY SAW CONDENSATION(WATER) NOT OIL AND OIL LEVEL IS NOT LOW.					
JOB# 6 TOTALS					
JOB# 7 CHARGES	JOB# 6 JOURNAL PREFIX BMCS			JOB# 6 TOTAL	0.00
LABOR					
J# 7 52BMZ		SEATS	TECH(S):5198	WARRANTY	
CLIENT STATES BOTH FRONT SEAT BELTS ARE TWISTED UNTWISTED SEAT BELTS.					
JOB# 7 TOTALS					
JOB# 8 CHARGES	JOB# 7 JOURNAL PREFIX BMCS			JOB# 7 TOTAL	0.00
LABOR					
J# 8 51BMZ99-1		BODY MISC.	TECH(S):5198	WARRANTY	
CLIENT STATES CARPET IN LEFT REAR SHELF AREA COMING LOOSE FROM TRIM, SEE NICK DONE, NO CHARGE.					
JOB# 8 TOTALS					
JOB# 9 CHARGES	JOB# 8 JOURNAL PREFIX BMCS			JOB# 8 TOTAL	0.00
LABOR					

Copyright © 1998 The Reynolds and Reynolds Company EPAINTIME 30-512385 (08/03)



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501
		LICENSE NO.			MILEAGE	1,182	COLOUR	BLACK/CREMA	STOCK NO.	
		YEAR / MAKE / MODEL	02/BMW/28/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES	
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02
		F. T. E. NO.			P. O. NO.		REPAIR DATE	02/21/05		
		COMMENTS								MO: 1186

LABOR
 J# 9 51BMZ99-2 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES FRONT CUP HOLDER RIM IS WARPED
 NOT WARRANTY, CUP HOLDER CRUSHED.
 CUP HOLDER ON ORDER

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 0 51-16-7-025-454 INST. KIT WARRANTY
 PART ON SPECIAL ORDER
 ** QUANTITY 1 IS SPECIAL ORDERED **
 TOTAL - PARTS 0.00

JOB# 9 TOTALS-----
 JOB# 9 JOURNAL PREFIX BMCS JOB# 9 TOTAL 0.00

JOB# 10 CHARGES-----

LABOR
 J#10 66BMZ REMOTE CONTROL SYST. TECH(S):5198 INTERNAL
 CLIENT REQUESTS COST ON EXTRA MASTER REMOTE KEY
 PART ON ORDER

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 1 66-12-6-933-717 KEY CUT 198.45 198.45
 VIN. AH61818
 TOTAL - PARTS 198.45

JOB# 10 TOTALS-----
 PARTS 198.45
 JOB# 10 JOURNAL PREFIX BMCS JOB# 10 TOTAL 198.45

JOB# 11 CHARGES-----

LABOR
 J#11 51BMZ99-3 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES DRIVES DOOR HARD TO CLOSE, RUBBING ON TOP OF
 B PILLAR
 RUBBER SEAL COMING OFF AND RUBBING AGAINST DOOR.
 SPECIAL ORDER PART

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
 0 54-34-8-266-953 SEALING WARRANTY
 PART ON SPECIAL ORDER
 ** QUANTITY 1 IS SPECIAL ORDERED **
 0 51-71-8-232-333 GASKET WARRANTY
 PART ON SPECIAL ORDER
 ** QUANTITY 1 IS SPECIAL ORDERED **
 TOTAL - PARTS 0.00

JOB# 11 TOTALS-----
 JOB# 11 JOURNAL PREFIX BMCS JOB# 11 TOTAL 0.00

JOB# 12 CHARGES-----

LABOR-----

Copyright © 1998 The Reynolds and Reynolds Company ERMINTIME GO-512385 (08/03)



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501	
		LICENSE NO.		MILEAGE	1,182	COLOR	BLACK/CREMA	STOCK NO.			
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	WBAEJ13412AH61818				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F.T.E. NO.		P.O. NO.		R.O. DATE	02/21/05				
		COMMENTS								MO: 1186	

LABOR
 J#12 32BMZ *STEERING DIAGNOSIS TECH(S):5198 WARRANTY
 CLIENT STATES STEERING PULLS RIGHT OR LEFT BUT CANNOT LET GO OF WHEEL, CAR WILL NOT GO STRAIGHT, CHECK AND ADVISE UNKNOWN, HOWEVER FOUND ALL TIRE PRESSURES A LITTLE BELOW 20 PSI. PRESSURIZED TO PROPER SPECS AND DROVE CAR AND DOES NOT WANDER AND GOES STRAIGHT.

JOB# 12 TOTALS-----
 JOB# 12 JOURNAL PREFIX BMCS JOB# 12 TOTAL 0.00

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$0.00 (+TAX)
 APPROVED REVISED ESTIMATE (# 1) OF \$215.00 (+TAX) ON 02/22/05 AT 03:38pm
 BY RAY COMMENTS KEY AND CUP HOLDER
 TOTALS-----

*****	TOTAL LABOR....	0.00
* [] CASH [] CHECK CK NO. [] *	TOTAL PARTS....	198.45
* [] VISA [] MASTERCARD [] DISCOVER *	TOTAL SUBLET...	0.00
* [] AMER XPRESS [] OTHER [] CHARGE *	TOTAL G.O.G....	0.00
*****	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	16.37
	TOTAL INVOICE \$	214.82

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE



Copyright © 1998 The Reynolds and Reynolds Company ERAINTIVE 00-512385 08/03



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501
		LICENSE NO.			MILEAGE	1,182	COLOR	BLACK/CREMA	STOCK NO.	
		YEAR / MAKE / MODEL	02/BMW/28/2 DOOR ROADSTER				DRIVER'S DATE	07/26/02	DELIVERY MILES	
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SPRING DEALER NO.	04124	PRODUCTION DATE	03/01/02
		T. E. NO.			P. O. NO.		RECORD DATE	02/21/05		
		COMMENTS								

MO: 1186

JOB# 1 CHARGES

LABOR-----
 J# 1 00BMZ MAINTENANCE TECH(S):5198 WARRANTY
 PERFORM 1200 MILE SERVICE
 PERFORMED 1200 MILE SERVICE AS PER CHECK LIST.

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	2	XJ	BMW XJ DIFF OIL		WARRANTY
	2	07-11-9-963-355	SEAL RING		WARRANTY
			TOTAL - PARTS	0.00	

JOB# 1 TOTALS-----
 JOB# 1 JOURNAL PREFIX BMCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES

LABOR-----
 J# 2 51BMX99-4 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES FRONT WINDSHIELD LOWER EDGE BY ANTENNA IS
 DISCOLORED OR FOGGED
 FRONT WINDSHIELD TINTED(AFTERMARKET).

JOB# 2 TOTALS-----
 JOB# 2 JOURNAL PREFIX BMCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR-----
 J# 3 63BMZ *LIGHTS TECH(S):5198 WARRANTY
 CLIENT STATES RIGHT HEADLAMP HOLDS MOISTURE, LENS FOGGED UP
 SPECIAL ORDER PART

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	0	63-12-8-385-934	HEADLAMP		WARRANTY
			PART ON SPECIAL ORDER		
			** QUANTITY 1 IS SPECIAL ORDERED **		
			TOTAL - PARTS	0.00	

JOB# 3 TOTALS-----
 JOB# 3 JOURNAL PREFIX BMCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES

LABOR-----
 J# 4 51BMZ99 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES DRIVERS SUN VISOR CLIP DOES NOT HOLD PROPERLY
 SPECIAL ORDER PART

PARTS-----	QTY----	FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-	
	0	51-16-8-236-127	SUN VISOR		WARRANTY
			PART ON SPECIAL ORDER		
			** QUANTITY 1 IS SPECIAL ORDERED **		
	0	51-16-8-262-006	BRACKET		WARRANTY
			PART ON SPECIAL ORDER		

Copyright © 1988 The Reynolds and Reynolds Company - ERMINTIME GO-512385 (08/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501	
		LICENSE NO.			MILEAGE	1,182	COLOR	BLACK/CREMA	STOCK NO.		
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.			P. O. NO.		R. O. DATE	02/21/05			
		COMMENTS									

MO: 1186

PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE	
** QUANTITY 1 IS SPECIAL ORDERED **					
				TOTAL - PARTS	0.00
JOB# 4 TOTALS					
JOB# 5 CHARGES	JOB# 4 JOURNAL PREFIX BMCS JOB# 4 TOTAL				0.00
LABOR					
J# 5 11BMZ		*ENG REPAIR DIAG	TECH(S):5198	WARRANTY	
CLIENT STATES CHECK ENGINE, MAKING TICKING NOISE CAR NEEDS TO BE DRIVEN.					
JOB# 5 TOTALS					
JOB# 6 CHARGES	JOB# 5 JOURNAL PREFIX BMCS JOB# 5 TOTAL				0.00
LABOR					
J# 6 18BMZ		*EXHAUST SYS DIAG	TECH(S):5198	WARRANTY	
CLIENT STATES THERE IS OIL LEAKING FROM REAR EXHAUST TIPS AND DRIPPING ON GROUND NO OIL LEAK. ONLY SAW CONDENSATION(WATER) NOT OIL AND OIL LEVEL IS NOT LOW.					
JOB# 6 TOTALS					
JOB# 7 CHARGES	JOB# 6 JOURNAL PREFIX BMCS JOB# 6 TOTAL				0.00
LABOR					
J# 7 52BMZ		SEATS	TECH(S):5198	WARRANTY	
CLIENT STATES BOTH FRONT SEAT BELTS ARE TWISTED UNTWISTED SEAT BELTS.					
JOB# 7 TOTALS					
JOB# 8 CHARGES	JOB# 7 JOURNAL PREFIX BMCS JOB# 7 TOTAL				0.00
LABOR					
J# 8 51BMZ99-1		BODY MISC.	TECH(S):5198	WARRANTY	
CLIENT STATES CARPET IN LEFT REAR SHELF AREA COMING LOOSE FROM TRIM, SEE NICK DONE, NO CHARGE.					
JOB# 8 TOTALS					
JOB# 9 CHARGES	JOB# 8 JOURNAL PREFIX BMCS JOB# 8 TOTAL				0.00
LABOR					

Copyright © 1988 The Reynolds and Reynolds Company ERAINTIVE GQ-512385 (08/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN

MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3705	INVOICE DATE	02/23/05	INVOICE NO.	BMCS97501	
		LICENSE NO.			MILEAGE	1,182	COLOUR	BLACK/CREMA	STOCK NO.		
		YEAR / MAKE / MODEL	02/BMW/28/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	WBAAEJ13412AH61818				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.			P. O. NO.		REC'D DATE	02/21/05			
F		COMMENTS									MO: 1186

LABOR
 J# 9 51BMZ99-2 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES FRONT CUP HOLDER RIM IS WARPED
 NOT WARRANTY, CUP HOLDER CRUSHED.
 CUP HOLDER ON ORDER

PARTS	----	QTY	----	FP-NUMBER	-----	DESCRIPTION	-----	UNIT PRICE	-----		
		0		51-16-7-025-454		INST. KIT				WARRANTY	
		PART ON SPECIAL ORDER									
		** QUANTITY 1 IS SPECIAL ORDERED **									
		TOTAL - PARTS								0.00	

JOB# 9 TOTALS -----
 JOB# 9 JOURNAL PREFIX BMCS JOB# 9 TOTAL 0.00

JOB# 10 CHARGES -----

LABOR
 J#10 66BMZ REMOTE CONTROL SYST. TECH(S):5198 INTERNAL
 CLIENT REQUESTS COST ON EXTRA MASTER REMOTE KEY
 PART ON ORDER

PARTS	----	QTY	----	FP-NUMBER	-----	DESCRIPTION	-----	UNIT PRICE	-----		
		1		66-12-6-933-717		KEY CUT		198.45		198.45	
		VIN. AH61818									
		TOTAL - PARTS								198.45	

JOB# 10 TOTALS -----
 PARTS 198.45
 JOB# 10 JOURNAL PREFIX BMCS JOB# 10 TOTAL 198.45

JOB# 11 CHARGES -----

LABOR
 J#11 51BMZ99-3 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES DRIVES DOOR HARD TO CLOSE, RUBBING ON TOP OF
 B PILLAR
 RUBBER SEAL COMING OFF AND RUBBING AGAINST DOOR.
 SPECIAL ORDER PART

PARTS	----	QTY	----	FP-NUMBER	-----	DESCRIPTION	-----	UNIT PRICE	-----		
		0		54-34-8-266-953		SEALING				WARRANTY	
		PART ON SPECIAL ORDER									
		** QUANTITY 1 IS SPECIAL ORDERED **									
		0		51-71-8-232-333		GASKET				WARRANTY	
		PART ON SPECIAL ORDER									
		** QUANTITY 1 IS SPECIAL ORDERED **									
		TOTAL - PARTS								0.00	

JOB# 11 TOTALS -----
 JOB# 11 JOURNAL PREFIX BMCS JOB# 11 TOTAL 0.00

JOB# 12 CHARGES -----

LABOR -----

Copyright © 1998 The Reynolds and Reynolds Company EPA/MTWVE GO-512385 (08/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., UNIVERSAL CITY, CA 91608
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

SERVICE AND PARTS OPEN
MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
04/14/03	62648	696	5173	5024 5024	I I	11BMZ 63BMZ	*ENG REPAIR DIAG *LIGHTS

SALESPERSON NO.

S E R V I C E

STATE REG# AH190621

TERMS CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHECK <input type="checkbox"/> FINANCIAL APPROVAL <input type="checkbox"/> OTHER <input type="checkbox"/>	VEHICLE NO. WBAEJ13412AH61818	YEAR/MAKE/MODEL 02/BMW/Z8/2 DOOR ROADSTER	PRODUCTION DATE 05/01/02	STOCK NO.	LICENSE NO.	R.O. NO. 97501
SAVE REMOVED PARTS FOR CUSTOMER <input type="checkbox"/> YES <input type="checkbox"/> NO	CUSTOMER NO. 35226	SERVICE CONTRACT	DELIVERY DATE 07/26/02	DELIVERY MILES	SELLING DEALER NO. 04124	R.O. DATE 02/21/05
	COLOR BLACK/CREMA/BLK L	CONTRACT NO.	EXPIRATION DATE	EXPIRATION MILES	TAX NO. 3705	
	TURBO	M/MC BMZZ	AIR COND. Y	P. S. Y	TRANS M	MILEAGE 1,182
			ADVISOR NO. 5236	ADVISOR NICHOLAS JANCIC		
I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate the vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.						
	TIME RECEIVED 10:23am	DATE/TIME PROMISED 02/24/05 07:00pm	PRIORITY 1	LABOR RATE \$		
APPOINTMENT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CUSTOMER ACKNOWLEDGES RECEIPT HEREOF					

JOB	LABOR INSTRUCTIONS	ORIGINAL ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	TOTAL ESTIMATE \$
X	ORIGINAL CUSTOMER ESTIMATE: TOTAL 0.00			
1	W 00BMZ MAINTENANCE PERFORM 1200 MILE SERVICE			
2	W 51BMX99-4 BODY MISC. CLIENT STATES FRONT WINDSHIELD LOWER EDGE BY ANTENNA IS DISCOLORED OR FOGGED			
3	W * 63BMZ *LIGHTS CLIENT STATES RIGHT HEADLAMP HOLDS MOISTURE, LENS FOGGED UP			
4	W 51BMZ99 BODY MISC. CLIENT STATES DRIVERS SUN VISOR CLIP DOES NOT HOLD PROPERLY			
5	W * 11BMZ *ENG REPAIR DIAG CLIENT STATES CHECK ENGINE, MAKING TICKING NOISE			
6	W 18BMZ *EXHAUST SYS DIAG CLIENT STATES THERE IS OIL LEAKING FROM REAR EXHAUST TIPS AND DRIPPING ON GROUND			
7	W 52BMZ SEATS CLIENT STATES BOTH FRONT SEAT BELTS ARE TWISTED			
8	W 51BMZ99-1 BODY MISC. CLIENT STATES CARPET IN LEFT REAR SHELF AREA COMING LOOSE FROM TRIM, SEE NICK			

IMPORTANT: REMOVE ALL PERSONAL PROPERTY AND VALUABLES FROM YOUR VEHICLE. WE DO NOT ASSUME RESPONSIBILITY FOR LOSS OR DAMAGE FOR ARTICLES LEFT IN YOUR VEHICLE.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.

"By law, you may choose another licensed Smog Check facility to perform any needed repairs or adjustments that the Smog Check test indicates are necessary."

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

WE GUARANTEE OUR LABOR 12 MONTHS OR 12,000 MILES - WHICHEVER OCCURS FIRST.

NOTICE TO CUSTOMER

WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES.

RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.

THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.

B.A.R. # AH190621 EPA # CAL000262279
[CONTINUE] [NEXT PAGE] 97501

Copyright © 1995 The Reynolds and Reynolds Company ERALZRWOE GC0514808 Q (07/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., UNIVERSAL CITY, CA 91608
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

SERVICE AND PARTS OPEN
MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
04/14/03	62648	696	5173	5024 5024	I I	11BMZ 63BMZ	*ENG REPAIR DIAG *LIGHTS

SALESPERSON NO.

S E R V I C E

STATE REG# AH190621

TERMS CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHECK <input type="checkbox"/> OTHER <input type="checkbox"/>	VEHICLE I.D. NO. WBAEJ13412AH61818	YEAR/MAKE/MODEL 02/BMW/Z8/2 DOOR ROADSTER	PRODUCTION DATE 05/01/02	STOCK NO.	LICENSE NO.	R.O. NO. 97501
SAVE REMOVED PARTS FOR CUSTOMER <input type="checkbox"/> YES <input type="checkbox"/> NO	CUSTOMER NO. 35226	SERVICE CONTRACT	DELIVERY DATE 07/26/02	DELIVERY MILES	SELLING DEALER NO. 04124	R.O. DATE 02/21/05
	COLOR BLACK/CREMA/BLK L	CONTRACT NO.	EXPIRATION DATE	EXPIRATION MILES	TAG NO. 3705	
	TURBO M/MC BMZZ	AIR COND. Y	P. S. Y	TRANS M	MILEAGE 1,182	ADVISOR NO. 5236 ADVISOR NICHOLAS JANCIC

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate the vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

TIME RECEIVED: 10:23am DATE/TIME PROMISED: 02/24/05 07:00pm PRIORITY: 1

APPOINTMENT: Yes No LABOR RATE: \$

CUSTOMER ACKNOWLEDGES RECEIPT HEREOF

JOB	LABOR INSTRUCTIONS
9	W 51BMZ99-2 BODY MISC. CLIENT STATES FRONT CUP HOLDER RIM IS WARPED
10	C 66BMZ REMOTE CONTROL SYST. CLIENT REQUESTS COST ON EXTRA MASTER REMOTE KEY
11	W 51BMZ99-3 BODY MISC. CLIENT STATES DRIVES DOOR HARD TO CLOSE, RUBBING ON TOP OF B PILLAR
12	W 32BMZ *STEERING DIAGNOSIS CLIENT STATES STEERING PULLS RIGHT OR LEFT BUT CANNOT LET GO OF WHEEL, CAR WILL NOT GO STRAIGHT, CHECK AND ADVISE

ORIGINAL ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	TOTAL ESTIMATE \$
REVISED ESTIMATE \$		ADDITIONAL COST \$
REASON		CONTACTED BY
AUTHORIZED BY	<input type="checkbox"/> PERSON <input type="checkbox"/> PHONE #	DATE TIME
2ND REVISED ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	ADDITIONAL COST \$
REASON		CONTACTED BY
AUTHORIZED BY	<input type="checkbox"/> PERSON <input type="checkbox"/> PHONE #	DATE TIME

IMPORTANT: REMOVE ALL PERSONAL PROPERTY AND VALUABLES FROM YOUR VEHICLE. WE DO NOT ASSUME RESPONSIBILITY FOR LOSS OR DAMAGE FOR ARTICLES LEFT IN YOUR VEHICLE.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.

"By law, you may choose another licensed Smog Check facility to perform any needed repairs or adjustments that the Smog Check test indicates are necessary."

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

WE GUARANTEE OUR LABOR 12 MONTHS OR 12,000 MILES - WHICHEVER OCCURS FIRST.

NOTICE TO CUSTOMER

WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES.

RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.

THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.



Copyright © 1985 The Reynolds and Reynolds Company EPA/LZRW02E GC0514608 Q (07/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., UNIVERSAL CITY, CA 91608
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

SERVICE AND PARTS OPEN
MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

NICK (818) 432-5899 XT 855

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
02/21/05	97501	1182	5236	5198	W	00BMZ	MAINTENANCE
				5198	W	51BMX99-4	BODY MISC.
				5198	W	63BMZ	*LIGHTS
				5198	W	51BMZ99	BODY MISC.
				5198	W	11BMZ	*ENG REPAIR DIAG
				5198	W	18BMZ	*EXHAUST SYS DIAG

SALESPERSON NO.

S E R V I C E

STATE REG# AH190621

TERMS CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHECK <input type="checkbox"/> (PRIOR APPROVAL) OTHER <input type="checkbox"/>	VEHICLE I.D. NO. WBAEJ13412AH61818	YEAR/MAKE/MODEL 02/BMW/Z8/2 DOOR ROADSTER	PRODUCTION DATE 05/01/02	STOCK NO.	LICENSE NO. 5LSU439	R. O. NO. 100595
SAVE REMOVED PARTS FOR CUSTOMER <input type="checkbox"/> YES <input type="checkbox"/> NO	CUSTOMER NO. 35226	SERVICE CONTRACT	DELIVERY DATE 07/26/02	DELIVERY MILES	SELLING DEALER NO. 04124	R. O. DATE 04/19/05
	COLOR BLACK/CREMA/BLK L	CONTRACT NO.	EXPIRATION DATE	EXPIRATION MILES	TAG NO. 3098	
	TURBO BMZZ	M/MC Y	AIR COND. Y	P. S. Y	TRANS M	MILEAGE 1,654
		ADVISOR NO. 5236	ADVISOR NICHOLAS JANCIC	I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate the vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.		
	TIME RECEIVED 09:46am	DATE/TIME PROMISED 04/22/05	PRIORITY 07:00pm	LABOR RATE \$	X _____	
APPOINTMENT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CUSTOMER ACKNOWLEDGES RECEIPT HEREOF					

JOB	LABOR INSTRUCTIONS	ORIGINAL ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	TOTAL ESTIMATE \$
X	ORIGINAL CUSTOMER ESTIMATE: TOTAL 115.00			
1	W * 63BMZ *LIGHTS CLIENT STATES RIGHT HEADLAMP HOLDS MOISTURE. INSTALL S/O PART			
2	C 54BMZ CONV.TOP/SUNROOF CLIENT REQUESTS CAPS FOR HARDTOP INSTALLED. CHECK FOR S/O PART			
3	W * 51BMX99-4 BODY MISC. CLIENT STATES DRIVERS SUNVISOR CLIP DOES NOT HOLD PROPERLY INSTALL S/O PART			
4	C * 66BMZ REMOTE CONTROL SYST. CLIENT REQUESTS SPARE MASTER KEY..CHECK FOR PRE PAID S/O PART			
5	W * 51BMZ99 BODY MISC. CLIENT STATES DRIVERS DOOR HARD TO CLOSE RUBBING RUBBER SEAL ON TOP OF B PILLAR. INSTALL S/O PART			
6	C * 51BMZ99-1 BODY MISC. CLIENT STATES CUP HOLDER RIM IS WARPED, CHECK FOR S/O PART			
7	W 34BMZ *BRAKE SYSTEM DIAG CLIENT STATES CHECK BRAKES. THEY GRIND COLD BUT QUIET WHEN THEY GET WARM			

IMPORTANT: REMOVE ALL PERSONAL PROPERTY AND VALUABLES FROM YOUR VEHICLE. WE DO NOT ASSUME RESPONSIBILITY FOR LOSS OR DAMAGE FOR ARTICLES LEFT IN YOUR VEHICLE.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.

"By law, you may choose another licensed Smog Check facility to perform any needed repairs or adjustments that the Smog Check test indicates are necessary."

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

WE GUARANTEE OUR LABOR 12 MONTHS OR 12,000 MILES - WHICHEVER OCCURS FIRST.

NOTICE TO CUSTOMER

WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES.

RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.

THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.

Copyright © 1995 The Reynolds and Reynolds Company EFALZRW00E GC0514608 Q (07/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., UNIVERSAL CITY, CA 91608
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

SERVICE AND PARTS OPEN
MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
02/21/05	97501	1182	5236	5198	W	00BMZ	MAINTENANCE
				5198	W	51BMX99-4	BODY MISC.
				5198	W	63BMZ	*LIGHTS
				5198	W	51BMZ99	BODY MISC.
				5198	W	11BMZ	*ENG REPAIR DIAG
				5198	W	18BMZ	*EXHAUST SYS DIAG

SALESPERSON NO.

S E R V I C E

STATE REG# AH190621

TERMS CASH <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHECK <input type="checkbox"/> (PRIOR APPROVAL) OTHER <input type="checkbox"/>	VEHICLE I.D. NO. WBAEJ13412AH61818	YEAR/MAKE/MODEL 02/BMW/Z8/2 DOOR ROADSTER	PRODUCTION DATE 05/01/02	STOCK NO.	LICENSE NO. 5LSU439	R. O. NO. 100595
SAVE REMOVED PARTS FOR CUSTOMER <input type="checkbox"/> YES <input type="checkbox"/> NO	CUSTOMER NO. 35226	SERVICE CONTRACT	DELIVERY DATE 07/26/02	DELIVERY MILES	SELLING DEALER NO. 04124	R. O. DATE 04/19/05
	COLOR BLACK/CREMA/BLK L	CONTRACT NO.	EXPIRATION DATE	EXPIRATION MILES	TAG NO. 3098	
	TURBO M/MC BMZZ	AIR COND. Y	P. S. Y	TRANS M	MILEAGE 1,654	ADVISOR NO. 5236
	RESIDENCE PHONE	BUSINESS PHONE	I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate the vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.			
	TIME RECEIVED 09:46am	DATE/TIME PROMISED 04/22/05 07:00pm	PRIORITY 1	LABOR RATE \$	X _____	
APPOINTMENT <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	CUSTOMER ACKNOWLEDGES RECEIPT HEREOF					

- LABOR INSTRUCTIONS**
- 8 **W * 51BMZ99-3 BODY MISC.**
CLIENT STATES MATERIAL AROUND REAR WINDOW COMING LOOSE
 - 9 **W * 51BMZ99-2 BODY MISC.**
CLIENT STATES DRIVERS FLOOR MAT HOLDINGS COME LOOSE
 - 10 **W * 52BMZ99 SEATS MISC.**
CLIENT STATES PASS SEAT BACK REST WILL NOT ADJUST

ORIGINAL ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	TOTAL ESTIMATE \$
REVISED ESTIMATE \$		ADDITIONAL COST \$
REASON		CONTACTED BY
AUTHORIZED BY	<input type="checkbox"/> PERSON <input type="checkbox"/> PHONE #	DATE TIME
2ND REVISED ESTIMATE \$	HAZ. WASTE HNLG. & DISP.	ADDITIONAL COST \$
REASON		CONTACTED BY
AUTHORIZED BY	<input type="checkbox"/> PERSON <input type="checkbox"/> PHONE #	DATE TIME

IMPORTANT: REMOVE ALL PERSONAL PROPERTY AND VALUABLES FROM YOUR VEHICLE. WE DO NOT ASSUME RESPONSIBILITY FOR LOSS OR DAMAGE FOR ARTICLES LEFT IN YOUR VEHICLE.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.

"By law, you may choose another licensed Smog Check facility to perform any needed repairs or adjustments that the Smog Check test indicates are necessary."

ALL PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

WE GUARANTEE OUR LABOR 12 MONTHS OR 12,000 MILES - WHICHEVER OCCURS FIRST.

NOTICE TO CUSTOMER

WE MAKE A SEPARATE CHARGE FOR THE STORAGE AND DISPOSAL OF TOXIC WASTES.

RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.

THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE ON REQUEST.



Copyright © 1995 The Reynolds and Reynolds Company EPALZRW02E G0514608 Q (07/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

MAILING ADDRESS
P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN

MONDAY THRU FRIDAY

7:30 A.M. to 7:00 P.M.

SATURDAYS

8:00 A.M. to 5:00 P.M.

CLOSED SUNDAY

EPA # CAL000262279

BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3098	INVOICE DATE	04/22/05	INVOICE NO.	BMCS100595	
		LICENSE NO.	5LSU439	MILEAGE	1,654	COLOR	BLACK/CREMA	STOCK NO.			
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.		P. O. NO.		R. O. DATE	04/19/05				
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS									
MO: 1658											

JOB#	CHARGES	LABOR	PARTS	TOTALS	WARRANTY
JOB# 1	CHARGES	J# 1 63BMZ *LIGHTS CLIENT STATES RIGHT HEADLAMP HOLDS MOISTURE. INSTALL S/O PART UNKNOWN BUT FOGS UP AND DOES NOT GO AWAY WITHIN 10 MINUTES. INSIDE OF GLASS HAS WATER STAINS. REMOVED RF WHEEL AND INNER WHEEL LINER AND REPLACED HEADLIGHT HOUSING.	1 63-12-8-385-934 HEADLAMP	JOB# 1 JOURNAL PREFIX BMCS JOB# 1 TOTAL	0.00
JOB# 2	CHARGES	J# 2 54BMZ CONV. TOP/SUNROOF CLIENT REQUESTS CAPS FOR HARDTOP INSTALLED. CHECK FOR S/O PART DONE.		JOB# 2 JOURNAL PREFIX BMCS JOB# 2 TOTAL	0.00
JOB# 3	CHARGES	J# 3 51BMX99-4 BODY MISC. CLIENT STATES DRIVERS SUNVISOR CLIP DOES NOT HOLD PROPERLY. INSTALL S/O PART MISSING SUNVISOR HINGE COVERS. NO SIGNS OF OUTSIDE DAMAGE. REPLACED SUN VISOR AND MISSING COVER.	1 51-16-8-236-127 SUN VISOR 1 51-16-8-262-006 BRACKET	JOB# 3 JOURNAL PREFIX BMCS JOB# 3 TOTAL	0.00
JOB# 4	CHARGES	J# 4 66BMZ REMOTE CONTROL SYST. CLIENT REQUESTS SPARE MASTER KEY..CHECK FOR PRE PAID S/O PART DONE.		JOB# 4 JOURNAL PREFIX BMCS JOB# 4 TOTAL	0.00

Copyright © 1998 The Reynolds and Reynolds Company. ERMNTMNE 02-512385 08/03



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3098	INVOICE DATE	04/22/05	INVOICE NO.	BMCS100595	
		LICENSE NO.	5LSU439		MILEAGE	1,654	COLOR	BLACK/CREMA	STOCK NO.		
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.		P. O. NO.		R. O. DATE	04/19/05				
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS									
MO: 1658											

JOB# 4 TOTALS-----										
					JOB# 4 JOURNAL PREFIX BMCS		JOB# 4 TOTAL		0.00	
JOB# 5 CHARGES-----										
LABOR-----										
J# 5	51BMZ99	BODY MISC.		TECH(S):5198		WARRANTY				
CLIENT STATES DRIVERS DOOR HARD TO CLOSE RUBBING RUBBER SEAL ON TOP OF B PILLAR. INSTALL S/O PART DOOR RUBBED HOLE ON B PILLAR TOP TRIM AND L/S DOOR SEAL. TOP TRIM IS COMING FROM GERMANY(5-7 DAYS). INSTALLED L/S DOOR SEAL.										
PARTS	QTY	FP-NUMBER	DESCRIPTION		UNIT PRICE		WARRANTY			
	1	51-71-8-232-333	GASKET				WARRANTY			
	1	51-71-8-232-339	COVER				WARRANTY			
					TOTAL - PARTS		0.00			
JOB# 5 TOTALS-----										
					JOB# 5 JOURNAL PREFIX BMCS		JOB# 5 TOTAL		0.00	
JOB# 6 CHARGES-----										
LABOR-----										
J# 6	51BMZ99-1	BODY MISC.		TECH(S):5198		0.00				
CLIENT STATES CUP HOLDER RIM IS WARPED, CHECK FOR S/O PART PART ON PASS. SEAT.										
PARTS	QTY	FP-NUMBER	DESCRIPTION		UNIT PRICE		WARRANTY			
	1	51-16-7-025-454	INST. KIT		17.45		17.45			
					TOTAL - PARTS		17.45			
JOB# 6 TOTALS-----										
					PARTS		17.45			
					JOB# 6 JOURNAL PREFIX BMCS		JOB# 6 TOTAL		17.45	
JOB# 7 CHARGES-----										
LABOR-----										
J# 7	34BMZ	*BRAKE SYSTEM DIAG		TECH(S):5198		WARRANTY				
CLIENT STATES CHECK BRAKES. THEY GRIND COLD BUT QUIET WHEN THEY GET WARM DUE TO VERY LOW MILES, ROTORS HAVE A SLIGHT BUILD-UP OF RUST /OXIDATION. CAR NEEDS TO BE DRIVEN. FRONT BRAKES=12.0MM:REARS=10.0MM										
JOB# 7 TOTALS-----										
					JOB# 7 JOURNAL PREFIX BMCS		JOB# 7 TOTAL		0.00	
JOB# 8 CHARGES-----										
LABOR-----										
J# 8	51BMZ99-3	BODY MISC.		TECH(S):5198		WARRANTY				
CLIENT STATES MATERIAL AROUND REAR WINDOW COMING LOOSE										

Copyright © 1999 The Reynolds and Reynolds Company ERANTIME GC-512385 (08/03)



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3098	INVOICE DATE	04/22/05	INVOICE NO.	BMCS100595	
		LICENSE NO.	SLSU439	MILEAGE	1,654	COLOR	BLACK/CREMA	STOCK NO.			
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.		P. O. NO.		PO DATE	04/19/05				
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	TUCKED IN MATERIAL.								MO: 1658

JOB# 8 TOTALS	-----										
JOB# 9 CHARGES	-----										
LABOR	-----										
J# 9 51BMZ99-2	BODY MISC.	TECH(S):5198								WARRANTY	
CLIENT STATES DRIVERS FLOOR MAT HOLDOWNS COME LOOSE RESECURED FLOOR MAT HOLD DOWN.											
JOB# 9 TOTALS	-----										
JOB# 10 CHARGES	-----										
LABOR	-----										
J#10 52BMZ99	SEATS MISC.	TECH(S):5198								WARRANTY	
CLIENT STATES PASS SEAT BACK REST WILL NOT ADJUST INTERNAL OPEN CIRCUIT IN R/S SEAT SWITCH FOR SEAT BACK. CHECKED FUSE AND CHECKED OUT GOOD.REMOVED SEAT BACK PANEL AND CHECKED FOR POWER AND GROUND.FOUND NO POWER GOING INTO CONN.X736 PIN 10 OR 12.GROUND SIDE CHECKED OUT GOOD.REMOVED PANEL FOR SWITCH ASSEMBLY AND POWER AND GROUND CHECKED OUT GOOD AT CONN.X604 PINS 5 AND 6.JUMPED PINS 5(+)AND 6(-) TO PINS 10 AND 12 ALTERNATELY AND SEAT BACK RECLINES.CHECKED PINS 10 AND 12 AT THE SWITCH AND SHOWS OPEN CIRCUIT.INSTALLE D VOR'D SEAT SWITCH AND CHECKED OPERATION,CHECKED OUT GOOD.											
PARTS	QTY	FP NUMBER	DESCRIPTION	UNIT PRICE							WARRANTY
	1	61-31-1-392-492	SEAT SWITCH								0.00
				TOTAL - PARTS							0.00
JOB# 10 TOTALS	-----										
JOB# 10 JOURNAL PREFIX BMCS JOB# 10 TOTAL	0.00										

ESTIMATE
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$115.00 (+TAX)

Copyright © 1998 The Reynolds and Reynolds Company ERMINTIME 00-512285 (08/03)



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO. 35226		ADVISOR NICHOLAS JANCIC	5236	TAG NO. 3098	INVOICE DATE 04/22/05	INVOICE NO. BMCS100595
		LICENSE NO. 5LSU439	MILEAGE 1,654		COLOR BLACK/CREMA	STOCK NO.
YEAR / MAKE / MODEL 02/BMW/Z8/2 DOOR ROADSTER		DELIVERY DATE 07/26/02			DELIVERY MILES	
VEHICLE I.D. NO. W B A E J 1 3 4 1 2 A H 6 1 8 1 8		SELLING DEALER NO. 04124			PRODUCTION DATE 05/01/02	
F. T. E. NO.		P. O. NO.		R. O. DATE 04/19/05		
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS				
						MO: 1658

TOTALS		

* <input checked="" type="checkbox"/> CASH <input type="checkbox"/> CHECK CK NO. []	TOTAL LABOR...	0.00
* <input type="checkbox"/> VISA <input type="checkbox"/> MASTERCARD <input type="checkbox"/> DISCOVER	TOTAL PARTS...	17.45
* <input type="checkbox"/> AMER XPRESS <input type="checkbox"/> OTHER <input type="checkbox"/> CHARGE	TOTAL SUBLET...	0.00
*****	TOTAL G.O.G. ...	0.00
	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	1.44
	TOTAL INVOICE \$	18.89

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE





CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

MAILING ADDRESS
P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

EPA # CAL000262279
BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3098	INVOICE DATE	04/22/05	INVOICE NO.	BMCS100595
		LICENSE NO.	5LSU439		MILEAGE	1,654	COLOR	BLACK/CREMA	STOCK NO.	
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES	
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02
		F. T. E. NO.		P. O. NO.		R. O. DATE	04/19/05			
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 1658							

JOB# 4 TOTALS-----

JOB# 4 JOURNAL PREFIX BMCS JOB# 4 TOTAL 0.00

JOB# 5 CHARGES-----

LABOR-----

J# 5 51BMZ99 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES DRIVERS DOOR HARD TO CLOSE RUBBING RUBBER SEAL
 ON TOP OF B PILLAR. INSTALL S/O PART
 DOOR RUBBED HOLE ON B PILLAR TOP TRIM AND L/S DOOR SEAL.
 TOP TRIM IS COMING FROM GERMANY(5-7 DAYS).INSTALLED L/S
 DOOR SEAL.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1	51-71-8-232-333	GASKET		WARRANTY
	1	51-71-8-232-339	COVER		WARRANTY
				TOTAL - PARTS	0.00

JOB# 5 TOTALS-----

JOB# 5 JOURNAL PREFIX BMCS JOB# 5 TOTAL 0.00

JOB# 6 CHARGES-----

LABOR-----

J# 6 51BMZ99-1 BODY MISC. TECH(S):5198 0.00
 CLIENT STATES CUP HOLDER RIM IS WARPED, CHECK FOR S/O PART
 PART ON PASS. SEAT.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1	51-16-7-025-454	INST. KIT	17.45	17.45
				TOTAL - PARTS	17.45

JOB# 6 TOTALS-----

PARTS 17.45

JOB# 6 JOURNAL PREFIX BMCS JOB# 6 TOTAL 17.45

JOB# 7 CHARGES-----

LABOR-----

J# 7 34BMZ *BRAKE SYSTEM DIAG TECH(S):5198 WARRANTY
 CLIENT STATES CHECK BRAKES. THEY GRIND COLD BUT QUIET WHEN
 THEY GET WARM
 DUE TO VERY LOW MILES,ROTORS HAVE A SLIGHT BUILD-UP OF RUST
 /OXIDATION.
 CAR NEEDS TO BE DRIVEN.
 FRONT BRAKES=12.0MM:REARS=10.0MM

JOB# 7 TOTALS-----

JOB# 7 JOURNAL PREFIX BMCS JOB# 7 TOTAL 0.00

JOB# 8 CHARGES-----

LABOR-----

J# 8 51BMZ99-3 BODY MISC. TECH(S):5198 WARRANTY
 CLIENT STATES MATERIAL AROUND REAR WINDOW COMING LOOSE

Copyright © 1998 The Reynolds and Reynolds Company ERMNTNVE 00-512365 (08/03)



CENTURY WEST BMW

4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967

MAILING ADDRESS
P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN

MONDAY THRU FRIDAY
7:30 A.M. to 7:00 P.M.
SATURDAYS
8:00 A.M. to 5:00 P.M.
CLOSED SUNDAY

EPA # CAL000262279
BAR # AH190621

CUSTOMER NO.	35226	ADVISOR	NICHOLAS JANCIC	5236	TAG NO.	3098	INVOICE DATE	04/22/05	INVOICE NO.	BMCS100595	
		LICENSE NO.	5LS0439		MILEAGE	1,654	COLOR	BLACK/CREMA	STOCK NO.		
		YEAR / MAKE / MODEL	02/BMW/Z8/2 DOOR ROADSTER				DELIVERY DATE	07/26/02	DELIVERY MILES		
		VEHICLE I.D. NO.	W B A E J 1 3 4 1 2 A H 6 1 8 1 8				SELLING DEALER NO.	04124	PRODUCTION DATE	05/01/02	
		F. T. E. NO.			P. O. NO.		R.O. DATE	04/19/05			
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 1658								

TUCKED IN MATERIAL.

JOB# 8 TOTALS-----

JOB# 9 CHARGES-----
JOURNAL PREFIX BMCS JOB# 8 TOTAL 0.00

LABOR-----
J# 9 51BMZ99-2 BODY MISC. TECH(S):5198 WARRANTY
CLIENT STATES DRIVERS FLOOR MAT HOLDOWNS COME LOOSE
RESECURED FLOOR MAT HOLD DOWN.

JOB# 9 TOTALS-----

JOB# 10 CHARGES-----
JOURNAL PREFIX BMCS JOB# 9 TOTAL 0.00

LABOR-----
J#10 52BMZ99 SEATS MISC. TECH(S):5198 WARRANTY
CLIENT STATES PASS SEAT BACK REST WILL NOT ADJUST
INTERNAL OPEN CIRCUIT IN R/S SEAT SWITCH FOR SEAT BACK.
CHECKED FUSE AND CHECKED OUT GOOD.REMOVED SEAT BACK PANEL
AND CHECKED FOR POWER AND GROUND.FOUND NO POWER GOING INTO
CONN.X736 PIN 10 OR 12.GROUND SIDE CHECKED OUT GOOD.REMOVED
PANEL FOR SWITCH ASSEMBLY AND POWER AND GROUND CHECKED OUT
GOOD AT CONN.X604 PINS 5 AND 6.JUMPED PINS 5(+)AND 6(-) TO
PINS 10 AND 12 ALTERNATELY AND SEAT BACK RECLINES.CHECKED
PINS 10 AND 12 AT THE SWITCH AND SHOWS OPEN CIRCUIT.INSTALLE
D VOR'D SEAT SWITCH AND CHECKED OPERATION,CHECKED OUT GOOD.

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-----
1 61-31-1-392-492 SEAT SWITCH WARRANTY
TOTAL - PARTS 0.00

JOB# 10 TOTALS-----

JOURNAL PREFIX BMCS JOB# 10 TOTAL 0.00

ESTIMATE-----
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$115.00 (+TAX)



CENTURY WEST BMW
 4245 LANKERSHIM BLVD., NO. HOLLYWOOD, CA 91602
 TEL: (818) 432-5899 • (800) 447-8871 • FAX: (818) 760-3967
 MAILING ADDRESS
 P.O. BOX 8825, UNIVERSAL CITY, CA 91618

SERVICE AND PARTS OPEN
 MONDAY THRU FRIDAY
 7:30 A.M. to 7:00 P.M.
 SATURDAYS
 8:00 A.M. to 5:00 P.M.
 CLOSED SUNDAY

EPA # CAL000262279
 BAR # AH190621

CUSTOMER NO. 35226	ADVISOR NICHOLAS JANCIC	5236	TAG NO. 3098	INVOICE DATE 04/22/05	INVOICE NO. BMCS100595	
	LICENSE NO. 5LS0439		MILEAGE 1,654	COLOR BLACK/CREMA	STOCK NO.	
	YEAR / MAKE / MODEL 02/BMW/Z8/2 DOOR ROADSTER			DELIVERY DATE 07/26/02	DELIVERY MILES	
	VEHICLE I.D. NO. W B A E J 1 3 4 1 2 A H 6 1 8 1 8			SELLING DEALER NO. 04124	PRODUCTION DATE 05/01/02	
	F. T. E. NO.		P. O. NO.	R. O. DATE 04/19/05		
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS				MO: 1658

TOTALS																	
***** * <input checked="" type="checkbox"/> CASH <input type="checkbox"/> CHECK CK NO. [] * <input type="checkbox"/> VISA <input type="checkbox"/> MASTERCARD <input type="checkbox"/> DISCOVER * <input type="checkbox"/> AMER XPRESS <input type="checkbox"/> OTHER <input type="checkbox"/> CHARGE *****	<table> <tr><td>TOTAL LABOR....</td><td align="right">0.00</td></tr> <tr><td>TOTAL PARTS....</td><td align="right">17.45</td></tr> <tr><td>TOTAL SUBLET...</td><td align="right">0.00</td></tr> <tr><td>TOTAL G.O.G....</td><td align="right">0.00</td></tr> <tr><td>TOTAL MISC CHG.</td><td align="right">0.00</td></tr> <tr><td>TOTAL MISC DISC</td><td align="right">0.00</td></tr> <tr><td>TOTAL TAX.....</td><td align="right">1.44</td></tr> <tr><td>TOTAL INVOICE \$</td><td align="right">18.89</td></tr> </table>	TOTAL LABOR....	0.00	TOTAL PARTS....	17.45	TOTAL SUBLET...	0.00	TOTAL G.O.G....	0.00	TOTAL MISC CHG.	0.00	TOTAL MISC DISC	0.00	TOTAL TAX.....	1.44	TOTAL INVOICE \$	18.89
TOTAL LABOR....	0.00																
TOTAL PARTS....	17.45																
TOTAL SUBLET...	0.00																
TOTAL G.O.G....	0.00																
TOTAL MISC CHG.	0.00																
TOTAL MISC DISC	0.00																
TOTAL TAX.....	1.44																
TOTAL INVOICE \$	18.89																

THANK YOU FOR YOUR BUSINESS!!

CUSTOMER SIGNATURE





OUR VALUED CUSTOMER

VICK DEUKMAJIAN
Service Consultant

YOUR VEHICLE

Year 2002	Make BMW	Model Z8	Engine Type 5.0L V8 DOHC (MFI)
Odometer 8,804	VIN # WBAEJ13412AH61818	License #	Date 1/15/2021



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. PERFORM TIRE AIR PRESSURE CHECK. INFLATE TO FACTORY RECOMMENDED SPECIFICATIONS AND DOCUMENT AS NECESSARY
- ✓ B. PERFORM RUSNAK BMW COURTESY INSPECTION
- ✓ C. CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VALVE COVERS
- ✓ D. CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VANOS DISTRIBUTION BLOCK AND LINES
- ✓ E. CUSTOMER STATES THAT THE PASSENGER WINDOW REGULATOR NEEDS TO BE REPLACED
- ✓ F. CUSTOMER IS REQUESTING TO HAVE THE PERFORMANCE STRUT BRACE INSTALLED.



Package Results

Additional Observations	Recommendation
REPLACE 4 TIRES	TIRES CRACKED AND AGED HEAVILY
ALIGNMENT	PERFORM 4 WHEEL ALIGNMENT WITH TIRES



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. PERFORM TIRE AIR PRESSURE CHECK. INFLATE TO FACTORY RECOMMENDED SPECIFICATIONS AND DOCUMENT AS NECESSARY		\$0.00		X
B. PERFORM RUSNAK BMW COURTESY INSPECTION		\$0.00		X
C. CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VALVE COVERS		\$0.00		X
D. CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VANOS DISTRIBUTION BLOCK AND LINES		\$0.00		X
E. CUSTOMER STATES THAT THE PASSENGER WINDOW REGULATOR NEEDS TO BE REPLACED		\$1,211.40		X
F. CUSTOMER IS REQUESTING TO HAVE THE PERFORMANCE STRUT BRACE INSTALLED.		\$3,645.00		X

Original Customer Requests		Status	Cost	Deferred	Approved
Subtotal			\$4,856.40		\$4,856.40
Additional Recommendations		Status	Cost	Deferred	Approved
TIRES CRACKED AND AGED HEAVILY (REPLACE 4 TIRES)		Fail	\$1,363.66		X
Subtotal			\$1,363.66		\$1,363.66
Totals, Taxes and Fees			Cost	Deferred	Approved
Estimate Subtotal			\$6,220.06	\$0.00	\$6,220.06
Tax			\$97.89		\$97.89
Estimate Total			\$6,317.95		\$6,317.95

RUSNAK BMW
THOUSAND OAKS

BMW - Kinematics Diagnosis System

Software:

Feb 25 2009

Spec:

{40} 119.0.2

Serial number:

Service date:

Date/Time

1/14/21

14:29

Vehicle

BMW : Z8 - E52 (1999 - 2003) : Adjustment

Customer number:

826

Chassis number:

Code number:

Odometer reading:

Customer:

First Reg.

License:

Mechanic:

	Dimension	Kind	Front left	Front right	Rear left	Rear right
<u>Spring Test</u>	mm	Target	633+/-10	633+/-10	626+/-10	626+/-10
		Actual	633	633	626	626
<u>Design Condition</u>	mm	Target	633+/-2	633+/-2	626+/-2	626+/-2
		Actual	633	633	626	626
<u>Tire Air Pressure</u>	bar/psi/kPa	Actual				
<u>Tire Tread Depth</u>	mm	Actual				
<u>Tire Marking</u>	Star	Yes/No				

Dimension [degree, min]			Before Measurement	Target Data	Max. difference	After Measurement
Rear Axle	Camber	left	-1°36'	-1°27'	+0°05'//-0°05'	-1°30'
		right	-1°50'	-1°27'		-1°31'
	Toe	left	0°11'	0°12'	+0°05'//-0°05'	0°12'
		right	0°01'	0°12'		0°12'
		total	0°12'	0°24'		0°24'
	Geom. driving axis		0°05'	0°00'	+0°12'//-0°12'	0°00'
Front Axle	Camber	left	-0°45'	-0°30'	+0°30'//-0°30'	-0°43'
		right	-0°58'	-0°30'	+0°30'//-0°30'	-0°56'
	Toe	left	0°26'	0°04'	+0°03'//-0°03'	0°04'
		right	0°13'	0°04'	+0°03'//-0°03'	0°03'
		total	0°39'	0°08'	+0°06'//-0°06'	0°08'
	Track differential angle	left	-2°02'	-1°55'	+0°30'//-0°30'	-2°02'
		right	-2°00'	-1°55'	+0°30'//-0°30'	-2°00'
	Max steering lock on curve inside wheel	left		-34°18'		
		right		-34°18'		
	Caster	left	6°23'	6°44'	+0°30'//-0°30'	6°23'
		right	6°23'	6°44'	+0°30'//-0°30'	6°23'
	SAI	left	13°21'			13°18'
right		13°33'			13°30'	
Setback	total	-0°06'	0°00'	+0°15'//-0°15'	-0°04'	

Rusnak BMW
3645 Auto Mall Dr
Westlake Village , CA 91362
(805) 433-9576

RECEIPT

Customer Information:

Invoice Details:

Invoice #: OZ957BTDDU
Invoice Date: Monday, January 18, 2021 01:39
PM

Repair Order/Ref #: 571433

Description of Product/Services	Amount
Service Performed	\$ 6287.93

Payment Details:

Paid On: Monday, January 18, 2021 01:40 PM
Credit Card: XXXXXXXXXXXXX7001 exp XX
/XXXX

Card Type: AMEX

Payment Type: Chip

Confirmation #: 826988

Dealer Associate: Vick Deukmajian

Cashier: Vick Deukmajian

Customer Signature

THANK YOU!

Rusnak BMW

Processed by myKaarma eBridge Payments

Customer Number: 256840

571433

INVOICE



RUSNAK / WESTLAKE

3645 Auto Mall Drive
Thousand Oaks, CA 91362
(805) 496-6500
(818) 991-6340
www.rusnakbmw.com

SERVICE-PARTS DEPT. HOURS.
MONDAY THRU FRIDAY 7:30 A.M. TO 6:00 P.M
NO VEHICLES RELEASED AFTER 6:00 P.M.

ADVISOR: 24023 Vicken Deukmajian

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Includes details for a BMW Z8 Roadster with VIN WBAEJ13412AH61818.

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL
A PERFORM TIRE AIR PRESSURE CHECK. INFLATE TO FACTORY RECOMMENDED SPECIFICATIONS AND DOCUMENT AS NECESSARY
CAUSE: TIRE PRESSURE
CARB PERFORM TIRE AIR PRESSURE CHECK. INFLATE TO FACTORY RECOMMENDED SPECIFICATIONS AND DOCUMENT AS NECESSARY

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
PERFORMED TIRE INFLATION SERVICE AS PER REQUEST. RIGHT FRONT 34 LEFT FRONT 34 RIGHT REAR 34 LEFT REAR 34

B PERFORM RUSNAK BMW COURTESY INSPECTION
CAUSE: INSPECTION
MPIL PERFORM RUSNAK BMW COURTESY INSPECTION
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
PERFORMED RUSNAK BMW COURTESY INSPECTION. PLEASE NOTE THAT YOUR BMW IS EQUIPPED WITH A SERVICE INDICATOR TO REMIND YOU OF NEEDED SERVICE. HOWEVER, PLEASE BE AWARE THAT THE OWNER IS ULTIMATELY RESPONSIBLE TO ENSURE THAT THIS BMW IS PROPERLY SERVICED.

C CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VALVE COVERS
CAUSE: DECLINED
11 GENERAL REPAIR
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
DECLINED

D CUSTOMER STATES THAT THE VEHICLE IS LEAKING OIL FROM THE VANOS DISTRIBUTION BLOCK AND LINES
CAUSE: DECLINED
11 GENERAL REPAIR
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

Form containing tables for 'Original Estimate', 'Revised Estimate', and 'HAZARDOUS WASTE DISPOSAL'. Includes checkboxes for 'Tire pressure check/inflation service' and 'Customer declined tire pressure check/inflation service'. Signature lines for customer and dealership representative.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. STORAGE CHARGES: Equal to \$100.00 per day, if vehicle is not picked up in 3 days.

Customer Number: 256840

571433

INVOICE



RUSNAK / WESTLAKE

3645 Auto Mall Drive
Thousand Oaks, CA 91362
(805) 496-6500
(818) 991-6340
www.rusnakbmw.com

SERVICE-PARTS DEPT. HOURS.
MONDAY THRU FRIDAY 7:30 A.M. TO 6:00 P.M
NO VEHICLES RELEASED AFTER 6:00 P.M.

OR: 24023 Vicken Deukmajian

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Includes details for BMW Z8 ROADSTER, VIN WBAEJ13412AH61818, and invoice date 15JAN21.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes a 'DECLINED' entry.

E CUSTOMER STATES THAT THE PASSENGER WINDOW REGULATOR NEEDS TO BE REPLACED
CAUSE: RIGHT WINDOW REGULATOR FAULTY
11 GENERAL REPAIR
20278 C
PS2 10% SAVING CARD PARTS
LS1 10% SAVING CARD LABOR
1 51-33-8-234-386 WINDOW LIFTER, ELECTRIC, RIG:H51330
PARTS: 814.30 LABOR: 410.00 OTHER: -122.43 TOTAL LINE E: 1101.87
REPLACE THE RIGHT WINDOW REGULATOR

F CUSTOMER IS REQUESTING TO HAVE THE PERFORMANCE STRUT BRACE INSTALLED.
CAUSE: UPPER STRUT MOUNT AND STRUT REINFORCEMENT
11 GENERAL REPAIR
20278 C
LS1 10% SAVING CARD LABOR
PS2 10% SAVING CARD PARTS
3L ADVISOR COURTESY ADJ LBR
1 51-71-0-420-759 STRUT BRACE:H5110D
6 07-14-6-989-335 BLIND RIVET NUT, FLAT HEADED:889520
2 31-33-0-422-175 GUIDE SUPPORT:H31310
6 41-61-8-217-419 TORX-BOLT WITH WASHER:889520
2 31-30-0-422-419 WASHER-GASKET DA 147:H3110D
1 31-35-2-229-447 WASHER:H3110D
PARTS: 1292.47 LABOR: 2788.00 OTHER: -508.05 TOTAL LINE F: 3572.42
REMOVE AND INSTALL FRONT STRUTS TO REPLACE THE UPPER STRUT MOUNT AND INSTALL STRUT BRACE

Form containing signature lines for customer and dealership representative, and a table for 'HAZARDOUS WASTE DISPOSAL' with columns for Description and Totals.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. STORAGE CHARGES: Equal to \$100.00 per day, if vehicle is not picked up in 3 days.

Customer Number: 256840

571433

INVOICE



RUSNAK / WESTLAKE

3645 Auto Mall Drive
Thousand Oaks, CA 91362
(805) 496-6500
(818) 991-6340
www.rusnakbmw.com

SERVICE-PARTS DEPT. HOURS.
MONDAY THRU FRIDAY 7:30 A.M. TO 6:00 P.M
NO VEHICLES RELEASED AFTER 6:00 P.M.

R: 24023 Vicken Deukmajian

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Values: BLACK, 02, BMW Z8 ROADSTER, WBAEJ13412AH61818, 8804 / 8806, T2005. Includes dates and options like ENG:4.9_Liter.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Contains itemized list of tire replacements and labor costs.

PARTS: 1341.18 LABOR: 164.00 OTHER: -141.52 TOTAL LINE G: 1363.66
REPLACED AND BALANCED ALL FOUR TIRES. OLD: LF - EJ1K CJB 1901, RF - EJ1K CJB 1901, RR - EJ7H CJB 1601, LR - EJ7H CJB 3001. NEW: LF - EJ1K JDH 4718, RF - EJ1K JDH 4718, RR - EJ7H DJH 2920, LR - EJ7H DJH 2920

EST: 7,218.00 07JAN21 13:32 SA: 24023
CONTACT:

Form with sections for: Original Estimate, Revised Estimate, *HAZARDOUS WASTE DISPOSAL COSTS, *ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED, and a signature block for customer and dealership.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. STORAGE CHARGES: Equal to \$100.00 per day, if vehicle is not picked up in 3 days.

Car Tekk & Smog

05/27/2020

14038 O Xnard St
 Van Nuys, CA 91401
 8187875901
 Ard270824

Invoice #1442

2002 BMW Z8

Tag: B953C0
 ID: WBAEJ13412AH61818

Mileage 8,687

<u>Labor</u>	<u>Hours</u>	<u>Rate</u>	<u>Amount</u>
SMOG CHECK	0.54	\$95.00	\$51.75
			<u>\$51.75</u>

<u>Part No.</u>	<u>Parts</u>	<u>Quantity</u>	<u>Each</u>	
	SMOG CERT. RK111265C	1.00	\$8.25	\$8.25
				<u>\$8.25</u>

Subtotal	<u>\$60.00</u>
Tax	<u>\$0.00</u>
Total	<u>\$60.00</u>

SMOG CHECK

An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto, until such time as cash payment has been made in full. It is understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control. Upon signing this repair order it is accepted as a complete and comprehensive description of the repair work done on this vehicle. I agree to pay storage fee of \$95.00 per day on vehicle left after repairs are done.

EST: _____ REVISED _____ REASON _____ CONTACT: _____ HOW: _____

DATE _____ SIGNED _____

I acknowledge notice and oral approval of an increase in the original estimate. I the registered owner authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore in an estimate only. your employees may operate the vehicle for inspection, test and delivery at my own risk. By law you may choose another licensed smog check facility to perform any needed repairs or adjustment that the smog check test indicates are necessary.

SIGNED _____ DATE _____

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/27/2020 @ 12:18 PM

Model Year: 2002	Vehicle Make: BMW	Vehicle Model: Z8
VIN (scanned from vehicle):	WBAEJ13412AH61818	
License Plate: B953C0	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 8687	

Overall Test Result

PASS

Congratulations! Your vehicle passed the Smog Check inspection, which helps California reach its daily goal of removing smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Visual Inspection: PASS Functional Inspection: PASS

Smog Check Certificate Number: RK111265C

DMV ID Number: 1634K480R668

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Visual Inspection Result Information

<u>Result</u>	<u>Inspection Category</u>	<u>Result</u>	<u>Inspection Category</u>
PASS	Air Injection System	PASS	Catalyst
PASS	Computers, Sensors, Switches, and Wiring	PASS	Crankcase Emission Controls
NOTAPPLICABLE	Exhaust Gas Recirculation (EGR)	PASS	Fuel Evaporative System (EVAP)
PASS	Fuel Metering System	PASS	Other Emission Related Components/Systems
NOTAPPLICABLE	Turbocharger/Supercharger	PASS	Vacuum Lines to Sensors/Switches

Emission Control Systems Functional Check Results

<u>Result</u>		<u>Result</u>	
PASS	Liquid Fuel Leak Check	PASS	OBDII
PASS	Smoke Check		

Smog Check Inspection Station Information

Station ID: RC270824	Inspector Name/ID: MOZEH, ADEL/EO033222
CAR TEKK & SMOG	Software Version/OIS ID: 20.1.1082.0/CV006436
14038 OXNARD ST	
VAN NUYS, CA 91401	
(818) 787-5901	

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

5-27-2020

Date



Inspector's Signature

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/27/2020 @ 12:18 PM

Model Year: 2002	Vehicle Make: BMW	Vehicle Model: Z8
VIN (scanned from vehicle):	WBAEJ13412AH61818	
License Plate: B953C0	License State: CA	Fuel Type: Gasoline
Certification Type: California	Odometer: 8687	

Supplemental Recall Information

The open recalls for your vehicle are listed below. Recall information is provided as a customer courtesy and is not considered part of the Smog Check inspection.

There were no recall items identified for your vehicle. Please check with the vehicle manufacturer, dealership, or the repair facility for potential recalls on your vehicle.

What is a recall?

A recall is issued when it is determined that there is either an unreasonable risk to safety or an issue related to vehicle emissions. The vehicle manufacturer is required to fix the vehicle at no cost to the consumer.

What should I do about the listed recalls?

If your vehicle is included in this recall, it is very important that you get it fixed as soon as possible given the potential risks to you and your passengers if it is not addressed. Contact your vehicle manufacturer/dealer to arrange for repairs or check www.nhtsa.gov/recalls for more information.

Repair Order Detail - Internal Copy

RO Number: 6395930

RO Status: CLOSED

Phone(s): Contact:
Vehicle: WBAEJ13412AH61818

Main: (818)652-6522
2002 Z8RD

Click to View Cust Copy
Cell: (818)652-6522
JET-BLACK 5LSU439

Mileage: 8,769
Service advisor: 238777
Tag number: TO739

Payment type:

Waiter: No
Estimate: 0.00
Customer Comments: Yes

~~~~~  
A  
CT C CHECK TIRE PRESSURE, 0.00 0.00  
INFLATE IF NECESSARY  
-PLEASE INFORM CENTER  
BMW IF TIRES NITROGEN  
FILLED -LEFT  
FRONT \_\_\_\_\_ RIGHT  
FRONT \_\_\_\_\_ -LEFT  
REAR \_\_\_\_\_ RIGHT  
REAR \_\_\_\_\_

Tech(s): 99999  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
Story: SET TIRES TO SPECS, SEE ESTIMATE FOR TIRES ALL 4 CRACKED AND  
UNSAFE TO DRIVE  
~~~~~

B
TEXT C MY SIGNATURE/INITIAL 0.00 0.00
IS CONSENT TO
RECEIVING -AUTOMATED
FOLLOWUP AND
MARKETING
COMMUNICATIONS
AS-LISTED ON THE
REVERSE _____
-

Tech(s): 99999
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
~~~~~

C CHECK AND ADVISE PASSENGER WINDOW MALFUNCTION  
99 C CHECK AND ADVISE 0.50 97.50  
PASSENGER WINDOW  
MALFUNCTION

Tech(s): 238866  
Pts: 0.00 Lbr: 97.50 Other: 0.00 Total Line C: 97.50  
Story: .5 PERFORM DIAG FOUND FAILED WINDOW REGULATOR CUSTOMER  
DECLINED REPAIRS  
~~~~~

D OIL CHANGE
99 C OIL CHANGE 0.50 97.50

Tech(s): 238866
Pts: 0.00 Lbr: 97.50 Other: 0.00 Total Line D: 97.50
Story: TECH 336 .5 PERFORM ENGINE OIL FILTER CHANGE
~~~~~

# Repair Order Detail - Internal Copy

|                           |        |
|---------------------------|--------|
| Customer Pay              |        |
| Labor                     | 195.00 |
| Parts                     | 0.00   |
| Lube                      | 0.00   |
| Sublet                    | 0.00   |
| Miscellaneous/Shop Charge | 0.00   |
| Deductible                | 0.00   |
| Total Charges             | 195.00 |
| Less Insurance/Adjustment | 0.00   |
| Sales Tax                 | 10.22  |
| Total                     | 205.22 |



# Repair Order Detail - Internal Copy

RO Number: 6278457

RO Status: CLOSED

Click to View Cust Copy

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main: (818)652-6522  
2002 Z8RD

Cell: (818)652-6522  
JET-BLACK 5LSU439

Mileage: 8,326  
Service advisor: 238777  
Tag number: TWTR71

Payment type:

Waiter: No  
Estimate: 0.00  
Customer Comments: Yes

```

A
  CT          C    CHECK TIRE PRESSURE,          1.00          167.00
                   INFLATE IF NECESSARY
                   -PLEASE INFORM CENTER
                   BMW IF TIRES NITROGEN
                   FILLED -LEFT
                   FRONT _____ RIGHT
                   FRONT _____ -LEFT
                   REAR _____ RIGHT
                   REAR _____
    Tech(s): 238812
  Pts:          0.00 Lbr:          167.00 Other:          0.00 Total Line A:          167.00
  Story: FRT 33PSI REAR 41PSI
  
```

```

B
  TEXT        C    MY SIGNATURE/INITIAL          0.00          0.00
                   IS CONSENT TO
                   RECEIVING -AUTOMATED
                   FOLLOWUP AND
                   MARKETING
                   COMMUNICATIONS
                   AS-LISTED ON THE
                   REVERSE
    Tech(s): 99999
  Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line B:          0.00
  
```

```

C
  99          C    REPLACE BATTERY PER REQUEST          0.00          0.00
                   REPLACE BATTERY PER
                   REQUEST
    Tech(s): 99999
  Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line C:          0.00
  Story: BATTERY REPLACEMENT REQUESTED - REPLACE BATTERY COMPLETED
  
```

```

D
  WIKI        C    I AM A WIKI CUSTOMER          0.00          0.00
                   ---
    Tech(s): 99999
  Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line D:          0.00
  
```

|              |        |
|--------------|--------|
| Customer Pay |        |
| Labor        | 167.00 |
| Parts        | 0.00   |

# Repair Order Detail - Internal Copy

|                           |        |
|---------------------------|--------|
| Lube                      | 0.00   |
| Sublet                    | 0.00   |
| Miscellaneous/Shop Charge | 0.00   |
| Deductible                | 0.00   |
| Total Charges             | 167.00 |
| Less Insurance/Adjustment | 0.00   |
| Sales Tax                 | 15.80  |
| Total                     | 182.80 |

# Repair Order Detail - Internal Copy

RO Number: 6246815

RO Status: CLOSED

Phone(s): Contact:                      Main: (818)652-6522                      [Click to View Cust Copy](#)  
 Vehicle: WBAEJ13412AH61818              2002 Z8RD                      JET-BLACK              5LSU439                      Cell: (818)652-6522

Mileage: 8,054                      Payment type:                      Waiter: No  
 Service advisor: 238777                      Estimate:              0.00  
 Tag number: TWTR67                      Customer Comments: Yes

```

    ~~~~~
 A INSTALL SPECIAL ORDER REAR VIEW MIRROR
 99 C INSTALL SPECIAL ORDER 0.00 0.00
 REAR VIEW MIRROR
 Tech(s): 99999
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00
 Story: REPLACED REAR VIEW MIRROR AS PER REQUEST.
    ~~~~~
    
```

```

    B   WASH           C   CENTER BMW COURTESY           0.00           0.00
                   WASH AND VACUUM - - -
    Tech(s): 99999
    Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line B:      0.00
    ~~~~~

```

```

 C CT C CHECK TIRE PRESSURE, 0.00 0.00
 INFLATE IF NECESSARY
 -PLEASE INFORM CENTER
 BMW IF TIRES NITROGEN
 FILLED -LEFT
 FRONT _____ RIGHT
 FRONT _____ -LEFT
 REAR _____ RIGHT
 REAR _____
 Tech(s): 99999
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00
 Story: SET TIRE PRESSURE FRONT AND REAR 34 PSI
    ~~~~~
    
```

```

    D   WIKI           C   I AM A WIKI CUSTOMER           0.00           0.00
                   - - -
    Tech(s): 99999
    Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line D:      0.00
    ~~~~~

```

|                           |              |
|---------------------------|--------------|
| Customer Pay              | 0.00         |
| Labor                     | 0.00         |
| Parts                     | 0.00         |
| Lube                      | 0.00         |
| Sublet                    | 0.00         |
| Miscellaneous/Shop Charge | 0.00         |
| Deductible                | 0.00         |
| Total Charges             | 0.00         |
| Less Insurance/Adjustment | 0.00         |
| Sales Tax                 | 58.97        |
| <b>Total</b>              | <b>58.97</b> |



# Repair Order Detail - Internal Copy

RO Number: 6243196

RO Status: CLOSED

Click to View Cust Copy

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main: (818)652-6522  
2002 Z8RD

Cell: (818)652-6522  
JET-BLACK 5LSU439

Mileage: 8,014  
Service advisor: 238777  
Tag number: TU93

Payment type:

Waiter: No  
Estimate: 0.00  
Customer Comments: Yes

~~~~~  
A OIL CHANGE  
99 C OIL CHANGE 0.50 83.98  
Tech(s): 238866  
Pts: 0.00 Lbr: 83.98 Other: 0.00 Total Line A: 83.98  
Story: TECH 336 , 5 PERFORM BMW ENGINE LOW MILAGE OIL CH NAGE  
~~~~~

B CHECK ENGINE LIGHT IS ON DID LOOSE POWER  
99 C CHECK ENGINE LIGHT IS 1.50 255.18  
ON DID LOOSE POWER  
Tech(s): 238866  
Pts: 0.00 Lbr: 255.18 Other: 0.00 Total Line B: 255.18  
Story: TECH 336 1.5 , CHECK FAULT MEM FOUND MISFIRE #4 CY L. REMOVE  
COIL REMOVE SPARK PLUG INPECT SPARK PLUG FOUND FAILED COIL  
BY SWAPING WITH #3 AND FAULT MI GRATE. REPLACE #4 COIL AND  
CLEAR FAULTS  
~~~~~

C SEEMS TO HESITATE ON ACELERATION  
99 C SEEMS TO HESITATE ON 0.00 0.00  
ACELERATION  
Tech(s): 99999  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
Story: SEE LINE 2  
~~~~~

D ESTIMATE REAR VIEW MIRROR  
99 C ESTIMATE REAR VIEW 0.00 0.00  
MIRROR  
Tech(s): 99999  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00  
Story: PART HAS BEEN ORDERED FROM GERMANY  
~~~~~

E R/F SEAT BELT IS TWISTED  
99 C R/F SEAT BELT IS 2.00 342.12  
TWISTED  
Tech(s): 238866  
Pts: 0.00 Lbr: 342.12 Other: 0.00 Total Line E: 342.12  
Story: TECH 336 2.0 , REMOVE SEAT AND COVERS UNTWIST SEAT BELT AND  
REINSTALL, CHECK OERATION OF SEAT BELT  
~~~~~

F C/D CART WONT EJECT  
99 C C/D CART WONT EJECT 0.00 0.00  
Tech(s): 99999  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00  
Story: NO REBUILT AVAlABLE NEED TO REPLACE CHANGER , CUST OMER  
DECLINED REPAIRS AT THIS TIME .  
~~~~~

# Repair Order Detail - Internal Copy

RO Number: 6243196

RO Status: CLOSED

[Click to View Cust Copy](#)

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main: (818)652-6522  
2002 Z8RD

Cell: (818)652-6522  
JET-BLACK 5LSU439

Mileage: 8,014  
Service advisor: 238777  
Tag number: TU93

Payment type:

Waiter: No  
Estimate: 0.00  
Customer Comments: Yes

```

~~~~~
G
  11          C      BRAKE FLUID FLUSH - -          1.00          148.00
      Tech(s): 238866
Pts:          0.00 Lbr:          148.00 Other:          0.00 Total Line G:          148.00
Story: TECH 336 1.0 PERFORM BRAKE FLUID FLUSH
  
```

```

~~~~~
H
 21 C COOLANT FLUSH - - - 1.00 148.00
 Tech(s): 238866
Pts: 0.00 Lbr: 148.00 Other: 0.00 Total Line H: 148.00
Story: TECH 336 1.0 PERFORM COOLANT FLUSH

```

Customer Pay	
Labor	977.28
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	977.28
Less Insurance/Adjustment	0.00
Sales Tax	22.35
Total	999.63

# Repair Order Detail - Internal Copy

RO Number: 6044525

RO Status:

Phone(s): Contact:  
 Vehicle: WBAEJ13412AH61818

Main:  
 2002 Z8RD

Click to View Cust Copy  
 Cell:  
 JET-BLACK 5LSU439

Mileage: 3,844  
 Service advisor: 238853  
 Tag number:

Payment type:

Waiter: No  
 Estimate:  
 Customer Comments: Yes

A	RCL	W	CHECK FOR OPEN RECALLS OR CAMPAIGNS	0.88	88.55
---	-----	---	----------------------------------------	------	-------

Tech(s):	238866				
Pts:	0.00	Lbr:	88.55	Other:	0.00
				Total Line A:	88.55

B	CHECK TRUNKLID - WHEN OPENS TRUNK,CLICKING AT BACK OF TRUNKLID BY BODY - SEE MARK IF ANY QUESTIONS				
99	C	CHECK TRUNKLID - WHEN OPENS TRUNK,CLICKING AT BACK OF TRUNKLID BY BODY - SEE MARK IF ANY QUESTIONS	0.50	56.50	

Tech(s):	238866				
Pts:	0.00	Lbr:	56.50	Other:	0.00
				Total Line B:	56.50

Customer Pay	
Labor	56.50
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge*	0.00
<b>Total Charges**</b>	<b>56.50</b>

\*Miscellaneous/Shop Charge includes tax and/or deductible originally on RO.

\*\*Total Charges includes any Insurance/Adjustment originally on RO.



# Repair Order Detail - Internal Copy

RO Number: 6025322

RO Status:

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main:  
2002 Z8RD

Click to View Cust Copy  
Cell:  
JET-BLACK 5LSU439

Mileage: 3,390  
Service advisor: 238853  
Tag number:

Payment type:

Waiter: No  
Estimate:  
Customer Comments: Yes

A ROAD TESTED WITH CUSTOMER & FORMAN#215;SERVICE ENG INE SOON LIGHT ON - LACK OF POWER & CAR STARTED CH UGGING - CK FOR FAULTS & REPORT				
99	W	ROAD TESTED WITH CUSTOMER & FORMAN#215;SERVICE ENG INE SOON LIGHT ON - LACK OF POWER & CAR STARTED CH UGGING - CK FOR FAULTS & REPORT	1.63	164.45
Tech(s): 238866				
Pts:	0.00	Lbr: 164.45	Other: 0.00	Total Line A: 164.45

Customer Pay	
Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge*	0.00
Total Charges**	0.00

\*Miscellaneous/Shop Charge includes tax and/or deductible originally on RO.

\*\*Total Charges includes any Insurance/Adjustment originally on RO.



# Repair Order Detail - Internal Copy

RO Number: 6021614

RO Status:

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main:  
2002 Z8RD

Click to View Cust Copy  
Cell:  
JET-BLACK 5LSU439

Mileage: 3,125  
Service advisor: 238853  
Tag number:

Payment type:

Waiter: No  
Estimate:  
Customer Comments: Yes

~~~~~  
A CAR WON'T START - HAS TO JUMP-START;CK & REPORT  
99 W CAR WON'T START - HAS 0.50 46.00  
TO JUMP-START;CK &  
REPORT

Tech(s): 238866  
Pts: 0.00 Lbr: 46.00 Other: 0.00 Total Line A: 46.00  
~~~~~

B LT DOOR WON'T CLOSE - CK & REPORT  
99 W LT DOOR WON'T CLOSE - 0.25 23.00  
CK & REPORT

Tech(s): 238866  
Pts: 0.00 Lbr: 23.00 Other: 0.00 Total Line B: 23.00  
~~~~~

C CK ENGINE FOR A LACK OF POWER & REPORT  
99 W CK ENGINE FOR A LACK 1.25 115.00  
OF POWER & REPORT

Tech(s): 238866  
Pts: 0.00 Lbr: 115.00 Other: 0.00 Total Line C: 115.00  
~~~~~

D NEED EST ON DAMAGED FIREWALL PADDING TO REPLACE.  
99 C NEED EST ON DAMAGED 0.00 0.00  
FIREWALL PADDING TO  
REPLACE.

Tech(s): 99999  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00  
~~~~~

E HARD TOP LATCH COVERS ARE BROKEN, AND CENTURY WEST BMW ORDERED IT  
ALREADY. PLEASE CHECK AND SEE IF WE CAN REPLACE IT HERE AT CENTER  
BMW.  
99 W HARD TOP LATCH COVERS 0.13 11.50  
ARE BROKEN, AND  
CENTURY WEST BMW  
ORDERED IT ALREADY.  
PLEASE CHECK AND SEE  
IF WE CAN REPLACE IT  
HERE AT CENTER BMW.

Tech(s): 238866  
Pts: 0.00 Lbr: 11.50 Other: 0.00 Total Line E: 11.50  
~~~~~

F DRIVERS SIDE DOOR SEAL AT COV.TOP WORN  
99 W DRIVERS SIDE DOOR 0.38 34.50  
SEAL AT COV.TOP WORN

Tech(s): 238866  
Pts: 0.00 Lbr: 34.50 Other: 0.00 Total Line F: 34.50  
~~~~~



# Repair Order Detail - Internal Copy

RO Number: 6021614

RO Status:

Phone(s): Contact:  
Vehicle: WBAEJ13412AH61818

Main:  
2002 Z8RD

Click to View Cust Copy  
Cell:  
JET-BLACK 5LSU439

Mileage: 3,125  
Service advisor: 238853  
Tag number:

Payment type:

Waiter: No  
Estimate:  
Customer Comments: Yes

~~~~~

Customer Pay	
Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge*	0.00
Total Charges**	0.00

\*Miscellaneous/Shop Charge includes tax and/or deductible originally on RO.

\*\*Total Charges includes any Insurance/Adjustment originally on RO.

# Warranty Vehicle Inquiry

Thu May 11, 2023 13:12:25 EDT

VIN : WBAEJ13412AH61818 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES\*

\*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2023 BMW of North America, LLC

Vehicle Data	
<b>VIN:</b> WBAEJ13412AH61818	<b>Davis #:</b> N/A
<b>Chassis Number:</b> WBAEJ13412AH61818	<b>TCU MIN:</b>
<b>Line Make:</b> 01 - BMW Car	<b>Vehicle Production Date:</b> 2002/05
<b>Model Year:</b> 2002	<b>Series:</b> E52
<b>AG Model Code/Desc:</b> EJ13 - Z8 5 0 US	<b>Wholesale Center ID/Loc:</b> 04124-01
<b>NA Model Code/Desc:</b> 0280 - Z8	<b>Wholesale Date:</b> 07/24/2002
<b>Motor Type:</b> S62	<b>Retail Center ID/Loc:</b> 04124-01
<b>Exterior Trim Code:</b> 668 - Jet Black	<b>Retail Date:</b> 07/26/2002
<b>Interior Color Code:</b> P1CS - Crema/Black Leather	<b>In-Service Date:</b> 07/26/2002
<b>MSRP:</b> \$132,745.00	<b>See - Vehicle Comments</b>

Vehicle Comments		
Add Date	Comment Status	Vehicle Comment
	Active	DINAN PERF.SFTWRE.INST BY LONG BCH @ 21 MI.ANY FAILURES RELATED TOOR AS A CONSEQUENCE OF. THIS OR ANYOTHER MODS ARE NOT COVERED BY THE ORIGINAL 4/50,000 OR CPO WARRANTIESSEE 10/2002 NATIONAL VEHICLE FILE

Campaign Details as of: May 11, 2023 at 01:10:58 PM EDT

NO OPEN CAMPAIGNS

Option Information			
Code	Description	Code	Description
0097	FIRST AID KIT	0847	CPT8000 TIMEPORT PHONE KIT
0AAA	100% OPTIONS		

Customer Information
----------------------

Name (First/Last):

Address:

Warranty/Maintenance Programs/Contract Services(Administered by BMW NA)												
Type	Warr/Program Codes/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Current Age (Mth)	Retail Center	Center Name	Vendor Code/Deductible	Contract Holder (First/Last)
	New Vehicle Limited Warranty	0000000 EXPIRED	07/26/2002		07/26/2006	48	50,000	250				
FE	Federal Emissions 8/80 FE 96 MO/80K MLS	0000000 EXPIRED	07/26/2002	07/26/2002	07/26/2010	96	80000	250	04124	Long Beach BMW	00	
CA	<b>California Emissions</b>	Vehicle may qualify for California Emissions Coverage. Please verify if the vehicle was sold or is registered in a California Emissions Covered State (AZ,CA,CT,DE,MA,MD,ME,NJ,NM,NY,OR,PA,RI,VT,WA). Please confirm model year, selling state and current registration of the vehicle and click here to determine coverage.										

Repair History (Claims)										
Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
04355	01	735650	05/30/2007	44525	05/23/2007	05/30/2007	N/A	3,844	0012230200	B121106 Recall Programming DME control module (OBD communication)
04355	01	602550	07/20/2006	25322	07/15/2006	07/20/2006	N/A	3,389	1213001200	Ignition coil permanent failure
04355	01	581510	06/01/2006	21614	05/16/2006	06/01/2006	N/A	3,123	1213001200	Ignition coil permanent failure
									5121014100	Lock striker, front Poorly adjusted
									5171004100	Seal, front door Poorly adjusted
									5421011300	Hardtop, lock including trim Broken
									6121001200	Vehicle battery permanent failure
20268	01	168440	04/27/2005	100595	04/22/2005	04/27/2005	N/A	1,654	5116033700	Sun visors (including mirror cover) Loose
									5171000100	Seal, front door Cracked / broken off
									6131621400	Switch, seat adjustment, front (without memory) Temporary malfunction
									6312024800	Housing, headlight Not leaktight
20268	01	143540	02/26/2005	97501	02/24/2005	02/26/2005	N/A	1,182	85990088MP	1200 MI SERV -M5,Z8,S54B32 M3
66682	01	324130		167784	07/17/2002		N/A	3	5191205400	Paintwork, bodyshell Scratches / scoring
									9999010100	Missing parts ex works

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES  
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES\*

\*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.  
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2023 BMW of North America, LLC



4903

Owner's Manual  
for Vehicle



# **Service and Warranty Information**

2002 Z8





Owner's Manual  
for Radio and  
Navigation System





**Service Contact**  
Africa, America, Asia,  
Australia, Oceania  
2001/2002

BMW Service

[www.bmw.com](http://www.bmw.com)





## BMW Safety Tips

Please read the following information carefully, and share it with all passengers. Help us to make your driving experience a safer one.

**Warning: Ignoring these safety tips could result in serious injury or death!**

### Restraint Systems and Proper Positioning

Always make sure everyone in the vehicle is wearing a restraint device properly – either safety belts or a child-restraint system.




Safety belts should be worn snugly across the hips and shoulder; avoid any twisting of the belt. Always position the shoulder belt across your chest, not behind your back.

Expectant mothers should always wear their safety belts; take care to position the lap belt against the lower hips. The shoulder strap should be worn to the side of the fetus and between the breasts.



Each safety belt is designed to be used by only one person. Do not allow infants or small children to ride in passengers' laps.



Manually adjustable safety belt anchors can be moved up or down to suit your individual torso.



#### Warning: Passenger Airbag!

Children should always ride in the rear seat and use an appropriate child-restraint system or the safety belts. Never install a child-restraint system in any front seat. The safety belts have a label with instructions for locking the belt when installing a child-restraint system.



#### Warning: Front and Rear Side Airbags!

For vehicles equipped with side airbags, all occupants should be properly restrained and sitting upright. Never let an occupant's head rest near any side airbag.




Drivers and passengers should never sit close to the frontal airbags. Always move both driver and passenger seats as far back from frontal airbags as practical.



#### Warning: Driver Airbag!

Airbags need room to inflate. The safest driving position is a comfortable one. In a comfortable driving position, the arms are slightly bent with the hands at 9 and 3 o'clock positions on the steering-wheel, and the pedals are within easy reach.



Properly adjust the head restraint so that the center is roughly at ear height.

**At BMW, your safety is a priority.**



Illustrations do not represent every model. See the vehicle Owner's Manual for more detailed information.



ULTIMATE SONIC TRANSPARENCY

# BMW Audiophile Demonstration Disc

